

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2023/SZ/39

Dated: 18/01/2023

FIRE SAFETY CERTIFICATE

Certified that the **Aakash Public School**, Ishwar Colony, Arjun Park, New Delhi-110043, comprised of ground floor plus three upper floors (third floor having single hall only on terrace not in use and closed), owned/occupied by Aakash Public School was issued Fire Safety Certificate by this department vide letter No. F.6/DFS/MS/School/2019/SZ/1970 dated 15/10/2019. The School building was re-inspected by the officer concerned of this department on 06/01/2023 in the presence of Mr. Sumeet Sharma (Manager) and found that the School building have deemed complied the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules 2010 and that the building/ premises (Ground floor, First floor & Second floor) is fit for occupancy class "Educational" for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule-38 of the Delhi Fire Service Rules, 2010 printed as below.

(SUNIL CHAWDHARY) DY. CHIEF FIRE OFFICER SOUTH ZONE

Copy to:-

- The Manager, Aakash Public School, Ishwar Colony, Arjun Park, New Delhi-110043
- Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on <u>www.dfs.delhigovt.nic.in</u>.
- The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.
- 9. In case of usage of third floor for schooling purpose then this FSC will be null and void.

N/21

INSPECTION REPORT

	-	INSPECTION	N REPORT					
3	2. Buil	e of Occupancy : Education	blic School, Ishwar (s (third floor having : al	Colony, Arjun Park, single hall only on to	New Delhi-43 errace not in use			
	1 TVD	e of Case : Renewal						
	5. Deta	ils of Previous NOC : F.6/DFS/M	IS/School/2019/SZ/1	970 dated 15/10/20	019			
		Safety directives letter No : N/A						
		of inspection : 06/01/2023						
		e of Inspecting Officer : A.D.O. R.H e and designation of officers	K.Yadav					
			at Channa (Managar					
		에 집중하는 것이 있는 것이 해야 하는 것이 있는 것이 없는 것이 있는 것이 있는 것이 있는 것이 없는 것이 있는 것이 없는 것이 있는 것이 없는 것이 없	et Sharma (Manager & FF) & 2008 (SF a					
			nrifNOC/1974/2022					
No.	Minimum Standards on fire prevention and		NBC/BBL Provided at site Remarks					
	fire sa	fety U/R 33	Requirement	rionaca arone	MR/NMR			
	Acces	s to building						
		Road width	Accessible 06 m	Provided	MR			
		Gate width	4.5 m	4.5 & 3.9 m	MR			
		Width of internal road	N/A	N/A	N/A			
22	Numb	er, Width, Type & Arrangement of Exit	ts					
	a. Nu	mber of staircases						
	•	Upper Floors	02 No's	02 No's	MR			
	•	Basements	N/A	N/A	N/A			
	b. Wi	dth of staircases	1. 50 m each	1.50 m each	MR			
	•	Upper Floor	Contract On Contract Contract Contract		N/A			
	•	Basements	N/A	N/A	IN/A			
	U PERMIT	tection of exits Fire check door	N/A	N/A	N/A			
	:	Pressurization	N/A	N/A	N/A			
	d N	o. of continuous staircases to						
		rrace	Required	Provided	MR			
	e. W	idth of Corridor	1.50 m	1.50m	MR			
	f. C	lass room Door Size	1.0 m	1.02 m	MR			
3.	Com	partmentation						
	•	Fire check door	N/A	N/A	N/A			
	•	Sealing of electrical shafts	N/A	N/A	N/A			
	•	Fire Rating of shaft door	N/A	N/A	N/A			
	•	Water Curtain	N/A	N/A	N/A			
	•	Fire Dampers	N/A N/A	N/A N/A	N/A N/A			
4.	Smoke Management System							
	•	Basements	N/A	N/A	N/A			
	•	Upper floors	Required	Natural ventilation	MR			
5.	Fire	Extinguishers						
		Total numbers	18 no.'s	Provided	MR			
			ABC/CO ₂ type	Provided	MR			
	1	Types	ISI marked	ISI marked	MR			
	1	IS marking	151 marked					

h

i

N/22

6.	First-Aid Hose Reels						
	Total numbers on each floor	02 no.'s	Provided				
	Length of hose reel hose	30 m	Provided	MR			
	 Nozzle diameter 	5 mm		MR			
7.		22.17.190 (24.1	Provided	MR			
/.	Automatic fire detection and alarming system						
	Type of detectorsLocation of Main Panel	N/A	N/A	N/A			
	Location of Repeater Panel	N/A	N/A	N/A			
	 Alternate source of power 	N/A	N/A	N/A			
	 Hooters' Location 	N/A	N/A	N/A			
		N/A	N/A	N/A			
8.	MOEFA	N/A	N/A	N/A			
9.	Public Address System	N/A	N/A	N/A			
0.	Automatic Sprinkler System			0.00			
	• Basement	N/A	N/A	N/A			
	Ground Floor	N/A	N/A	N/A			
	 Sprinkler above false ceiling 	N/A	N/A	N/A			
1.	Internal Hydrants						
	 Size of riser/down-comer 	N/A	N/A	N/A			
	 Number of hydrants per floor 	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
2.	Yard Hydrants						
	Total number of hydrants	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
13.	Pumping Arrangements	a server d'a the					
	Ground Level						
	 Discharge of main Pump 	N/A	N/A	N/A			
	Head of Main pump	N/A	N/A	N/A			
	Number of main pumps	N/A N/A	N/A N/A	N/A			
	Jockey Pump out put			N/A N/A			
	Jockey pump head	N/A	N/A	ALC: NOT AND			
	Standby Pump out put	N/A	N/A	N/A			
	Standby Pump Head Auto Starting (Manual Stopping)	N/A	N/A	N/A			
	Auto Starting/Manual Stopping	N/A	N/A	N/A			
		N/A	N/A	N/A			
	> p. 11	N/A	N/A	N/A			
	 Pump House Access Terrace level 						
	 Terrace level Discharge of pump 	450 LPM	Provided	MR			
	 Head of the pump 	30 m	Provided	MR			
	 Power Supply 	Required	Provided	MR			
	Auto Starting of pump	Required	Provided	MR			
	As an international and a second state of a second state of the se						
4.	Captive Water Storage for fire fighting						
	 Underground tank capacity 	N/A	N/A	N/A			
	Draw-off connection	N/A	N/A	N/A			
	Fire service inlet	N/A	N/A	N/A			
	Access to tank	N/A	N/A	N/A			
	Overhead Tank capacity	10,000 ltrs	Provided	MR			
	Exit Signage.	Required	Provided	MR			

5

15

4/23

A	R provision of Lifts.			No Lift			
MIR	· pressurization of Ent Shart	N/A	N/A	N/A			
MR	Pressurization of Lift lobby	N/A	N/A	N/A			
0	Communication In lift Car	N/A	N/A	N/A			
	Fireman's Grounding Switch	N/A	N/A	N/A			
_	Lift Signage	N/A	N/A	N/A			
ī. —	Standby power supply	N/A	N/A	N/A			
8.	Refuge Area.						
	> Total Area	N/A	N/A	N/A			
	> Location	N/A	N/A	N/A			
).	Fire Control Room						
	Detector System Panel	N/A	N/A	N/A			
	Flow Switch Panel	N/A	N/A	N/A			
	PA System Panel	N/A	N/A	N/A			
	Battery backup	N/A	N/A	N/A			
	Building Floor Plans	N/A	N/A	N/A			
	Special Fire Protection System for Protection of special Risks, if any:	n N/A	N/A	N/A			

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the Fire Safety Certificate issued vide letter number F.6/DFS/MS/School/2019/SZ/1970 dated 15/10/2019 renewal under Rule 37 of the Delhi Fire Service Rules 2010 is recommended.

Note:-Third floor having single hall only on terrace is not in use and closed. Photographs have been enclosed (placed at C-32)

Signature of Inspecting Officer Name:- R.K.Yadav Designation:- Asstt. Divisional Officer

D.O. (South West)

pet up

er y

01/202