

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F.6/DFS/MS/EH/2023/SZ/ 21

Dated. J.S.. / . O.J. / 2023

FIRE SAFETY CERTIFICATE

Certified that the Restaurant in the Name & Style of M/s 1022 located at Ground Floor, DDA Shop No 3, 4, 5, 8 & 9, Azad Apartment CSC, Sri Aurobindo Marg, New Delhi 110016 in the building comprised of Ground Floor Only owned/occupied by A Unit of Butter Café and Bar Pvt Ltd, have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Delhi Fire Service on 11/01/2023 in the presence of Mr. Uday Panday and that the premise is fit for occupancy class Group—D Assembly Building (Restaurant) with effect from 18/01/2023 for a period of Three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on _______/2023 at New Delhi by

(ATUL GARG) DIRECTOR

Copy to: -

1. The Dy. Health Officer, Public Health Department, South Zone, Green Park, Delhi- 110016 (Ref. MHA Portal 2022121021262 dated 10/12/2022)

Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire fighting system.
- 4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."

	The state of the s	,		1777			
in .	INSPECTIO	N REPORT		The second secon			
	Name & Address of the Building	9 Azad Apartment CSC, Sri Aurobindo Marg, New					
	Type of Occupancy	Delhi 110016 George D. Assambly Building (Esting House)					
2	Building Comprised of						
	Type of Case	9 Azad Apartment CSC, Sri Autobindo Mag, Delhi 110016 Group-D Assembly Building. (Eating House) Ground Floor only New Case Nil Nil 11/01/2023 DO (South) & ADO (BCP) Mr. Uday Panday 1983 Restt. Running at Ground Floor only MHA Portal 2022121021262 dated 10/12/2022 UBBL/NBC-2016 Provided at Site Remarks MR/NMR O9 m					
4	Details of Previous NOC						
5	Fire Safety Directives Letter No						
6	Date of Inspection	1					
7	Name of the Inspecting Officers						
8	Name & Designation of Officers						
9	from the building side						
10	Year of construction	1983 Rest	t. Running at Ground Fl	oor only			
11	Applicant letter No.	MHA Portal 2022121021262 dated 10/12/2022					
S. No.	Minimum standards on Fire Prevention	UBBL/ NBC	- Provided at Site				
	and Fire Safety U/R 33	2016		MR/NMR			
1	Access to Building.						
	Road width	09 m	Provided	MR			
	Gate width		About on road	N/A			
	 Width of internal road 			N/A			
2	Number, width, type & arrangement of ex						
	a) Number of Staircase						
	Upper floors.	N/A	N/A				
	Basement floor.	N/A	N/A	N/A			
	b) Width of Staircase						
	Upper floors	N/A	N/A	N/A			
	Basement floor	N/A	N/A	N/A			
	c) Protection of exits						
	> Fire check door	N/A	N/A	N/A			
	Pressurization	N/A	N/A	N/A			
	d) No. of continuous staircase to terrace	N/A	N/A	N/A			
	e) Width of corridor	N/A	N/A	N/A			
	f) Door size	1.50 mtr	1.50 mtr each	MR ´			
3	Compartmentation.						
	Fire check door.	N/A	N/A	N/A			
	 Sealing of electrical shafts. 	N/A	N/A	N/A			
	Fire rating of shaft door.		N/A	N/A			
	Water curtain	N/A	N/A	N/A			
	Fire dampers.	N/A	N/A	N/A			
4	Smoke Management system.	ř.					
	Basement		N/A	N/A			
	Upper floors	NA	N/A	N/A			
5	Fire Extinguishers.						
	Total numbers	10 Nos	10 Nos	MR ~			
	Types	ABC/CO ₂	ABC- & CO ₂	MR			
	ISI Marking	ISI marked		MR			
6	First Aid Hose Reels.						
	Total numbers on each floor.	One	Provided	MR			
	1 Ottal numbers on such most.		1.011404	IVII\ /			

March Co

				नहात्स
	d Class and home	30m	Provided	MR
	Length of hose-reel hose.	5mm	Provided	MR
	Nozzle Diameter Recomming system	m.		
7	Automatic fire detection & alarming system	N/A	N/A	N/A
	Type of detectors	N/A	N/A	N/A
	Location of Main Panel	N/A	N/A	N/A
	Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of power		N/A	
	Hooter's location	N/A	Provided	N/A
8	MOEFA	Required		MR
9	Public Address System	N/A	N/A	N/A
10	Automatic Sprinkler System			
	Basement	N/A	N/A	N/A
	Ground/ upper floors.	N/A	N/A	N/A
	Sprinkler above false ceiling	N/A	N/A	N/A
11	Internal Hydrants.			
-11	Size of Riser/Down-comer	100 mm	Provided	MR
	Number of Hydrant per floor	One	Provided	MR
	Hose box.	One	Provided	MR
12				1
12	Yard Hydrants.	N/A	N/A	N/A
	Total number of hydrants. Here boy	N/A	N/A	N/A
12	Hose box. Promoting appropriate			
13	Pumping arrangements.			
	Ground Level Discharge of main nump	N/A	N/A	N/A
	Discharge of main pump.Head of main pump.	N/A	N/A	N/A
	Head of main pump.Number of main pumps.	N/A	N/A	N/A
	> Jockey Pump output.	N/A	N/A	N/A
	Jockey Pump head.	N/A	N/A	N/A
	Standby Pump output.	N/A	N/A	N/A
	Standby Pump head.	N/A	N/A	N/A
	➤ Auto Starting/Manual Stopping.	N/A	N/A	N/A
	Pump house access.	N/A	N/A	N/A
	Terrace Level			
	Discharge of pump.	450 LPM	Provided	MR
	➤ Head of pump.	40m	Provided	MR
	> Power supply.	Required	Provided	MR
	> Auto starting of pump.	Required	Provided	MR
4	Captive water storage for fire fighting.			
4		N/A	N/A	N/A
	 Underground tank capacity. Draw-off connection. 	N/A	N/A	N/A
	Fire Service Inlet.	N/A	N/A	N/A
	> Access to tank.	N/A	N/A	N/A
15	Overhead tank capacity.	20,000 Ltrs	Provided	MR
		Required	Provided	MR
	Exit Signage.	required	110,1000	
6	Provision of Lifts.	N/A	N/A	N/A
	Pressurization of lift shaft. Pressurization of lift lobby	N/A N/A	N/A N/A	N/A
	 Pressurization of lift lobby. Communication in lift car. 	N/A N/A	N/A N/A	N/A
	• Fireman's switch.	N/A N/A	N/A N/A	N/A
	• Lift signage.	N/A N/A	N/A N/A	N/A
		IN/A	N/A	N/A

N (

N/A

Standby Power Supply

17

to

N/A

de

N/A



18	Refuge Area			
	Total area Location	N/A N/A	N/A N/A	N/A N/A
	Detector system panel.	N/A	N/A	N/A
	Flow switch panel.	N/A	N/A	N/A
	PA system panel.	N/A	N/A	N/A
	Battery backup.	N/A	N/A	N/A
	 Building floor plan. 	N/A	N/A	N/A
20	Special Fire Protection System for the Protection of special Risk, if any.	N/A	N/A	N/A

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Keeping in view of the substantially satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 (3) of the Delhi Fire Service Rules, 2010.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspection Officer

ded led

> Name: Sh. Manoj Kumar Sharma Design: DO (South)

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar Design: ADO (BCP)

Dy. CFO (SZ)

Vugh 701/200

is but up

Disector My

ploaded 1871/23