



Dated: /9 / 0/ /2023

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No.F.6/DFS/MS/2023/NDZ/ 27

FIRE SAFETY CERTIFICATE

Certified that the Cross River Mall located at Plot No. 9B & 9C, CBD, Shahdara, Delhi32, comprised of 2 Basements, Ground and Three upper Floors, owned / occupied by STC Developers
Pvt. Ltd., was issued FSC vide letter No. F6/DFS/MS/NDZ/2019/2308 Dated 12/12/19. The premises was
re-inspected by the officers concerned of this department on dated 06/01/2023 in the presence of Sh.
Vipin (Manager) and observed that all the fire prevention and fire safety arrangements provided in the
premises found in good working condition. The premises have therefore deemed complied with the rule
33 of the Delhi Fire Service Rule, 2010 and the building/premises is fit for occupancy class
"Mercantile" (Group-F) / Multiplex Building with effect from /9 / 01 /2023 for a period of three
years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and
subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010 & also
conditions printed below.

Issued on 19/61/2022 at New Delhi by.

(ATUL)GARG)/ \
DIRECTOR\

DELHI FIRE SERVICE.

To,

Sh. Arihant Jain, AGM (Marketing), M/S STC Developers Pvt. Ltd., LGF 10, Vasant Square Mall, Vasant Kunj, Plot -A, Sec- B, New Delhi-110070.

Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided their in shall be maintained in good working conditions at all times.
- Loss of life or property due to non-functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. Basement shall be used strictly as per Building By-Laws.
- 6. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 7. "The owner / Occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule37] along with a copy of this Certificate, six months prior to its expiry".
- 8. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <u>WWW.dfs.Delhigovt.nic.in</u>.

INSPECTION REPORT

1. Name & Address of the building: Cross River Mall at Plot No. 9B & 9C,

CBD, Shahdara, Delhi-110032.

2. Building is comprised of

: Two Basement, Ground & Three Upper Floors

3. Type of Occupancy

: Mercantile (Group-F) / Multiplex (Mall)

4. Type of Case

: Renewal

5. Details of Previous FSC letter

: F6/DFS/MS/NDZ/2019/2308 dated. 12/12/19

6. Fire safety directive letter no.

: F6/MS/DFS/BP/2004/1629 dated. 27/07/04

7. Date of Inspection

: 06/01/2023.

8. Name of the Inspecting officer : A.K. Jaiswal, D.O.(ED) & Deepak Kumar, A.DO. (Shah.)

9. Name and designation of

Officer from the building side

: Sh. Vipin (Manager)

10. Year of Construction

: 2006 & 2022.

11. Applicant's email

$\frac{1.7}{S}$	Applicant's email : dated	05, Dec. 2022		
N	Millium Standards on fire	Directive	Provided at Site	Remar
1	prevention and fire safety U/R33	Requirement	1 Tovided at Site	Remar
1	Access to building	1		
	Road width	12 M	24 M	MR
	• Gate width	4.5 M	07 M	
2	Width of internal road	0616		MR
2	Number, Width, Type and Arrangem	ent of Exits	06 M	MR
	a. Number of Staircases	DAILS		
	Upper Floor	11 Nos.	12 N	
	 Basement 	11 Nos. +2	13 Nos.	MR
	B. Width of Staircases	ramp	13 Nos. + 02	MR
	Upper Floor	1.50 m	ramp	
	 Basement 	1.50 m	2 m & 1.5 m	MR
	c. Protection of exits	1.50 III	2 m, 1.5 m	MR
	 Fire check door 			
	 Pressurization 	Required	Provided	MR
	e. No. of continuous staircases to	Required	Provided	MR
	terrace	04 Nos.		
	g. Width of Corridor	04 Nos.	06 Nos.	MR
	h. Door Size	2.00 m	2.50 m	MR
3	Compartmentation.	1.25 m	1.00 m & 1.25 m	MR
_				
	THE CHECK GOOF	Required	Provided	MR
	Sealing of electrical shafts	Required	Provided	MR
	 Fire rating of shaft door 	02 hrs.	02 hrs.	MR
	Water curtain	N/A	N/A	N/A
	 Fire Dampers 	Required	Provided	MR
	Smoke Management System.			IVIIC
	 Basement 	Required	Provided	MR
	 Upper floor 	Required	Provided	MR
	Fire Extinguishers			.,,,,
	Total numbers	120 Nos.	140 Nos.	MR
	• types	ABC & Co2	ABC & Co2	MR
1	IS marking	ISI marked	ISI marked	
		151 marked	131 marked	MR



	Tel Carlot					
6	First-aid-Hose Reels. Total numbers of each floor	06 Nos	Drovided			
	 Length of hose reel hose 		Provided	MR		
	Nozzle diameter	30 M	Provided	MR		
		05 mm	Provided	MR		
7	Automatic fire detection and alarming system					
	Type of detectors	Heat & Smoke	Provided	MR		
	 Location of main panel 	Control room	Provided	MR		
	 Location of repeater panel 	Security room	Provided	MR		
	Alternate source of power	Battery & DG Se	t Provided	MR		
0	Hooter's location	Staircase	Provided	MR		
8	MOEFA	Required	Provided	MR		
9	Public address System.	Required	Provided	MR		
10	Automatic Sprinkler System –			IVIIC		
	Basement	Required	Provided	MR		
	upper floor	Required	Provided	MR		
	 sprinkler above false ceiling 	Required	Provided	MR		
11	Internal Hydrants			-		
	 size of riser/down-comer 	150mm	Provided	MR		
	 Number of hydrants per floor 	06 Nos.	Provided	MR		
	Hose Box	06 Nos.	Provided	MR		
12	Yard Hydrants.					
	 Total number of hydrants 	11 Nos.	13 Nos.	MR		
	Hose Box	11 Nos.	13 Nos.	MR		
13	Pumping Arrangements.		13 1103.	IVIK		
	Ground Level					
	Discharge of main Pump	2850 LPM	Provided	MR		
	➤ Head of Main Pump	60 M	Provided	MR		
	Number of main pumps	2 Nos.	Provided	MR		
	Jockey pump out put		Provided	MR		
	Jockey pump head	60M	Provided	MR		
	Standby pump out put	2850 LPM	Provided	MR		
	Standby pump Head	60 M	Provided	MR		
	Auto Starting /Manual	Required	Provided	MR		
	stopping					
	Pump House Access	Required	Provided	MR		
	Terrace Level	NY/-				
	Discharge of pump	N/A	N/A	N/A		
	Head of the Pump	N/A	N/A	N/A		
	Power supply	N/A	N/A	N/A		
	Auto Starting of pump	N/A	N/A	N/A		
14	Captive Water Storage for Fire					
	Fighting.					
	Underground tank capacity	2,00,000 Ltrs	2,00,000 Ltrs	MR		
	> Draw-off connection	Required	Provided	MR		
	Fire service inlet	Required	Provided	MR		
	Access to tank	Required	Provided	MR		
	Overhead Tank capacity	50,000Ltrs	50,000Ltrs	MR		
15	Exit Signage.	Required	Provided	MR		





$6 \mid P$	Provision of Lifts.			
	 Pressurization of Lift Shaft 	Required	Provided	MR
	 Pressurization of Lift lobby 	Required	Provided	MR
-	Communication in lift car	Required	Provided	MR
-	• Firemen's grounding switch	Required	Provided	MR
17	Lift Signage	Required	Provided	MR
17 18	Standby power supply Refuge Area.	Required	Provided	MR
19	Total areaLocationFire Control Room	N/A N/A	N/A N/A	N/A N/A
	Detector system panel Flow switch	Required	Provided	MR
	1 low Switch nanel	Required	Provided	MR
	PA system panel Battary I in the system panel	Required	Provided	MR
	Battery backup	Required	Provided	MR
2	Building Floor Plans Special Fire Protection systems for protection of any in Private Protection of any in Private P	Required	Provided	MR
L	protection of special Risks, if any:	Required	Provided in all LT & HT Panels	MR

The fire protection systems provided in the building were tested, checked and functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, The Fire Safety Certificate issued vide Letter No. F6/DFS/MS/NDZ/2019/2308 Dated 12/12/19 renewal under rule is

Signature of the Inspecting Officer Name :Deepak Kumar

Designation : ADO (Shahd) Signature of the Inspecting Officer Name : A.K. Jaiswal

Designation : D.O. (ED)

Déreeta

T. Letteris put up for sty. pl.