



No.F.6/DFS/MS/School/2023/NDZI/54

Dated: 27/01/2023

FIRE SAFETY CERTIFICATE

Certified that the **Saraswati Public Secondary School**, located at Budh Vihar, Mandoli, Delhi-110093, building comprised of **Ground and Two Upper Floors**, owned / occupied by Saraswati Public Secondary School, has already been issued issued NOC/FSC vide letter No. F6/DFS/MS/2006/2979 dated 06/10/2006. The premises was re-inspected by the officer concerned of this department on **07/01/2023** in presence of Mrs. Santosh Aggarwal and observed that all the Fire Prevention and Fire Safety arrangements provided in the premises, found in good working condition. The premises have therefore deemed complied with the Fire Prevention and Fire Safety Requirements in accordance with Circular No. 262-362 Dt. 17/01/2005 issued by Director of Education and the building/premises is fit for occupancy class "**Educational**" (**Group-B**) with effect from **27/01/2023** for a period of **three years**, subject to conditions printed below.

Issued on 27/01/2023 **at New Delhi by.**


27/01/23
(S.K. DUA)

**DY. CHIEF FIRE OFFICER
DELHI FIRE SERVICE.**

Copy to:-

1. The Principal, Saraswati Public Secondary School, Budh Vihar, Mandoli, Delhi-110093.
2. The Dy. Director of Education, Old Secretariat, Civil Lines, Delhi-110054.

Conditions for the validity of Fire Safety Certificate:

1. All the fire safety arrangement provided therein shall be maintained in good working conditions at all times.
2. Loss of life or property due to non-functional fire safety measure shall be at the responsibility of the Management.
3. The trained fire fighting staff should be available round the clock.
4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
5. This certificate cannot be treated in any case for regularizations of unauthorized construction, if any.
6. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.
7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.

N/7

INSPECTION REPORT

1. Name & address of the building: Saraswati Public Secondary School, Budh Vihar, Mandoli, Delhi-110093.
2. Building is comprised of : G+2 Upper Floors
3. Type of Occupancy : Educational
4. Type of Case : Renewal
5. Details of previous NOC : F6/DFS/MS/2006/2979 dated 06/10/2006
6. Fire Safety directives Letter No.: DOE Circular No. 262-362 Dt. 17/01/2005
7. Date of inspection : 10/01/2023
8. Name of the Inspecting Officer : A.K. Jaiswal, D.O. (E.D.)
9. Name and designation of Officer from the building side : Mrs. Santosh Aggarwal
10. Year of Construction : 2005-06
11. Applicant's letter received : through E-mail dated 07/01/2023

S.No.	Minimum Standards on fire prevention and fire safety U/R 33	D.O.E. Cir Req. 17/01/2005	Provided at Site	Remarks
1	Access to building			
	• Road width	6.0 m	6.0 m	M/R
	• Gate width	4.5m	On Road	MR
	• Width of internal road	NA	NA	NA
2	Number, Width, Type and Arrangement of Exits			
	a. Number of Staircases			
	• Upper Floor	01 Nos.	02 Nos.	MR
	• Basement	N/A	N/A	N/A
	b. Width of Staircases			
	• Upper Floor	1.50 M	1.0 m x 2	MR (Old Accepted)
	• Basement	N/A	N/A	N/A
	c. Protection of exits			
	• Fire check door	N/A	N/A	N/A
	• Pressurization	N/A	N/A	N/A
	d. No. of continuous staircases to terrace	01	Provided	MR
	e. Width of Corridor	Required	Provided	MR
	f. Door size	1.0 m	1.0 m	MR
3	Compartmentation			
	• Fire check Door	N/A	N/A	N/A
	• Sealing of electrical Shafts	N/A	N/A	N/A
	• Fire rating of Shaft Door	N/A	N/A	N/A
	• Water Curtain	N/A	N/A	N/A
	• Fire Dampers	N/A	N/A	N/A
4	Smoke Management System			
	• Basement	N/A	N/A	N/A
	• Upper Floors	N/A	N/A	N/A
5	Fire Extinguishers			
	• Total Numbers	06 Nos.	06 Nos.	MR
	• Types	ABC & Co2	ABC & Co2	MR
	• IS Marking	ISI Marked	ISI Marked	MR

6	First-aid-Hose Reels			
	• Total numbers of each floor	01	01	MR
	• Length of hose reel hose	30 m	30 m	MR
	• Nozzle diameter	05 mm	05 mm	MR
7	Automatic fire detection and alarming system			
	• Type of detectors	N/A	N/A	N/A
	• Location of main panel	N/A	N/A	N/A
	• Location of repeater panel	N/A	N/A	N/A
	• Alternate source of power	N/A	N/A	N/A
	• Hooter's location	N/A	N/A	N/A
8	MOEFA	N/A	N/A	N/A
9	Public address System	N/A	N/A	N/A
10	Automatic Sprinkler System			
	• Basement	N/A	N/A	N/A
	• Upper Floor	N/A	N/A	N/A
	• Sprinkler above false Ceiling	N/A	N/A	N/A
11	Internal Hydrants			
	• Size of rise/down-comer	100 mm	Provided	MR
	• Number of Hydrants per Floor	01	Provided	MR
	• Hose Box	01	Provided	MR
12	Yard Hydrants			
	• Total number of Hydrants	N/A	N/A	N/A
	• Hose Box	N/A	N/A	N/A
13	Pumping Arrangements			
	• Ground Level			
	➤ Discharge of main Pump	N/A	N/A	N/A
	➤ Head of Main Pump	N/A	N/A	N/A
	➤ Number of main Pumps	N/A	N/A	N/A
	➤ Jockey pump output	N/A	N/A	N/A
	➤ Jockey pump head	N/A	N/A	N/A
	➤ Standby pump output	N/A	N/A	N/A
	➤ Standby pump head	N/A	N/A	N/A
	➤ Auto starting/Manual stopping	N/A	N/A	N/A
	➤ Pump house access	N/A	N/A	N/A
	• Terrace Level			
	➤ Discharge of pump	220 LPM	Provided	MR
	➤ head of the pump	40 MH	Provided	MR
	➤ Power supply	Required	Provided	MR
	➤ Auto Starting of pump	Required	Provided	MR
14	Captive Water Storage for Fire Fighting			
	• Underground tank capacity	N/A	N/A	N/A
	➤ Draw-off connection	N/A	N/A	N/A
	➤ Fire service inlet	N/A	N/A	N/A
	➤ Access to tank	N/A	N/A	N/A
	• overhead Tank capacity	2500 Ltrs.	Provided	MR
15	Exit Signage	Required	Provided	MR

16	Provision of Lifts			
	• Pressurization of Lift Shaft	N/A	N/A	N/A
	• Pressurization of Lift lobby	N/A	N/A	N/A
	• Communication in lift car	N/A	N/A	N/A
	• Firemen's grounding switch	N/A	N/A	N/A
	• Lift Signage	N/A	N/A	N/A
17	Standby power supply	N/A	N/A	N/A
18	Refuge Area			
	• Total area	N/A	N/A	N/A
	• Location	N/A	N/A	N/A
19	Fire Control Room			
	• Detector system panel	N/A	N/A	N/A
	• Flow switch panel	N/A	N/A	N/A
	• PA system panel	N/A	N/A	N/A
	• Battery backup	N/A	N/A	N/A
	• Building floor plans	N/A	N/A	N/A
20	Special Fire Protection systems for protection of special Risks, if any:	N/A	N/A	N/A

Note:-Shortcomings issued by letter No. F6/DFS/MS/2022/NDZ/755 Dated 26/12/2022 have been complied.

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required in Director of Education Circular No. 262-362 Dt. 17/01/2005, The Fire Safety Certificate issued vide letter no. F6/DFS/MS/2006/2979 dated 06/10/2006 is recommended to be renewed.

Ashok Kumar Jaiswal
20/1/2023

Signature of the Inspecting Officer
Name: Ashok Kumar Jaiswal
Designation: D.O. (East. Div.)

~~Dy. CFO (NDZ)~~ F.T. please.

KVP
23/01/23

~~DO (ED)~~ F.T. is added for sign. please.

~~Dy. CFO (NDZ)~~

KVP
23/01/23

Ashok Kumar Jaiswal
25/01/2023

F.T. wing