

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2023/ 35

Dated:-0/../02/2023

FIRE SAFETY CERTIFICATE

Certified that the Coral Plaza Guest House located at 2039/7, Gali No. 7, Chauna Mandi, Pahar Ganj, New Delhi is comprised of Ground + 04 Upper floors, Ground floor (02 guest rooms + Reception), 1st floor to 3rd floor (04 guest rooms at each floor) 4th floor not in use as per affidavit dated 24.12.2019, total 14 guest rooms up to third floor only, The FSC was earlier granted by this department vide letter No.F6/DFS/MS/GH/NDZ/2020/88 dated 04/03/20 for 14 guest rooms up to third floor only. Now, the premises was re-inspected by the officer concerned of this department on 25/01/23 in the presence of Manager and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, (Sub Division-A-1) Ground floor (02 guest rooms + Reception), 1st floor to 3rd floor (04 guest rooms at each floor) total 14 guest rooms up to third floor only, with effect from . D. / . 2.42023 for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued . 01./02/.20.2.3..at New Delhi by.

(S.K. Dua) Dy. Chief Fire Officer

Delhi Fire Service

Copy to:-

- 1. The Commissioner of North, MCD, Civic Centre, New Delhi, to kindly ensure the occupancy as detailed above.
- 2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi online ID No. 2022120220972 dated 02.12.2022.
- 3. The Manager, Coral Plaza Guest House at 2039/7, Gali No. 7, Chauna Mandi, Pahar Ganj, New Delhi.

Condition for the validity of Fire Safety Certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the
- The trained fire fighting staff should be available round the clock. 3.
- The compliance with regards to electrical installation, structural stability, set back area, occupancy and any deviation in construction etc. shall be verified from authority concerned.
- This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".
- 9. Any flammable material for interior decoration is prohibited.

MM7 INSPECTION REPORT

	Name & address of the building Coral Plaza Guest House located at 2039/7, Gali No. 7, Chauna Mandi, Pahar Ganj, New Delhi Residential, Sub Division-A-1 Ground + 04 Upper floors, Ground floor (Reception + 02 guest rooms), 1st floor to 3rd floor (04 guest rooms at each floor), 4th floor not in use as per affidavit dated 24.12.2019, Toatl -14 guest room Renewal Details of previous FSC:- Pire safety directives No Date of inspection:- Name of the inspecting officer:- Name of the inspecting officer:- Name of the publication of the provious FSC:- Coral Plaza Guest House located at 2039/7, Gali No. 7, Chauna Mandi, Pahar Ganj, New Delhi Residential, Sub Division-A-1 Ground + 04 Upper floors, Ground floor (Reception + 02 guest rooms at each floor), 4th floor not in use as per affidavit dated 24.12.2019, Toatl -14 guest room Renewal No. F6/DFS/MS/GH/NDZ/2020/88 dated 04/03/20. Fire safety directives No Date of inspection:- N/A 25/01/23 Sh. Ravinder Singh (ADO/CC)					
	Name & designation of officer					
	From the building side:-	Manager				
9	Year of construction:-	2013				
	Applicant's letter No:-	Online ID No.	2022120220972 da	Old Case		
S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement/ Existing fire safety arrangements	Provided at site	Remarks MR/NMR		
1.	Access to Building					
	1) Road width	N/A	06 mtr.	N/A		
	2) Gate width	N/A	N/A	N/A		
	3)Width of internal road	N/A	N/A	N/A		
2	Number, Width Type & Arr	angement of Ex	cits			
2.	A. Number of staircases					
	1. Upper floors	01 Nos.	01 Nos.	MR		
	2. Basements	N/A	N/A	N/A		
	B. Width of staircase			> 4D		
	1. Upper floors	1.5 mtr.	1.5 mtr.	MR		
	2. Basements	N/A	N/A	N/A		
	C. Protection of exits			N/A		
	1. Fire check door	N/A	N/A	N/A		
	2. Pressurization	N/A	N/A	MR		
	D. No. of continuous	01	01	NIIX		
	staircase to terrace		1.5 mtr	MR		
	E. Width of corridor	1.5 mtr.	1.5 mtr. 1.0 mtr.	MR		
	F. Door size	1.0 mtr.	1.0 mu.	1111		
3.	Compartmentation	1	N/A	NA		
J.	1) Fire check door	N/A	N/A N/A	N/A		
	2) Sealing of electrical shafts	N/A		NA		
	3) Fire rating of shaft door	N/A	N/A N/A	NA		
	4) Water curtain	N/A	N/A	NA		
	5) Fire Dampers	N/A	18/78	1		
4.	Smoke Management System	40 A CIPILI	N/A	NA		
7.	1) Basements	30 ACPH	Natural/Exhaust	MR		
	2) Upper floors	12 ACPH	fan			
5.	Fire Extinguishers	11 Nos.	12 Nos.	MR		
	1) Total numbers					



	,			11.10
	2) Types	ABC & CO2	ABC & CO2	MR
	3) ISI marking	Required	Provided	MR
6.	First-Aid Hose Reel	•		
0.	1) Total number of eachfloor	01	01	MR
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR
	3) Nozzle diameter	05 mm	05 mm	MR
7.	Automatic Fire Detection &	Alarming Syste	em	
/•	1) Type of detectors Co type	Required	Provided	MR
	2) Location of main panel	Ground floor	Provided	MR
	3) Location of repeater panel	N/A	N/A	N/A
	4) Alternate source of power	Required	Provided	MR
	5) Hooter's Location	at each floor	Provided	MR
	MOEFA	N/A	Provided	N/A
8	Public Address System	N/A	Provided	N/A
9.	Public Address System		1101100	
10.	Automatic Sprinkler System	N/A	N/A	N/A
	1) Basement	N/A	N/A	N/A
	2) Upper floors		N/A	N/A
	3) Sprinkler above false	N/A	13/7	
	ceiling			
11.	Internal Hydrants	NI/A	N/A	N/A
	1) Size of riser/down-comer	N/A	N/A	N/A
	2) Number of hydrants per	N/A	IN/A	14/74
	floor	27/4	NI/A	N/A
	3) Hose box	N/A	N/A	IN/A
12.	Yard Hydrants	T	121/4	N/A
	1) Total number of hydrants	N/A	N/A	
	2) Hose box	N/A	N/A	N/A
3.	Pumping Arrangement			
	1) Ground level	N/A	N/A	N/A
	a) Discharge of main	N/A	N/A	N/A
	pump			
	b) Head of main pump	N/A	N/A	N/A
	c) Number of main	N/A	N/A	N/A
	pump			
	d) Jockey pump out put	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		14/2	1 1/2	17/1
	output	N/A	N/A	N/A
	g) Stand by pump head		N/A N/A	N/A N/A
	h) Auto	N/A	N/A	N/A
	starting/Manual			
	stopping			
	2) Terrace level			
	a) Discharge of pump	450 LPM	450 LPM	MR
	b) Head of pump	30 mtr.	30 mtr.	MR
	c) Power supply	Required	Provided	MR
		Required	Provided	MR
	,	Required	TTOVIGEG	IVIIC
	pump			
	Captive Water Storage for I 1) Under ground tank capacity	Fire Fighting N/A	N/A	N/A

	a) Draw-off connection	N/A	N/A	N/A
	b) Fire service inlet	N/A	N/A	N/A
	c) Access to tank	N/A	N/A	N/A
	 d) Over head tank capacity 	5000 ltr.	5000 ltr.	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.	1		
	 a) Pressurization of lift shaft 	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	 c) Communication in lift car 	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risk, if any: ABC & CO ²			MR

The fire protection systems provided in the guest house building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, if approved we may ask renew the FSC issued vide letter no F6/DFS/MS/GH/NDZ/2020/88 dated 04/03/20, up to third floor only under rule 35 of the Delhi Fire Service rules 2010. Accordingly, DFA is put up for kind perusal and signature please.

Signature of the Inspecting Officer

Name: - Ravinder Singh Designation: - ADO (CC)

1 /cs

1R

IR IR IR

1R

F.T. plea

Liv groups

As cubbo

As opposed, For butut forker

Dervoor

NNO 81/02/23

12/23