

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI–110001

No. F.6/DFS/MS/Hotel/2023/SZ/

Dated: 3. Q. 1. Q. /. /2023

FIRE SAFETY CERTIFICATE

Certified that the **M/s HOTEL THE CLARIDGES** at 12 Dr. A. P. J. Abdul Kalam Road, New Delhi 110011 comprised of Basement, Ground plus three upper floors owned/occupied by A Unit of Claridges Hotel Pvt Ltd. was issued Fire Safety Certificate by this department vide letter No. F6/DFS/MS/Hotel/2020/SZ/38 dated 15/01/2020. The premise was re-inspected by the officer concerned of this department on 16/01/2023 in the presence of Mr. Rohit Kumar Sharma and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "**Residential & Lodging**", **Group-A-6**" (Starred Hotel) with effect from the date of issue $\frac{10}{2023}$ for a period of **Three years** in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on _____/2023 at New Delhi by

(SUNIL CHAWDHARY) DY. CHIEF FIRE OFFICER (SZ) DELHI FIRE SERVICE

Copy to: -

1/10

- 1. The Addl. Commissioner of Police (Lic.), 1st Floor, P.S. Defence Colony, New Delhi-110049.
- 2. M/s HOTEL THE CLARIDGES at 12 Dr. A. P. J. Abdul Kalam Road, New Delhi 110011

Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. The basement shall be used as per the provisions of BBL /NBC Part- IV
- 4. All the staff members must know the correct method of operation of fire fighting system.
- 5. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <u>www.dfs.delhigovt.nic.in</u>
- 6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."





	INSPECTI	ON REPORT			
1	Name & Address of the Building	M/s HOTEL			
		M/s HOTEL THE CLARIDGES at 12 Dr. A.P.J			
2	Type of Occupancy	Addul Kalam Road New Delhi 110003			
3	Building Comprised of	Residential &	Loading "Group-A-6"		
4	Type of Case	Basement, Gro	und + 03 upper floors.		
5	Details of Previous NOC	Renewal			
6	Fire Safety Directives Letter No	F6/DFS/MS/H	otel/2020/SZ/38 dated 1	5-01-2020	
	Energy Directives Eciler NO	F6/DFS/MS/79	9-18 dated 19/01/1978		
7	Date of Inspection	F6/MS/DFS/79	2-210 dated 17/06/1979		
8	Name of the Inspecting Officers	16/01/2023			
9	Name & Designation of Officers	DO (South) &	ADO (BCP)		
	from the building side	Mr. Rohit Kumar Sharma			
10	Year of construction				
11	Applicant letter No.	1952			
S. No.	Minimum standards on Fire Prevention	Outdoor diary no 8808 Dated 05-12-2022			
	and Fire Safety U/R 33	Old NOC Provided at Site		Remarks	
1	Access to Building.	Requirements		MR/NMR	
	Road width		1		
	Gate width	06 mtr	24 mtr	MR	
- 1	 Width of internal road 	05 mtr	Provided	MR	
2	Number, width, type & arrangement of exits.	-NA-	-NA-	-NA-	
	a) Number of Staircase	1			
		GF to 2 nd F:-5 Nos			
	Upper floors.Basement floor.	2^{nd} F to 3^{rd} F: 03 No	Provided	MR (old case)	
		03 Nos	02 Nos & 1 ramp	MR (old case)	
	b) Width of Staircase				
	Upper floors	1.50 mtr	1.20m each	MR (old case)	
	Basement floor	1.50 mtr	1.20m (each) & 04 ramp	MR (old case)	
	c) Protection of exits				
	Fire check door	Required	Provided	MR	
	> Pressurization	-NA-	-NA-	-NA-	
	d) No. of continuous staircase to terrace	Required	03 Nos	MR	
	e) Width of corridor	-NA-	-NA-	-NA-	
3	f) Door size	1 mtr	1.0 mtr (Final exit)	MR	
3	Compartmentation. • Fire check door.		1		
		-NA-	-NA-	-NA-	
	Sealing of electrical shafts.Fire rating of shaft door.	-NA- -NA-	-NA-	-NA-	
	Water curtain	-NA- -NA-	-NA-	-NA-	
	 Fire dampers. 	-NA- -NA-	-NA-	-NA-	
4	Smoke Management system.	-11/1-	-NA-	-NA-	
•	Basement	30 ACPH	Exhaust fr	-	
	Upper floors	12 ACPH	Exhaust fan provided	MR	
5	Fire Extinguishers.	12 ACTH	Exhaust fan provided	MR	
	Total numbers	25 Nos	46 N		
	 Types 	ISI marked	46 Nos	MR	
	ISI Marking		W.CO2 & ABC	MR	
6	First Aid Hose Reels.		Provided	MR	
	Total numbers on each floor.		0	-	
	 Length of hose-reel hose. 	Hose Reel	One	MR	
	 Nozzle Diameter 	1000 1001	30m	MR	
			05 mm	MR	

M


.

N/21

and the second se
etter re

8	MOEFA	Required	Provided	MR
9	Public Address System	Required	Provided	MR
10	Automatic Sprinkler System			
	Basement	Required	Provided	MR
	 Upper floors 	Required	Provided	MR
	 Sprinkler above false ceiling 	Required	Provided	MR
11	Internal Hydrants.) (B
	 Size of Riser/Down-comer 	150 mm	150 mm	MR
	 Number of Hydrant per floor 	02 no	03 no	MR
	• Hose box.	02 no	03 no	MR
12	Yard Hydrants.	I		
14	Total number of hydrants.	04 Nos	Provided	MR
	 Hose box. 	04 Nos	Provided	MR
12	• Hose box. Pumping arrangements.			
13	Ground Level			
	 Ground Level Discharge of main pump. 	2250 LPM	Provided	MR
	 Head of main pump. 	60m	Provided	MR
	 Number of main pumps. 	02	Provided	MR
	Jockey Pump output.	180 LPM	Provided	MR
	Jockey Pump head.	60m	Provided	MR
	Standby Pump output.	2250 LPM	Provided	MR
	Standby Pump head.	60m	Provided	MR
	Auto Starting/Manual Stopping.	Required	Provided	MR MR
	Pump house access.	Required	Provided	MR
	Terrace Level		NT A	-NA-
	Discharge of pump.	-NA-	-NA- -NA-	-NA-
	> Head of pump.	-NA- -NA-	-NA- -NA-	-NA-
	Power supply.	-NA-	-NA-	-NA-
	 Auto starting of pump. Captive water storage for fire fighting. 	-11/1-	1111	
14	Captive water storage for fire lighting. Underground tank capacity.	1,50,000 ltrs	Provided	MR
	 Underground tank capacity. Draw-off connection. 	Required	Provided	MR
	 Fire Service Inlet. 	Required	Provided	MR
	 Access to tank. 	Required	Provided	MR
	Overhead tank capacity	20,000 ltrs	Provided	MR
15		Required	Provided	MR
15	Exit Signage. Provision of Lifts.			
16	Pressurization of lift shaft.	-NA-	-NA-	-NA-
	 Pressurization of lift lobby. 	-NA-	-NA-	-NA-
	Communication in lift car.	Required	Provided	MR
	Fireman's switch.	Required	Provided	MR
	Lift signage.	Required	Provided	MR
17	Standby Power Supply	Required	Provided	MR
17	Refuge Area			
10	Total area	-NA-	-NA-	-NA-
	• I otal alca			





19	Fire Control Room.			
	Detector system panel	Required	Provided	MR
	 Flow switch panel. 	-NA-	-NA-	-NA-
	 PA system panel. 	Required	Provided	MR
	Battery backup	Required	Provided	MR
	 Building floor plan. 	-NA-	-NA-	-NA-
20	Special Fire Protection System for the Protection of special Risk, if any.		Co2 local application system provided in LT & HT Panel.	-NA-

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/Hotel/2020/SZ/38 dated 15-01-2020, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

un 19/11 Signature of the Inspection Officer Signature of the Inspecting Officer Name: Sh. Rajesh Kumar Name: Sh. Manoj Kumar Sharma Design: ADO (BCP) Design: DO (South) Dy. CFO (\$Z) As approved, F.T. Letter is portup to As signature PI 1 2023 Decesisi pooded