

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE

NEW DELHI- 110 001

Dated: 16/02/2023

C73

No.F.6/DFS/MS/GH/2023/NDZ/ 47

## FIRE SAFETY CERTIFICATE

Certified that M/s Marigold Rooms (Guest House) located atD-7, Krishana Nagar, Delhi-110051, comprised of basement, stilt, ground plus three upper floors (basement lying vacant, stilt parking, ground floor 05 guest rooms, 1<sup>st</sup>floor 06 guest rooms, 2<sup>nd</sup> floor 06 guest rooms&3<sup>rd</sup> floor 06 guest rooms, (Total 23 guest rooms) owned/occupied byM/s Marigold Rooms was issued FSC vide letter no. F.6/DFS/MS/GH/2019/NDZ/2282 dated 10/12/19. The premises was re-inspected by the officer concerned of this department on 08/02/2023in the presence of Mr. Deepakand observed that all the fire prevention and fire safety arrangements provided in the premises found in good working condition. The premises have therefore deemed complied with rule 33 of Delhi Fire Service Rule, 2010and that the building/premises is fit for occupancy class "Residential, Group- A"(Lodging or Rooming House) with effect from ./6/02-10.23....for a period of **three** years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010 & also conditions printed below.

(S.K. DUA) DY. CHIEF FIRE OFFICER DELHI FIRE SERVICE

To:-

Sh. VineetArora, House No. 223 A, West Azad Nagar, Delhi-110051

Copy to:-

The Joint Commissioner (Lic.) 1<sup>st</sup> floor Police Station Defence Colony, New Delhi

## MHA ID No. 2023012701149

## Conditions for the validity of Fire Safety Certificate

1. All the means of escape shall be kept free of all type of obstruction all the time.

- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipment shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.
- 5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction /unauthorized use of land if any.
- 6. The owner / occupier shall apply for renewal of this Fire Safety Certificate of the Director in Form 'J' [sub rule (1) of rule (37)] along with a copy of this Certificate, Six Months prior to its expiry.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on <u>www.dfs.delhigovt.nic.in</u>



1. Name & address of the building	: Marigold Rooms
	D-7, Krishana Nagar, Delhi-110051
2. Building is comprised of	:Basement (Vacant), Stilt(Parking),
	ground floor (05 rooms), first floor (06 rooms),
	second floor (06 rooms), third floor (06 rooms).
3. Type of Occupancy	:Residential Building
4. Type of Case	:Renewal
5. Details of Previous NOC letter	:F.6/DFS/MS/GH/2019/NDZ/2282 dt 10/12/19
6. Fire Safety directive letter No	: NBC Part VI
7. Date of Inspection	:08/02/2023
8. Name of the Inspecting officers	: ADO (Shd.), Deepak Kumar
9. Name and designation of Officer	
from the building side	: Mr. Deepak
10. Year of Construction	:2015-2016
11. Applicant's letter No	:2023012701149 dated 02/02/2023

- ]

1

	Minimum Standards on fire prevention and fire safety U/R33	NBC Part-IV Requirement	Provided at Site	Remarks MR/NMR		
	Access to building.					
	Road width	06mtr.	09mtr.	MR		
	Gate width	N/A	N/A	N/A		
	<ul> <li>Width of internal road</li> </ul>	N/A	N/A	N/A		
02						
	a. Number of Staircases					
	Upper Floor	02 nos.	02nos.	MR		
	<ul> <li>Basement</li> </ul>	02 nos.	02 nos	MR		
	B. Width of Staircases					
	Upper Floor	1.50mtr.	1.50mtreach	MR		
	<ul> <li>Basement</li> </ul>	1.50 mtr.	1.50mtr&1.14mtr	MR		
	c. Protection of exits					
	<ul> <li>Fire check door</li> </ul>	N/A	N/A	N/A		
	<ul> <li>Pressurization</li> </ul>	N/A	N/A	N/A		
	d. No. of continuous staircases toterrace	02 no.	02 no.	MR		
	e. Width of Corridor	1.50mtr.	1.15mtr	MR (old accepted		
	f. Door Size	01mtr.	01mtr.	MR		
03	Compartmentation.					
-	Fire check door	N/A	N/A	N/A		
	<ul> <li>Sealing of electrical</li> </ul>	Required	Provided	MR		
	shafts	N/A	N/A	N/A		
	<ul> <li>Fire rating of shaft door</li> </ul>	N/A	N/A	N/A		
	<ul><li>Water curtain</li><li>Fire Dampers</li></ul>	N/A	N/A	N/A		
04	Smoke Management System.					
-	Basement	Required	Provided	MR		
	Upper floor	Required	Provided	MR		
05.	Fire Extinguishers.					
	<ul> <li>Total numbers</li> </ul>	12nos.	18 nos.	MR		
	• types	ABC /CO2	ABC /CO <sub>2</sub>	MR		
-	IS marking	ISI marked	ISI marked	MR		

06	First-aid-Hose Reels.					
	Total numbers on each floor	01 No.	01 No.	MR		
	<ul> <li>Length of hose reel hose</li> </ul>	30 mtr.	30 mtr.	MR		
	Nozzle diameter	05 mm	05 mm	MR		
)7	Automatic fire detection and alarming system.					
	Type of detectors	Required (CO)	Provided	MR		
	<ul> <li>Location of main panel</li> </ul>	N/A	N/A	N/A		
	<ul> <li>Location of repeater panel</li> </ul>	N/A	N/A	N/A		
	Alternate source of power	N/A	N/A	N/A		
	Hooter's location	N/A	N/A	N/A		
08	MOEFA	Required	Provided	MR		
)9	Public address System.	Required	Provided	MR		
0						
	Basement	N/A	Provided	MR		
	upper floor	N/A	N/A	N/A		
	<ul> <li>sprinkler above false ceiling</li> </ul>	N/A	N/A	N/A		
11	Internal Hydrants		1.1// 1	11/		
	<ul> <li>size of riser/down-comer</li> </ul>	100 mm	100 mm	MR		
	<ul> <li>Number of hydrants per floor</li> </ul>	01 no	01 no	MR		
	Hose Box	01 no	01 no	MR		
12	Yard Hydrants.					
	<ul> <li>Total number of hydrants</li> </ul>	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
13	Pumping Arrangements.					
	Ground Level	N/A	N/A	N/A		
	Discharge of main Pump	N/A	N/A	N/A		
	Head of Main Pump	N/A	N/A	N/A		
	Number of main pumps	N/A	N/A	N/A		
	Jockey pump out put	N/A	N/A	N/A		
	Jockey pump head	N/A	N/A	N/A		
	Standby pump out put	N/A	N/A	N/A		
	Standby pump Head	N/A	Ń/A	N/A		
	Auto Starting /Manual stopping	N/A	N/A	N/A		
	<ul> <li>Pump House Access</li> <li>Terrace Level</li> </ul>	N/A	N/A	N/A		
	<ul> <li>Discharge of pump</li> </ul>	900 Lpm.	900 Lpm			
	Head of the Pump	40 mtr	40 mtr	MR MR		
	Power supply	Required	Provided	MR		
	Auto Starting of pump	Required	Provided	MR		
14	Captive Water Storage for Fire Fighting.					
	<ul> <li>Underground tank capacity</li> </ul>	N/A	N/A	N/A		
	Draw-off connection	N/A	N/A	N/A		
	Fire service inlet	N/A	N/A	N/A		
	> Access to tank	N/A	N/A	N/A		
45	Overhead Tank capacity	10,000 Ltr.	10,000 ltr	MR		
15 16	Exit Signage. Provision of Lifts.	Required	Provided	MR		
.0						
	Pressurization of Lift Shaft	N/A	N/A	N/A		
	Pressurization of Lift lobby	N/A	N/A	N/A		
	Communication in lift car	Required	Provided	MR		
	Firemen's grounding switch	Required	Provided	MF		
	<ul> <li>Lift Signage</li> </ul>	Required	Provided	MF		

b/30.



17	Standby power supply	Required	Provided	MD	
18	Refuge Area.	Required	Provided	MR	
	Total area	N/A	N/A	N/A	
	<ul> <li>Location</li> </ul>	N/A	N/A	N/A	
19	Fire Control Room				
	<ul> <li>Detector system panel</li> </ul>	N/A	N/A	N/A	
	<ul> <li>Flow switch panel</li> </ul>	N/A	N/A	N/A	
	<ul> <li>PA system panel</li> </ul>	N/A	N/A	N/A	
	<ul> <li>Battery backup</li> </ul>	Required	Provided	MR	
	<ul> <li>Building Floor Plans</li> </ul>	N/A	N/A	N/A	
20	Special Fire Protection systems for protection of special Risks, if any:	N/A	N/A	N/A	

6

MR MR MR

MR N/A V/A V/A I/A R

**Note:- (1)** Owner of the building has submitted an undertaking that a room on the terrace is closed and will not be used for guest house purpose in any case (undertaking dated 24/12/2022 attached at page C-64) and corridor is 1.15 meter in the guest house if agreed we may accept corridor width 1.15 meter being old case and existing building.

(2) Fire check doors not required as per Gazette notification dated 27/05/2019 as number of occupants are not more than 10.

The fire protection systems provided in the building were tested/checked and found functional at the time of inspection.

Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F.6/DFS/MS/GH/2019/NDZ/2282 dated 10/12/19 renewal under rule 35 of the Delhi Fire Service Rule, 2010 is recommended.

08/02/2023.

Signature of the Inspecting Officer Name : Deepak Kumar Designation : ADO (Shd)

DFA-Blease. F.T. please. (NDZ) Kiv 10/02/23 3/02/223 F.T. is added for sign. fl. DECTOROTEZ, F.Rwing KIV Jozpas