

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/WZ/ BNQT/2023/ *O6* 

Dated: 13 02 2023

## FIRE SAFETY CERTIFICATE

Certified that the M/s. Royal Lush Banquet (A unit of Royal Lush Private Limited) comprised of basement, ground plus two upper floors located at Plot No. C- 91/10, Ashok Vihar, Block- C, Wazirpur Industrial Area, Delhi- 110052, owned/occupied by the M/s. Royal Lush Private Limited, was granted fire safety certificate by this department vide letter No. F.6/DFS/MS/WZ/2020/BNQT/121 dated 28.02.2020. The banquet hall was re-inspected by the officer concerned of this department on 07/02/2023 in presence of Shri Parvinder Singh (Director) and found that the management have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building / premises is fit for occupancy class Assembly - Group D (Ground plus Two Upper Floors only) with effect from 13 02 2023 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of conditions, under rule 38 of the Delhi Fire Service Rules, 2010, printed overleaf.


Issued on \_\_13/02/2023 \_\_ at New Delhi.

(Dharampal Bhardwaj)
Dy. Chief Fire Officer

9 West Zone

Copy to: -

- Sh. Parvinder Singh, M/s. Royal Lush Banquet, Plot No. C- 91/10, Ashok Vihar, Block-C, Wazirpur Industrial Area, Delhi- 110052.
  - 2. The Deputy Health Officer, Keshav Puram Zone, Municipal Corporation of Delhi, Public Health Department, Keshav Puram, New Delhi.



- 1. All the fire safety arrangement provided there in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. The basement shall be used strictly as per the provision of unified building bye laws.
- 6. This certificate cannot be treated in any case for regularizations of unauthorized
- 7. The management has submitted an undertaking that the basement floor will not be used as Banquet hall and terrace floor as kitchen. If it is used in future, the Fire safety
- 8. "The owner / Occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule37] along with a copy of this Certificate, six
- 9. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.Delhigovt.nic.in.
- 10. This FSC is valid for ground plus two upper floors only.

## **INSPECTION REPORT**

Name & address of the building: M/s. Royal Lush Banquet, located at Plot No. C-91/10, Ashok Vihar, Block- C, Wazirpur Industrial Area, New Delhi- 52.

2. Type of Occupancy : Banquet Hall (Assembly)

3. Type of Case : Renewal

4. Details of previous NOC : F6/DFS/MS/WZ/2020/BNQT/121 dated 28/02/2020

5. Fire Safety directives Letter No.: F.6/DFS/MS/2019/6996 dated 20.11.2019

6. Date of inspection : 07.02.2023

7. Name of the Inspecting Officer: M.K. Chattopadhyay, DO (West)

8. Name and designation of Officer

from the building side : Sh. Parvinder Singh, Director

9. Year of Construction : 2019

10. Applicant's letter no. : MHA portal ID 2023011900843

The banquet hall is comprised of basement, ground plus two upper floors.

S No	Minimum standards on fire prevention and fire safety U/R 33	Requirements as per Rule 35 (6) of DFS Rules- 2010	Provided at site	Remarks MR/NMR		
1.	Access of building					
	Road width	06 mts	Provided	MR		
	Gate width	Required	Provided	MR		
	<ul> <li>Width of internal road</li> </ul>	NA	NA	NA		
2.	Number, width, Type & Arrangements of exits					
	a. Number of staircases					
	<ul> <li>Upper floors</li> </ul>	02	02	MR		
	Basements	02	02	MR		
	b. Width of staircases					
	<ul> <li>Upper floors</li> </ul>	2.0, 1.5 mts,	Provided	MR		
	<ul> <li>Basements</li> </ul>	1.5 mts each	Provided	MR		
	c. Protection of exits		11011404	11221		
	Fire check door	Required	Provided	MR		
	Pressurization	NA	NA	NA		
	d. No of continuous staircase to	02	Provided	MR		
	terrace	2.0 mts	Provided	MR		
	e. Width Of Corridor	2.0, 1.5 mts,	Provided	MR		
	f. Door Size			1,111		
3.	Compartmentation					
	Fire check door	Required	Provided	MR		
	<ul> <li>Sealing of electrical shafts</li> </ul>	NA	NA	NA		
	<ul> <li>Fire Rating of shaft door</li> </ul>	NA	NA	NA		
	Water Curtain	NA	NA	NA		
	Fire Dampers	NA	NA	NA		
4.	Smoke managements System					
	Basements	Required	Provided	MR		
	• Upper floor	Required	Provided	MR		
5.	Fire Extinguishers					
	<ul> <li>Total numbers</li> </ul>	08	Provided	MR		
	<ul> <li>Types</li> </ul>	ABC, CO2 & WCO2	Provided	MR		
	<ul> <li>IS marking</li> </ul>	ISI marked	Provided	MR		



١,	First - Aid Hose Reels					
	Total numbers on each floor	01	Provided	MR		
	<ul> <li>Length of hose reel hose</li> </ul>	30 m	Provided	MR		
	<ul> <li>Nozzle diameter</li> </ul>	5 mm	Provided	MR		
	Automatic fire detection and alarming system					
	Type of detectors	Smoke/Heat	Provided	MR		
	<ul> <li>Location of Main Panel</li> </ul>	Required	Provided	MR		
	<ul> <li>Location of Repeater Panel</li> </ul>	Required	Provided	MR		
	<ul> <li>Alternate source of power</li> </ul>	Required	Provided	MR		
	<ul> <li>Hooters' Location</li> </ul>	Each Floor	Provided	MR		
	MOEFA	Required	Provided	MR		
	Public Address System	NA	NA	NA		
)	Automatic Sprinkler System					
	Basements	Required	Provided	MR		
	Upper Floor	N/A	Provided	N/A		
	Sprinkler above false ceiling	N/A	N/A	N/A		
	Internal Hydrants	- //**	1.7/11	1 1/ / 7		
	Size of riser/down- comer	150 mm	Provided	MR		
	Number of hydrants per floor	01	Provided	MR		
	Hose Box	01	Provided	MR		
2	Yard Hydrants					
	Total number of hydrants	NA	NA	NA		
	Hose Box	NA	NA	NA		
}	Pumping Arrangements					
	Ground Level					
	Discharge of main pump	2280 lpm	Provided	MR		
	<ul><li>Head of main pump</li></ul>	60 mts	Provided	MR		
	Number of main pumps	01	Provided	MR		
	Jockey pump out put	180 lpm	Provided	MR		
	> Jockey pump head	60 mts	Provided	MR		
	Standby Pump out put	2280 lpm	Provided	MR		
	Standby Pump Head	60 lpm	Provided	MR		
	Auto Staring/Manual stopping	Required	Provided	MR		
	Pump House Access	Required	Provided	MR		
	Terrace level     Discharge of pump	2002	n			
	<ul><li>Discharge of pump</li><li>Head of the pump</li></ul>	9000 lpm	Provided	MR		
	Power supply	60 m	Provided	MR		
	<ul><li>Auto starting of pump</li></ul>	Required	Provided	MR		
,	Captive water Storage for fire fighting	Required	Provided	MR		
		2,00,000 lts	Provided	MR		
	<ul> <li>Underground tank capacity</li> <li>Draw of connection</li> </ul>	Required	Provided	MR		
	Fire service inlet	Required	Provided	MR		
	<ul><li>Access to tank</li></ul>	Required	Provided	MR		
	Overhead Tank capacity	10,000 Ltrs Required	Provided Provided	MR MR		
,	Exit Signage	Daguinad	Provided	IVIIX		



1	ion Of Line	from Ground to Up	per Floors	
16	mizotion of Litt Share	NA	NA	NA
		NA	NA	NA
	Communication in the Car	Required	Provided	MR
	Fireman's Grounding Switch	Required	Provided	MR
	Lift Signage	Required	Provided	MR
17	Standby power supply	Required	Provided	MR
18	Refuge Area			
	> Total area	NA	NA	NA
	Location	NA	NA	NA
19	Fire control room			
	Detector system panel	NA	NA	NA
	Flow Switch Panel	NA	NA	NA
	PA System Panel	NA	NA	NA
	Battery backup	NA	NA	NA
	Building Floor Plans	NA	NA	NA
20.	Special Fire Protection Systems for Protection of special Risks, if any;	Required	Provided	MR

The fire protection systems provided in the building were checked & found functional at the time of inspection.

Note: All the shortcomings issued by this department in previous inspection have been complied with by the management.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the NOC issued vide letter No. F6/DFS/MS/WZ/2019/1537 dated 26/07/2022, renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended.

DFA is put up for approval & signature please.

DO. (WES. 11.5.62

Signature of the Inspecting Officer Name: M.K. Chattopadhyay Designation: DO (West Division)

F-

13/2/2023

MS WY