आज़ादी वा अमृत महोत्सव

No.F6/DFS/MS/School/SZ/2023/112

Dated: 17/02/2023

FIRE SAFETY CERTIFICATE

Certified that the S.D.M.C Primary School (Girls), located at Lal Kuan Chungi No.2-I, New Delhi-110044, comprised of Ground floor only (Porta Cabin) was granted Fire Safety Certificate (FSC) by this department vide letter no. F6/DFS/MS/School/2016/SZ/887 dated 30.05.2016. The school building was re-inspected by Assistant Divisional Officer (M. Road) from this department on 02.01.2023 in the presence of Mrs. Renu Kumari Jain (Principal) and found that the school building have deemed complied with the fire prevention and fire safety requirements in accordance with the circular no. 3298 to 3398 dated 01.03.2011 issued by the Directorate of Education and the building (Ground floor only -Porta Cabin) is fit for occupancy of Group B "Educational Building" with effect from 1.7.102 20.2.23 renewed for a period of three years, subject to conditions printed below.

Issued on ... 17 10.2/2023 ... at New Delhi by

(Sunil Chawdhary)

Chief Fire Officer Delhi Fire Service

Copy to:-

- 1. The Directorate of Education, South MCD, S.P.M., Civic Centre, New Delhi.
- 2. The Principal, S.D.M.C Primary School (Girls), located at Lal Kuan Chungi No.2, New Delhi-110044.

Conditions for the validity of Fire Safety Certificate

- 1. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry
- 2. All the means of escape shall be kept free of all the type of obstruction all the time.
- 3. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 4. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc. may be got verified from the authorities concerned.
- 6. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.

~/10

ire (201 e/C

		INSPE	CTION REPORT				
1	Nar	Name & address of the building S.D.M.C Primary School (Girls), located at Lal Kuan Chungi No.2-I, New Delhi-110044.					
2	Bui	ilding is comprised of	Ground floor only (Porta Cabin)				
3	Type of occupancy Type of case Details of previous FSC		Group B –Educational Building Renewal F6/DFS/MS/School/2016/SZ/887 dated 30.05.2016				
4							
5							
6		e safety directives letter no.	F6/Estate/CC/Fire Safety/2011/3298 to 3398 dated				
	safety directives letter no.		01.03.2011				
7		te of inspection	02.01.2023				
8	Name of the inspecting officers		Rajesh Kumar Shukla, ADO (M. Road)				
9	Name of the designation of officer from the building side		Mrs. Renu Kumari Jain (Principal)				
10	Ye	ar of construction	2003				
11	Ap	plicant's letter no.	Outdoor Diary No.5072 dated 31.08.2022				
S.No		nimum standard of fire evention and fire safety U/R 33	Requirement as per DOE Circular dated 01.03.2011	Provided at site	Remarks MR/NMR		
1	Access to Building:						
	A	Road width	6.0 mtrs.	6.0 mtrs.	MR		
	В	Gate width	NA	NA	NA		
	C	Width of internal road	NA	NA	NA		
2	Number, Width, Type and Arrangement of Exits:						
	A	Number of staircases	·				
		a Upper floor	NA	NA	NA		
		b Basement	NA	NA	NA		
	В	Width of staircases					
		a Upper floor	NA	NA	NA		
		b Basement	NA	NA	NA		
	C	Protection of exits	NA	NA	NA		
		a Fire check door	NA	NA	NA		
		b Pressurization	NA	NA	NA		
	D	No. of continuous staircases to terrace	02 nos.	NA	NA		
	E	Width of corridor	1.5 mtrs.	Provided	MR		
	F	Door size	1.0 mtrs (for class room)	1.0 mtrs (for class room)	MR		
3	Co	mpartmentation:	,	1			
	A	Fire check door	NA '	NA	NA		
	В	Sealing of electrical shafts	NA	NA	NA		
	C	Fire rating of shaft door	NA	NA	NA		
	D	Water curtain	NA	NA	NA		
	E	Fire dampers	NA	NA	NA		
4	-	oke Management System:					
	A	Basement	NA	NA	NA		
	В	Upper floor	NA	NA	NA		

MO



5.	Fire Extinguisher:						
	A	Total numbers	06 nos.	06 nos.	MR		
	В	Types	CO ₂ & ABC	CO ₂ & ABC	MR		
	C	ISI marking	Required	Provided	MR		
6	First-Aid-Hose Reel:						
	A	Total numbers of each floor	NA	NA	NA		
	В	Length of hose reel hose	NA	NA	NA		
	C	Nozzle diameter	NA	NA	NA		
7	Au	tomatic Fire Detection and Al					
	A	Type of detectors	NA NA	NA	NA		
	B	Location of main panel	NA	NA	NA		
	C	Location of repeater panel	NA	NA	NA		
	D	Alternate source of power	NA	NA	NA		
	E	Hooters	NA	NA	NA		
8		OEFA:	NA	NA	NA		
9							
		blic Address System:	NA	NA	NA		
10	-	tomatic Sprinkler System: Basement	NIA	NIA	- N. A.		
	A		NA	NA	NA		
	В	Upper floor	NA	NA	NA		
	C	Sprinkler above false ceiling	NA	NA	NA		
11	Internal Hydrants:						
	A	Size of riser/down-comer	NA	NA	NA		
	В	Number of hydrants per floor	NA	NA	NA		
	C	Hose box	NA	NA	NA		
12	Yard Hydrants:						
	A	Total number of hydrants	NA	NA	NA		
	В	Hose box	NA	NA	NA		
13	Pu	mping Arrangements:					
1	Ground level						
	A	Discharge of main pump	NA	NA	NA		
	В	Head of main pump	NA	NA	NA		
	C	Number of main pumps	NA	NA	NA		
	D	Jockey pump out put	NA	NA	NA		
	E	Jockey pump head	NA	NA	NA		
	F	Standby pump out put	NA	NA	NA		
	G	Standby pump head	NA	NA	NA		
	Н	Auto starting /manual	NA	NA	NA		
		stopping					
	I	Pump house access	NA	NA	NA		
2	Terrace Level						
	A	Discharge of pump	NA	NA	NA		
	В	Head of the pump	NA NA	NA NA	NA NA		
	C	Power supply	NA				
	D	Auto starting of pump	NA	NA	NA		

S.D.M.C. Primary School (Girls), located at Lal Kuan Chungi No 2, New Delhi-110044

me



		Primary School (Girls), located at Lal Kuan Ch		u-110044			
4	Cap	tive Water Storage for Fire Fighting:					
	A	Underground tank capacity	NA	NA	NA		
	В	Draw-off connection	NA	NA	NA		
	C	Fire service inlet	NA	NA	NA		
	D	Access to tank	NA	NA	NA		
	E	Overhead tank capacity	NA	NA	NA		
15	Exi	t Signage:	Required	Provided	MR		
16	Pro	rovision of Lifts:					
	A	Pressurization of lift shaft	NA	NA	NA		
	В	Pressurization of lift lobby	NA	NA	NA		
	C	Communication in lift car	NA	NA	NA		
	D	Firemen's grounding switch	NA	NA	NA		
	E	Lift signage	NA	NA	NA		
17	Sta	andby Power Supply:	NA	NA	NA		
18	Re	Refuge Area:					
	A	Total area	NA	NA	NA		
	В	Location	NA	NA	NA		
19	Fire Control Room:						
	A	Detector system panel	NA	NA	NA		
	В	Flow switch panel	NA	NA	NA		
	C	PA system panel	NA	NA	NA		
	D	Battery backup	NA	NA	NA		
	E	Building floor plans	NA	NA	NA		
20	Sr	pecial Fire Protection systems for	NA		NA		
	pr	rotection of special Risks, if any:					

Meeting Requirement (MR), Not Meeting Requirement (NMR), Not Applicable (NA), Provided but Not Functional (PNF), Not Provided (NP).

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

Keeping in view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required in Directorate of Education Circular no. 3298 to 3398 dated 01.03.2011, the FSC issued vide letter no. F6/DFS/MS/School/2016/SZ/887 dated 30.05.2016 is recommended to be renewed.

> Signature of the Inspecting Officer Name Rajesh Kumar Shukla Designation ADO (M. Road)

1

10 P fir

SUE t fo

:lh

cat

re ire fic

yp

ise CCI bs sul

ati ild