

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F.6/DFS/MS/EH/2023/SZ/ 89

Dated. 66. 1.03/2023

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the name and style of M/s Gastronomica Kitchen and Bar located at M-55, M Block Market, Second Floor, Greater Kailash Part-1, New Delhi 110048 in the building comprised of Ground plus Two Upper floors owned/occupied by Unit of Vagabonds Restaurant Pvt Ltd was issued Fire Safety Certificate by this department vide letter no. F.6/DFS/MS/EH/2019/SZ/25 dated 17/01/2020. The restaurant premise was re-inspected by the officer concerned of this department on 28/02/2023 in the presence of Mr. Sanjay (Manager) and found that the said premise have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy Class D "Assembly Building" (Restaurant at Second Floor only) as above with effect from 0.6.../.03.../2023 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 6 / 03 /2023 at New Delhi by

DELHT FIRE SERVICE

Copy to: -

1. The Dy. Health Officer, Public Health Department, South Zone, Green Park, Delhi-110016 (Ref. MHA Portal 2023011100369 dated 31/03/2023)

Conditions for the validity of Fire Safety Certificate: -

- All the means of escape/entry/exit shall be kept free from any obstruction. 1.
- All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- All the staff members must know the correct method of operation of fire fighting system. 3.
- The basement shall be used as per the provisions of BBL /NBC Part- IV.
- The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any
- "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."

A CONTRACTOR OF THE PARTY OF TH	INSPECTIO	N REPORT	The state of the s	AT PM	
1	Name & Address of the Building	M/s Gastronomica Kitchen and Bar (Unit of Vagabonds Restaurant Pvt Ltd) located at M-55, M Block Market, Second Floor, Greater Kailash Part-1, New Delhi 110048			
2	Type of Occupancy	Group-D Assembly Building. (Eating House)			
3	Building Comprised of	Ground plus Two upper floor			
4	Type of Case	Renewal			
5	Details of Previous NOC	F.6/DFS/MS/EH/2019/SZ/25 dated 17/01/2020			
6	Fire Safety Directives Letter No	Nil			
9	Date of inspection	28/02/2023			
8	Name of the Inspecting Officers	DO (South) & ADO (BCP)			
9	Name & Designation of Officers	Mr. Sanjay (Manager)			
	from the building side	J., (
10	Year of construction	1990 Restt. Running at Second floor only			
11	Applicant letter No.	MHA Portal 2023011100369 dated 31/03/2023			
S. No.	Minimum standards on Fire Prevention	Old NOC	Provided at Site	Remarks	
	and Fire Safety U/R 33	requirements		MR/NMR	
1	Access to Building.		1		
	Road width	4.5 m	Provided	MR	
	Gate width	N/A	N/A	N/A	
	Width of internal road	N/A	N/A	N/A	
2	Number, width, type & arrangement of ex	its.			
	a) Number of Staircase				
	Upper floors.	02 Nos	02 Nos	MR	
	Basement floor.	N/A	NA	N/A	
	b) Width of Staircase		1		
	Upper floors	As per circular Dt 22.03.2005	1.50m & 1 m	MR (old case)	
	Basement floor	N/A	N/A	N/A	
	c) Protection of exits				
	> Fire check door	Required	Provided	MR	
	Pressurization	N/A	N/A	N/A	
	d) No. of continuous staircase to terrace	Required	Provided	MR	
	e) Width of corridor	N/A	N/A	N/A	
	f) Door size	02 Exits	Provided	MR	
3	Compartmentation.		J		
	Fire check door.	N/A	N/A	N/A	
	 Sealing of electrical shafts. 	N/A	N/A	N/A	
	 Fire rating of shaft door. 	N/A	N/A	N/A	
	Water curtain	N/A	N/A	N/A	
	Fire dampers.	N/A	N/A	N/A	
4	Smoke Management system.			1	
	Basement	NA	N/A	N/A	
	Upper floors	12 ACPH	Exhaust fan	MR	
5	Fire Extinguishers.			•	
3		08 Nos	08 Nos	MR	
3	Total numbers	00 1105			
3		ABC/CO ₂	ABC-04 & CO ₂ -04	MR	
3	Total numbersTypesISI Marking			MR MR	

m


	 Total numbers on each floor. 	One	Provided	MR
	 Length of hose-reel hose. 	30m	Provided	MR
	Nozzle Diameter	5mm	Provided	MR
7	Automatic fire detection & alarming sys	tem.		1
	Type of detectors	Smoke / Heat	Provided	MR
	 Location of Main Panel 	Required	Provided	MR
	 Location of Repeater Panel 	N/A	N/A	N/A
	 Alternate source of power 	Required	Provided	MR
	 Hooter's location 	Required	Provided	MR
8	MOEFA	Required	Provided	MR
9	Public Address System	N/A	N/A	N/A
10	Automatic Sprinkler System			1
	Basement	N/A	N/A	N/A
	 Ground/ upper floors. 	Required	Provided	MR
	 Sprinkler above false ceiling 	N/A	N/A	N/A
- 11	Internal Hydrants.			1
	Size of Riser/Down-comer	Required	100 mm	MR
	 Number of Hydrant per floor 	Required	One	MR
	Hose box.	Required	One	MR
12	Yard Hydrants.			1
	 Total number of hydrants. 	N/A	N/A	N/A
	Hose box.	N/A	N/A	N/A
13	Pumping arrangements.			
	Ground Level			
	Discharge of main pump.	N/A	N/A	N/A
	 Head of main pump. Number of main pumps. 	N/A	N/A	N/A
	Number of main pumps.Jockey Pump output.	N/A	N/A	N/A
	> Jockey Pump head.	N/A	N/A	N/A
	Standby Pump output.	N/A	N/A	N/A
	Standby Pump head.	N/A	N/A	N/A
	Auto Starting/Manual Stopping.	N/A	N/A	N/A
	Pump house access.	N/A	N/A	N/A
		N/A	N/A	N/A
	Terrace Level			
	Discharge of pump.Head of pump.	450 & 180 LPM	Provided	MR
	Power supply.	30m	Provided	MR
	Auto starting of pump.	Required	Provided	MR
14		Required	Provided	MR
	Captive water storage for fire fighting.			
	 Underground tank capacity. Draw-off connection. 	N/A	N/A	N/A
	Fire Service Inlet	N/A Required	N/A	N/A
	Access to tank.	N/A	Provided	MR
15	Overhead tank capacity. Exit Signage.	10,000 Ltrs	N/A Provided	N/A
	Provision of Lifts,	Required	Provided	MR MR
	 Pressurization of lift shaft. Pressurization of lift lobby. 	N/A	N/A	N/A
	Communication in lift car.	N/A	N/A	N/A N/A
	• Fireman's switch.	N/A	N/A	N/A N/A
	 Lift signage. 	N/A		
		N/A	N/A	N/A

0/



N/A

N/A



N/A

N/A

N/A

N/A

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F.6/DFS/MS/EH/2019/SZ/25 dated 17/01/2020, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please

Signature of the Inspection of the Name: Sh. Manoj Kumar Sharma

Standby Power Supply

Total area

Location

Detector system panel.

Flow switch panel.

PA system panel.

Battery backup.

Building floor plan.

Special Fire Protection System for the

Protection of special Risk, if any.

Fire Control Room.

Refuge Area

17

18

19

20

MI

١

Design: DO (South)

CFO (HQ)

Signature of the Inspecting Officer
Name: Sh. Rajesh Kumar
Design: ADO (BCP)

Director My 123

Director My 123

And Old Amlun

And Old Amlun

As approved F.T. detter is prepared a pour up

for Kind perusal sign to a

Director Mind perusal sign