





GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No.F.6/DFS/MS/2023/NDZ/ / 58

Dated: 66 / 03 /2023

FIRE SAFETY CERTIFICATE

Certified that the Gautam Public School located at Kondli, Near Mayur Vihar-Ill, Delhi-110096, running on ground and first floor only of the building comprised of Ground & two upper floors only, owned / occupied by Gautam Public School, was issued FSC vide letter No. F6/DFS/MS/School/2019/NDZ/2048 Dated 24/10/2019. The School building was re-inspected by the officer concerned of this department on 28/02/2023 in presence of Mrs. Luxmi and observed that all the fire prevention and fire safety arrangements provided in the premises found in good working condition. The premises have therefore deemed complied with 262-362 Dated 17/01/2005 and that the building is fit for occupancy class "Educational" (Group-B) with effect from 06 / 03/2023 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS rule 2010.

Issued on 66/03/23 at New Delhi by.

DIRECTOR
DELHI FIRE SERVICE.

Copy to :-

- 1. The Principal, Gautam Public School, Kondli, Near Mayur Vihar-III, Delhi-110096.
- 2. The Dy. Director of Education, B-Block, Anand Vihar, Delhi-110053.

Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided their in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non-functional fire safety measure shall be at the responsibility of the management.
- 3. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 4. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 5. "The owner / Occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule37] along with a copy of this Certificate, six months prior to its expiry".
- 6. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.

E-29

11/18

| | INSPECTI | ON REPORT | r | 1,000 |
|-----|---|--|------------------------------------|-----------------|
| 1. | Name & address of the building: Gau | tom D. Liv | • | - |
| 2. | Building Kor | tam Public School | ol, | _ |
| ۷. | Dullding is come. | Idil. Near Morris | X 7 1 1 | -110096 - |
| 3. | Type of Occupancy (Sch | ound &Two upper | r floors only | |
| | TYDC OI Cace | - de la contraction de la cont | r floors only i G+1 floor Only) | _ |
| 5. | Details of provide the Rene | ewal | | _ |
| 6. | Fire Safety directives Lett | DFS/MS/School/ | 2019/NDZ/2048 E | |
| 7. | | | | Dated 24/10/19_ |
| | | 2/2023 | Jacod. 1 //01/2005/ | - |
| 9. | Name of the Inspecting Officer : A.K. Name and designation of Officer | Jaiswal, D.O. (F | E.D.) - | _ |
| | from the building side | | | _ |
| 10. | Year of Construction 12002 | Luxmi (Head Mi | istress) | - |
| 11 | .Applicant's letter No | | | - |
| 3 | Minimum standards on fire | 942/2023 Dated | d 23/01/2023 | |
| N | o prevention and fire safety U/R 33 | D.O.E. Circula | ar Provided at | Remarks |
| 1. | | Requirements | s Site | MR/NMR- |
| 1. | - 1100055 Of building | | | .r. |
| | Road width | 6 mtr | 3 mtr | MR (Old |
| | • Crate width | | 3 11.6 | accepted) |
| | Outc width | N/A | N/A | N/A |
| 2. | Width of internal road | N/A | N/A | N/A |
| ۷. | Number, width, Type & Arrangemen | ts of exits | | ; |
| | a. Number of staircases | | | |
| | • Upper floors | 01 | 02 | MR |
| | Basements Width of the second secon | N/A | N/A | N/A |
| | b. Width of staircases | | | |
| | • Upper floors | 1.5 m | 1.5 m, 1.34 m | MR |
| | Basements Protection of the second | N/A | N/A | N/A |
| | c. Protection of exits | | | |
| | Fire check door | N/A | N/A | N/A |
| | Pressurization | N/A | N/A | N/A |
| | d. No of continuous staircase to | 01 nos. | 02 nos. | MR |
| | terrace Width Of Comiden | | | , |
| | e. Width Of Corridor | 1.50 m | 1.50 m | MR / |
| | f. Door Size | 1.00 m | 1.00 m | MR / |
| 3. | Compartmentation | | | |
| | Fire check door | N/A | N/A | N/A |
| | Sealing of electrical shafts | N/A | N/A | |
| | Fire Rating of shaft door | N/A | N/A | N/A |
| | Water Curtain | N/A | N/A N/A | N/A |
| 1 | Fire Dampers | 14/71 | IN/A | N/A |
| 4. | Smoke managements System | | - | |
| | Basements | N/A | N/A | |
| ľ | Upper floors | N/A | | N/A |
| 5. | Fire Extinguishers | N/A | N/A | N/A |
| - | | 08 nos. | - | |
| L | | | 09 nos. | MR / |
| | • Types | ISI marked | Provided | MR |
| | | ABC/CO ₂ | | |
| | IS marking | Required | Provided | MR |
| | | | | 1411 |
| | | | i | |
| | 2 84 / | as a | | |



4/19

| 6. | First – Aid Hose Reels | 01 no. | 01 no. | MD |
|-----|--|-----------|---------------|-------|
| } | Total numbers on each floor | 30 m | | MR |
| | Length of hose reel hose | 05 mm | 30 m 05 mm | MR |
| 7 | Nozzle diameter Automatic fire detection and alarming | | U3 mm | MR |
| 7. | | N/A | N/A | N/A |
| | Type of detectorLocation of Main Panel | N/A | N/A | |
| | | | | N/A |
| | Location of Repeater Panel | N/A | N/A | N/A |
| | Alternate source of power | N/A | N/A | N/A |
| | Hooters' Location | N/A | N/A | N/A |
| 3. | MOEFA | N/A | N/A | N/A |
| 9. | Public Address System | N/A | N/A | N/A |
| 10. | Automatic Sprinkler System | | | 1 |
| | Basements | N/A | N/A | N/A |
| | Upper Floor | N/A | N/A | N/A |
| | Sprinkler above false ceiling | N/A | N/A | N/A |
| | | | 13/73 | IN/A |
| 11. | Internal Hydrants | | | |
| | Size of riser/down- comer | N/A | N/A | N/A |
| | Number of hydrants | N/A | N/A | N/A |
| | per floor | | 1.071 | 18/74 |
| | Hose Box | N/A | NI/A | 27/4 |
| 12. | Yard Hydrants | 14/74 | N/A | N/A |
| | | N/A | 15 | |
| | Total number of hydrantsHose Box | | N/A | N/A |
| 13. | Pumping Arrangements | N/A | N/A | N/A |
| | Ground Level | | | |
| | | 21/4 | | |
| | Discharge of main pumpHead of main pump | N/A | N/A | N/A |
| | Number of main pumps | N/A | N/A | N/A |
| | Jockey pump out put | N/A | N/A | N/A |
| | > Jockey pump head | N/A | N/A | N/A |
| | Standby Pump out put | N/A | N/A | N/A |
| | Standby Pump Head | N/A | N/A | N/A |
| | Auto Staring/Manual stopping | N/A | N/A | N/A |
| | Pump House Access | N/A | N/A | N/A |
| | Terrace level | N/A | N/A | N/A |
| | Discharge of pump | 220.1 | | |
| | | 220 lpm | 220 lpm | MR |
| | Head of the pump | 40 m | 40 m | MR |
| | Power supply | Required | Provided | MR |
| | > Auto starting of pump | Required | Provided | MR |
| 14. | The storage for the right | ing | 1 | |
| | Underground tank capacity | N/A | N/A | N/A |
| | Draw of connection | N/A | N/A | N/A |
| | > Fire service inlet | N/A | N/A | N/A |
| | Access to tank | N/A | N/A | N/A |
| | Overhead Tank capacity | 2500 ltrs | 5000 ltrs | MR |
| 15 | . Exit Signage. | N/A | N/A | |
| | | 13/11 | IN/A | N/A |
| | | | | |
| | | 100 | se se p | |

se b

| 16. | Provision of Lifts. | | | |
|-----|------------------------------|-----|-----|------------|
| | Pressurization of Lift Shaft | N/A | N/A | NI/A |
| | Pressurization of lift lobby | N/A | N/A | N/A |
| | Communication in lift Car | N/A | N/A | N/A |
| | Fireman's Grounding Switch | N/A | N/A | N/A N/A |
| | ▶ Lift Signage | N/A | N/A | N/A N/A |
| 17. | Standby power supply | N/A | N/A | N/A |
| 18. | Refuge Area | | | IVIA |
| | > Total area | N/A | N/A | N/A |
| | > Location | N/A | N/A | N/A |
| 9. | Fire control room | | | 13//1 |
| - | Detector system panel | N/A | N/A | N/A |
| - | Flow Switch Panel | N/A | N/A | N/A |
| L | PA System Panel | N/A | N/A | N/A |
| L | Battery backup | N/A | N/A | N/A |
| _ | Building Floor Plans | N/A | N/A | N/A |
| 0. | Special Firm P | N/A | N/A | N/A |

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, The Fire Safety Certificate issued vide letter no. F6/DFS/MS/School/2019/NDZ/2048 Dated 24/10/2019 grant under the circular No. 262-362 Dated 17/01/2005 renewal of FSC is recommended.

Signature of the Inspecting Officer Name: Ashok Kumar Jaiswal Designation: D.O. (East Division)

MR MR MR

de de

T. Letter is added for sign. fl.