2-19

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2023/SZ/ / 2 9

Dated: 27/102/2023

## **FIRE SAFETY CERTIFICATE**

Certified that the **Satyavati Public School**, Ishwar Colony (Nangli Dairy), New Delhi-110043 comprised of ground plus one upper floor having total 32 rooms (Including Class Rooms, Offices, Labs, Library, Staff Room & Store etc.) owned/occupied by Satyavati Public School was issued FSC by this department vide letter no. F.6/DFS/MS/School/2018/SZ/262 dated 15/02/2018. The school was re-inspected by the officer concerned of this department on 14/02/2023 in the presence of Sh. Harish Mohan (Teacher) and found that School building have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises is fit for occupancy class "Educational" for a period of three years, subject to compliance of the conditions printed as under.

Issued on 27/02/2023 at New Delhi.

(SUNIL CHAWDHARY) CHIEF FIRE OFFICER DELHI FIRE SERVICE

Copy to:1. The Manager,

Satyavati Public School, Ishwar Colony (Nangli Dairy), New Delhi-110043

 Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi–110054.

## Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape arrangements shall be kept unlocked & unobstructed for speedy evacuation of occupants in case of an emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

N/11

INSPECTION REPORT

Name & address of the building:

Building comprised of

Satyavati Public School, Ishwar Colony (Nangli Dairy), New Delhi-43. Ground plus one upper floor only.

2. Type of Occupancy

Educational

4. Type of Case

Renewal

5. Details of Previous NOC

F.6/DFS/MS/School/2018/SZ/262 dated 15/02/2018

6. Fire Safety directives letter No

Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011

7. Date of inspection8. Name of Inspecting Officer

: 14/02/2023

8. Name of hispecting Officer

: A.D.O. R.K. Yadav

9. Name and designation of officers From the building side

: Sh. Harish Mohan (Teacher)

10. Year of Construction

: Before 2006

11. Applicant's letter No.

: Nil dated 31/01/2023

s. No.	Minimu fire safe	m Standards on fire prevention and ty U/R 33	Requirements as per FSC dt. 15.02.2018	Provided at site	Remarks MR/NMR				
	Access	o building							
	•	Road width	06 m	Provided	MR				
	•	Gate width	4.5 m	Directly accessible	MR				
	•	Width of internal road	N/A	from road N/A	N/A				
2.	Number, Width, Type & Arrangement of Exits								
	a. Nun	ber of staircases							
	•	Upper Floors	02 No.'s.	02 No.'s	M/R				
	•	Basements	N/A	N/A	N/A				
	b. Wid	th of staircases	1.50 & .75 m	1.53 & 1.38 m	M/R				
	•	Upper Floor	N/A	N/A	N/A				
	•	Basements	IN/A	19/74	IN/A				
	c Pro	tection of exits	N/A	N/A	N/A				
	0. 110	Fire check door	N/A	N/A	N/A				
		Pressurization							
			N/A	Two	N/A				
	1	o. of continuous staircases to	N/A	2.75/1.50 m	N/A				
		rrace			1,37,5				
	1	lidth of Corridor Poor Size	1.0 m	.96 m	M/R, being old				
3.		partmentation			case				
3.		<u> </u>	21/4						
	•	1 110 0110011 0001	N/A	N/A	N/A				
4.			N/A	N/A	N/A				
			N/A	N/A	N/A				
			N/A	N/A	N/A				
			N/A	N/A	N/A				
	Smoke Management System								
	•	Basements	N/A	N/A	N/A				
	•	Upper floors	Required	Natural ventilatio	n M/R				
5.	Fire	Extinguishers							
		Total numbers	10 no's	10 no.'s	M/R				
		Types	ABC/CO <sub>2</sub> type		111				
		IS marking	ISI marked	Provided	M/R				
			151 Illai Keu	Provided	M/R				

s h

	First-Aid Hose Reels			
6.		N/A	Provided	
	Total numbers on each floor	N/A	Provided	M/R
	<ul> <li>Length of hose reel hose</li> </ul>	N/A	Provided	M/R
	Nozzle diameter		riovided	M/R
7.	Automatic fire detection and alarming system	N/A	NI/A	
	Type of detectors     Location of Main Panel	N/A	N/A	N/A
	, of Peneater Panel	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
	Hooters' Location	N/A	N/A	N/A
		N/A	N/A	N/A
8.	MOEFA	N/A N/A	N/A	N/A
9.	Public Address System Automatic Sprinkler System	IN/A	Provided	M/R
10.	Basement	N/A	21/4	
	Ground Floor	N/A	N/A	N/A
	Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants	IN/A	N/A	N/A
11.	Size of riser/down-comer	N/A	21/4	
	Number of hydrants per floor	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
12.	Yard Hydrants	IN/A	N/A	N/A
	Total number of hydrants	X1/A	1	
	Hose Box	N/A	N/A	N/A
3.	Pumping Arrangements	N/A	N/A	N/A
	amping a rangements			
	Ground Level			
	Discharge of main Pump	N/A	N/A	- N
	Head of Main pump	N/A		N/A
	Number of main pumps		N/A	N/A
	Jockey Pump out put	N/A	N/A	N/A
	> Jockey pump head	N/A	N/A	N/A
	<ul><li>Standby Pump out put</li><li>Standby Pump Head</li></ul>	N/A	N/A	N/A
	> Auto Starting/Manual Stopping	N/A	N/A	N/A
	Auto Starting Manual Stopping	N/A	N/A	N/A
		N/A	N/A	
	> Pump House Access	N/A	N/A	N/A N/A
	Terrace level		IV/A	N/A
	<ul><li>Discharge of pump</li></ul>	N/A	100 1 0) 4	
	Head of the pump	N/A	180 LPM	M/R
	Power Supply	N/A	18 m N/A	M/R
	➤ Auto Starting of pump	N/A		N/A
	0 1 1	IN/A	N/A	N/A
4. C	Captive Water Storage for fire fighting			
	Underground tank capacity	N/A	N/A	N/A
	<ul><li>Draw-off connection</li></ul>	N/A	N/A	1000
	Fire service inlet			N/A
	Access to tank	N/A	N/A	N/A
	<ul> <li>Overhead Tank capacity</li> </ul>	N/A	N/A	N/A
		N/A	2500 ltrs	M/R
5. E	xit Signage.	N/A	Provided	M/R
. P	rovision of Lifts.		No Life	
	Pressurization of Lift Shaft	N/A	N/A	N/A
	Pressurization of Lift Shart     Pressurization of Lift lobby			-
	Communication In lift Car	N/A	N/A	N/A
		N/A	N/A	N/A
	<ul><li>Fireman's Grounding Switch</li><li>Lift Signage</li></ul>	N/A	N/A	N/A
	- Ditt Dignage	N/A	N/A	N/A
- 10	tandby power supply	N/A	N/A	N/A
7. S1				

W

,

1) Th

3	> Total Area > Location	N/A	N/A	N/A
		N/A	N/A	N/A
	Fire Control Room			
	Detector System Panel	N/A	T >//	
	Flow Switch Panel		N/A	N/A
	PA System Panel	N/A	N/A	N/A
	Battery backup	N/A	N/A	N/A
	Building Floor Plans	N/A	N/A	N/A
		N/A	N/A	N/A
٠.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F.6/DFS/MS/School/2018/SZ/262 dated 15/02/2018 renewal in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Signature of Inspecting &

Designation:- Asstt. Divisional Officer

Name:- R.K. Yadav Divisional Officer (South West) Swil choud hory

D CFO (Sunil Glowdboa