GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110 001

No.F6/DFS/MS/FH/2023/SZ/ 113

Dated: 2702 2023

FIRE SAFETY CERTIFICATE

Issued on... 2+ 32, 2023 at New Delhi by.

(Sunil Choudhary)
Chief Fire Officer

T.No.011-23412225

Copy to:- M/S The Malik Farm House Khasra No.68,69,70,71,73&74/2, Village Kapashera, New Delhi-110037.

Conditions for the validity of fire safety certificate are under:-

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.
- This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate on form J, six month prior to its expiry.

6 -1

W/21

		INSPECTION REPORT					
1	Name & address of the building	M/s The Malik Farm House (Amanta) Khasra					
Ţ .		No.68,69,70,71,73&74/2, Villa	0.68,69,70,71,73&74/2, Village Kapashera, New Delbi 110027				
2	Trype or Occupancy	Assembly building "D" Farm House					
3	Building Comprised of	Lower ground and upper fround floors. Both floors are directly					
		accessible from ground level.					
4	Type of case	Renewal					
5	Details of previous NOC	No.F6/DFS/MS/FH/2018/SZ/2	315, dated 12.10.2018				
6	Fire safety directives letter No	No.F6/DFS/MS/2012/FH/250	dated 11.07.2012				
7	Date of inspection	23.02.2023.					
8	Name of the inspecting Officers	ADO Vedpal		7			
9	Name and designation of officers	Mr. Anil Chopra (General Manager)					
	from the building side						
10		2010					
11	Applicant's letter No.	ID No.2022120521073					
S.	Minimum Standards on fire	Old NOC Requirement	Descripted of the later				
NO.	prevention and fire safety U/R	ola NOC Requirement		Remarks			
NO.	33			MR/NMR			
1	Access to building						
<u> </u>	1) Road width	Required	18 Mtr	MR			
	2) Gate width	5 Mtr					
	3) Width of internal road	N/A		MR			
2	Number, width Type & arranger		IN/A	N/A			
		HOUR OF EVIES					
	a. Number of staircases						
	1. Upper floors	01no.	01no.	MR			
	2. basements	N.A.		N.A.			
	b. Width of staircase		14.74.	IN.A.			
	1. Upper floors	1.25m	1.25m	MR			
	2. basements	N.A.		N.A.			
	c. Protection of exits	14.7 (.	IN.A.	N.A.			
	1. Fire check door	N/A	N/A	NI/A			
	2. Pressurization	N/A	N/A	N/A			
	d. No. of continuous staircase		N.A.	N/A			
	to terrace	IN.A.	IN.A.	N.A.			
	e. Width of corridor	N/A	NI/A				
	f. Door size	N/A	N/A	N/A			
3	Compartmentation.	IN/A	N/A	N/A			
	Fire check door	N/A	NI/A				
	2. Sealing of electrical shafts	N/A	N/A	N/A			
	3. Fire Rating of shaft door	N/A	N/A	N/A			
	4. water curtain	N/A	N/A	N/A			
	5. Fire dampers	N/A	N/A	N/A			
4	Smoke Management system.	14/7	N/A	N/A			
	basement	30 a/c per hour 12	N/A	N/A			
		a/c per hour					
	upper floors		Exhaust fan provided	d MR			
5	Fire Extinguishers			TIVIL			
	total numbers						
	Types	10Nos. ABC,CO2 ISI	12 Nos. Provided	MR			
	ISI marking	4	ABC and CO2	MR			
6	First-Aid Hose Reels.		ISI Mark	MR			
-							
	Total numbers on all around	01no.	01no.	MR			
	Length of Hose reel hose	30 Mtr	30mtr.	MR			
	Nozzle Diameter	5mm	5mm	MR			
				' ' '			
			-				

(gh)

Nzz

			N/A	A 1 1 1
	location of Main Panel location of Repeater panel	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
	hooter's location	N/A	N/A	N/A
8	MOEFA	N/A	N/A	N/A
9	Public Address System.	Required	Provided	N/A MR
10	Automatic Sprinkler System.	N.A.	N.A.	N.A.
	basement	NI/A		14.7.
	upper floors	N/A N/A	N/A	N/A
	sprinkler above false ceiling	N/A	N/A	N/A
11	Internal Hydrants	IN/A	N/A	N/A
	Size of riser/down-corner	100mm		11477
	Number of Hydrants per floor	01no.	100mm	MR
	Tuose Box	01no.	01no.	MR
12	Yard Hydrants.	U Ino.	01no.	MR
	total number of hydrants	Poguinad		T.VII. C
	house box	Required Required	04nos.	MR
13	Pumping arrangements	rveduiled	04nos.	MR
	1. Ground level			1,
	a. Discharge of main Pump	450lpm		
	D. Head of main pump	450ipm 40m	450lpm	MR
	c.Number of main pumps	01no.	40m	MR
	a.Jockey pump out put	N/A	01no.	MR
	e.jockey pump head	N/A	N/A	N/A
	f. Standby Pump output	N/A	N/A	N/A
	g.Stanby Pump head	N/A	N/A	N/A
	h.Auto Starting/Manual stopping	Required	N/A	N/A
	Pullip house access	Required	Provided	MR
	2.Terrace level	N/A	Provided	MR
	a. Discharge of pump	N/A	N/A	N/A
	b. head of the pump	N/A	N/A	N/A
	c. Power supply	N/A	N/A	N/A
	d. Auto starting of pump	N/A	N/A	N/A
4	Captive water storage for fire		N/A	N/A
4	fighting			
	Underground tank capacity	10000Liters	20000Liters	
	a. Draw-off connection	N/A	N/A	MR
	b. fire service inlet	N/A	N/A	N/A
	c.Access to tank	Required	Provided	N/A
_	Over head tank Capacity	N/A	N/A	MR
5	Exit Signage.	Required		N/A
6	Provision of lifts.	100	Provided	MR
	a. Pressurization of lift shaft	N/A	No Lift Provided	
	b. pressurization of lift lobby	N/A	N/A	N/A
	c. communication in lift car	N/A	N/A	N/A
	d. Fireman's grounding switch	N/A	N/A	N/A
	e. Lift signage	N/A	N/A	N/A
7		IN/A	N/A	N/A
<u>'</u>	Standby power supply	Required	Provided	
8	Refuge Area.		1 TOVIDED	MR
		Not Required		
	total area	N.A.		
	location	N.A.	N.A	N.A
		``·O·	N.A	N.A
9	Fire control room			

N/23

		19/2		
	tom Panel	N/A	N/A	N/A
a, d	a. detector system Panel b. Flow switch Panel c. PA system Panel d. Batter backup	N/A	N/A	N/A
		N/A	N/A	N/A
ö I n		Required	Provided	MR
l la B		NI/Δ	N/A	N/A
e. B	uilding floor plans	s for protection of special risks, if any:		
Cno	cial Fire Protection system	o lor protection		

The fire protection systems provided in the building were checked at random and found functional at the time of inspection.

time of the deemed compliance of the minimum standards on fire prevention and fire safety required under the rules the FSC issued vide letter No.F.6/DFS/MS/FH/2018/SZ/2315, dated 12.10.2018 renewal under Rule 37 of the Delhi Fire Service Rule 2010 is recommended. under Rule DFA is put up for your approval and signature please.

Signature of the Inspecting Officer

Name | Vedpal

Designation : D.O. SW

Suril Chondhay co

C. 2. S. W

FF letter by put up ?

Go Smilchdry

M. S. W/

Malik Farm House Kapashera

Renewal