

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI-110 001.

No. F.6/DFS/MS/EH/2023/SZ/100

Dated: 13/03/2023

FIRE SAFETY CERTIFICATE

Certified that the **M/s Café Another Day (Rudy Klub Hospitality Pvt. Ltd.)**, Plot No.G-12 , DDA-1, Distt. Centre, Janak Puri, New Delhi-110058, comprised of two portions one is basement, ground floor, upper ground floor plus five upper floors and other in which restaurant is located is comprised of basement ground floor and upper ground floor but the restaurant is running at ground floor only, owned/occupied by M/s Café Another Day (Rudy Klub Hospitality Pvt. Ltd.). The building was inspected by the officers concerned of this department on 01/03/2023 in the presence of Sh. Rajesh Thakur (Manager) and found that the restaurant have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises (**Ground floor only**) is fit for occupancy class Group D "Assembly Building" w.e.f. the date of issue of this certificate for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule-38 of the Delhi Fire Service Rules, 2010 printed below.

Issued on.....13/03/2023.....at New Delhi.

(ATUL GARG)
DIRECTOR
DELHI FIRE SERVICE

Copy to:-

1. The Deputy Health Officer, West Zone (SDMC), Public Health Department, Vishal Enclave, New Delhi.
2. The Partner, M/s Café Another Day (Rudy Klub Hospitality Pvt. Ltd.), Plot No.G-12 , DDA-1, Distt. Centre, Janak Puri, New Delhi-110058.

Following fire safety directives must be adhered to:-

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
4. The trained staff should be available round the clock.
5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
7. Basement shall be used as per the building bye laws.
8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

N/8

INSPECTION REPORT

1. Name & address of the building: M/s Café Another Day (Rudy Klub Hospitality Pvt. Ltd.),
Plot No.G-12, DDA-1, Distt. Centre, Janak Puri, New Delhi-110058
2. Building comprised of : Basement, ground & upper ground floor but restaurant is running at ground floor only
3. Type of Occupancy : Group D (Assembly Building)
4. Type of Case : Renewal
5. Details of Previous NOC : F6/DFS/MS/EH/2020/SZ/52 Dated 26/02/2020
6. Fire Safety directives letter No : N/A
7. Date of inspection : 01/03/2023
8. Name of Inspecting Officers : D.O. Vedpal Chhikara & A.D.O. R.K. Yadav
9. Name and designation of officers
From the building side : Sh. Rajesh Thakur (Manager)
10. Year of Construction : 2019-2020
11. Applicant's letter No. : ID No. 2023021502066 dated 15/02/2023

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	NBC Requirement	Provided at site	Remarks MR/NMR
1.	Access to building			
	<ul style="list-style-type: none"> • Road width • Gate width • Width of internal road 	06 mtrs 4.5 mtrs N/A	Provided Directly accessible from road N/A	MR MR N/A
2.	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases			
	• Upper Floors	N/A	N/A	N/A
	• Basements	N/A	N/A	N/A
	b. Width of staircases			
	• Upper Floor	N/A	N/A	N/A
	• Basements	N/A	N/A	N/A
	c. Protection of exits			
	• Fire check door	N/A	N/A	N/A
	• Pressurization	N/A	N/A	N/A
	d. No. of continuous staircases to terrace	N/A	N/A	N/A
	e. Width of Corridor	N/A	N/A	N/A
	f. Door Size	2.0 & 1.50 m	2.0 m each	MR
3.	Compartmentation			
	• Fire check door	N/A	N/A	N/A
	• Sealing of electrical shafts	N/A	N/A	N/A
	• Fire Rating of shaft door	N/A	N/A	N/A
	• Water Curtain	N/A	N/A	N/A
	• Fire Dampers	N/A	N/A	N/A
4.	Smoke Management System			
	• Basements	N/A	N/A	N/A
	• Ground floor	Required	Provided	MR
5.	Fire Extinguishers			
	• Total numbers on each floor	04 No.'s	Provided	MR
	• Types	ABC/CO ₂	Provided	MR
	• IS marking	ISI marked	ISI marked	MR

RS

tr

e

N/10

Provision of Lifts.

	<ul style="list-style-type: none"> • Pressurization of Lift Shaft • Pressurization of Lift lobby • Communication In lift Car • Fireman's Grounding Switch • Lift Signage 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
17.	Standby power supply	Required	Provided	MR
18.	Refuge Area.			
	<ul style="list-style-type: none"> ➤ Total Area ➤ Location 	N/A	N/A	N/A
		N/A	N/A	N/A
19.	Fire Control Room			
	<ul style="list-style-type: none"> • Detector System Panel • Flow Switch Panel • PA System Panel • Battery backup • Building Floor Plans 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection. The shortcoming issued vide letter No. F6/DFS/MS/2023/SZ/09 dated 09/01/2023 has been complied.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules the FSC was issued vide letter no. F6/DFS/MS/EH/2020/SZ/52 Dated 26/02/2020 renewal under Rule 37 of the Delhi Fire Service Rules 2010.

Note:- The restaurant is part of DDA-1 District Centre, Janakpuri, comprised of two portions one is basement, ground floor, upper ground floor plus five upper floors and other in which restaurant is located is comprised of basement ground floor and upper ground floor. The restaurant is not connected with basement and has separate entry/exit. The restaurant is having separate fire fighting system from the building.

Rkeil

Signature of Inspecting Officer
Name:- R.K. Yadav
Designation:- Asstt.Divisional Officer

[Signature]

3/8/23

Signature of Inspecting Officer
Name:- Vedpal Chhikara
Designation:- Divisional Officer

CFO (S2)

[Signature]
3/8/2023

Director
[Signature]
6/08/23

[Signature]

*This building
get NOC from
DFS or others
[Signature]*