(125



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2023/ 6/

Dated: 1.6.1. 23./2023

FIRE SAFETY CERTIFICATE

Certified that the Ricky Dx. Guest House located at 1242, Bazar Sangatrashan, Pahar Ganj, New Delhi is comprised of Ground + 04 Upper floors, Ground floor (Reception + 03 guest rooms), 1st floor to 3rd floor (05 guest rooms at each floor), total 18 guest rooms up to third floor only and 4th floor (01 guest room) not in use as per affidavit dated 30.09.2019, The FSC was earlier granted by this department vide letter No.F6/DFS/MS/GH/NDZ/2019/1921 dated 07/10/19 for 19 guest rooms up to fourth floor, Now, the premises was re-inspected by the officer concerned of this department on 06/03/23 in the presence of Mr. Ravi Kapoor and found that the said guest house building has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, (Sub Division-A-1) Ground floor (Reception + 03 guest rooms), 1st floor to 3rd floor (05 guest rooms at each floor) total 18 guest rooms up to third floor only, with effect from 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued ... 6. 6.9. 1.2023... at New Delhi by.

DIRECTOR Delhi Fire Service

Copy to:-

- 1. The Commissioner, MCD, Civic Centre, New Delhi. to kindly ensure the occupancy as
- 2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi 2022101519101 dated 15.10.2022 & mail id kapoorravikant96@gmail.com dated 17.02.2023
- 3. The Manager, Ricky Dx. Guest House at 1242, Bazar Sangatrashan, Pahar Ganj, New Delhi.

- Conditions for the validity of Fire Safety Certificate All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
 - 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the

3. The trained fire fighting staff should be available round the clock.

- 4. The compliance with regards to electrical installation, structural stability, set back area, occupancy and any deviation in construction etc. shall be verified from authority concerned.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any. 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi

Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (1)

of rule 37] along with a copy of this Certificate, six month prior to its expiry.

9. Any flammable material for interior decoration is prohibited.

INSPECTION REPORT

Ilding Ricky Dx. Guest House located at 1242,

Name & address of the building

Bazar Sangatrashan, Pahar Ganj, New Delhi 2. Type of occupancy:-Residential, Sub Division-A-1 Gr. + 04 Upper floors (total 18 Guest rooms) Ground floor (Reception + 03 guest rooms), 1st floor to 3rd floor (05 guest rooms at each floor) and 4th floor not in use as per affidavit dated 30.09.2019. 3. Type of case:-Renewal 4. Details of previous FSC:-No. F6/DFS/MS/GH/NDZ/2019/1921 dated 5. Fire safety directives No .-N/A 6. Date of inspection:-06/03/23 7. Name of the inspecting officer:-Sh. Ravinder Singh (ADO/CC) 8. Name & designation of officer From the building side:-Mr.Ravi Kapoor 9. Year of construction:-10. Applicant's letter No:id no. 2022101519101 dated 15.10.2022 & mail id kapoorravikant96@gmail.com dated 17.02.2023 Old Case Minimum Standards on fire Requirement Provided at site Remarks S.No. Prevention and fire safety Existing PSS MR/NMR U/R 33 Access to Building 1. N/A N/A 06 mtr. Approx. 1) Road width N/A 2) Gate width N/A N/A N/A N/A 3)Width of internal road N/A Number, Width Type & Arrangement of Exits 2. A. Number of staircases MR 01 Nos. 01 Nos. Upper floors N/A N/A N/A 2. Basements B. Width of staircase 0.90 Mtr. MR 0.80 mtr. Upper floors N/A N/A N/A 2. Basements C. Protection of exits N/A N/A N/A 1. Fire check door N/A N/A N/A 2. Pressurization MR 01 01 D. No. of continuous staircase to terrace N/A N/A N/A E. Width of corridor MR 01 mtr. 01 mtr. F. Door size Compartmentation 3. N/A N/A N/A 1) Fire check door N/A N/A N/A 2) Sealing of electrical shafts N/A N/A N/A 3) Fire rating of shaft door N/A N/A N/A 4) Water curtain N/A N/A N/A 5) Fire Dampers Smoke Management System 4. N/A N/A 30 ACPH 1) Basements MR Exhaust fan 12 ACPH Upper floors Fire Extinguishers 5. MR 10 Nos. 10 Nos. 1) Total numbers

الم الم

0

N/34

				(3		
	2) Types	ABC & CO2	ABC & CO2	MR		
	3) ISI marking	Required	Provided	MR		
6.	First-Aid Hose Reel			1111		
	1) Total number of eachfloo	or 01	01	MR		
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR		
	3) Nozzle diameter	05 mm	05 mm	MR		
7.	Automatic Fire Detection & Alarming System					
	1) Type of detectors co type	Required	Provided	MR		
	2) Location of main panel	Gr. floor	Provided	MR		
	Location of repeater pane		N/A	N/A		
	4) Alternate source of power	Required	Provided	MR		
	5) Hooter's Location	Gr. floor	Provided	MR		
8.	MOEFA	N/A	N/A	N/A		
9.	Public Address System	Required	functional	MR		
10.	Automatic Sprinkler System		ranctional	IVIX		
	1) Basement	N/A	N/A	N/A		
	2) Upper floors	N/A	N/A	N/A		
	3) Sprinkler above false	N/A	N/A	N/A		
	ceiling	3(0).7.20	1771	IN/A		
11.	Internal Hydrants					
	1) Size of riser/down-comer	N/A	N/A	N/A		
	2) Number of hydrants per	N/A	N/A	N/A		
	floor			W/A		
	3) Hose box	N/A	N/A	N/A		
12.	Yard Hydrants			T. C.		
	1) Total number of hydrants	N/A	N/A	N/A		
	2) Hose box	N/A	N/A	N/A		
13.	Pumping Arrangement		The second secon			
	Ground level	N/A	N/A	N/A		
	a) Discharge of main	N/A	N/A	N/A		
	pump					
	 b) Head of main pump 	N/A	N/A	N/A		
	c) Number of main	N/A	N/A	N/A		
	pump					
	d) Jockey pump out put	N/A	N/A	N/A		
	e) Jockey pump head	N/A	N/A	N/A		
	f) Stand by pump output	N/A	N/A	N/A		
	g) Stand by pump head	N/A	N/A	N/A		
	h) Auto starting/Manual	N/A	N/A	N/A		
	stopping					
	2) Terrace level	450 1 101	(
	a) Discharge of pump	and the second s	450 LPM	MR		
	b) Head of pump	Control of the Contro	30 mtr.	MR		
	c) Power supply	the regulation of the control of the	Provided	MR		
	d) Auto starting of pump		Provided	MR		
4.	Captive Water Storage for Fir 1) Under ground tank	The state of the s	N/A			
	The Linder ground tonk	I INI/A	N/A	N/A		



	b) Pressurization of lift	N/A	N/A	N/A
	lobby c) Communication in lift	N/A	N/A N/A	N/A N/A
	car	TV/A	IVA	IVA
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System f	or Protection	of special Disk	NA

The fire protection systems provided in the guest house building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, if approved, we may renew the FSC issued vide letter no F6/DFS/MS/GH/NDZ/2019/1921 dated 07/10/19, up to third floor only under rule 35 of the Delhi Fire Service rules 2010. Accordingly, DFA is put up for kind perusal and signature please.

Signature of the Inspecting Officer

Name: - Ravinder Singh Designation: - ADO (CC)