

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2023/SZ/ 192

Dated: 17/03/2023

## FIRE SAFETY CERTIFICATE

Certified that the S.D.M.C Primary Boys School, Dichaon Kalan, New Delhi-110043 comprised of ground plus one upper floor, having total 12 rooms (Including Class Rooms & Office etc.) owned/occupied by S.D.M.C was issued Fire Safety Certificate by this department vide letter No F.6/DFS/MS/School/2018/SZ/1940 dated 23/08/2018. The school building was re- inspected by the officer concerned of this department on 06/03/2023 in the presence of Sh. Yashpal Singh (Principal) and found that the School building have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed as under.

Issued on 17/03/2023 at New Delhi.

DIRECTOR DELHI FIRE SERVICE

29.

## Copy to:-

- The Principal, S.D.M.C Primary Boys School, Dichaon Kalan, New Delhi-110043
- Director of Education,
   S.D.M.C, Civic Centre,
   Minto Road, New Delhi-110001.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

## INSPECTION REPORT

S.D.M.C Primary Boys School, Dichaon Kalan, New Delhi-110043 1. Name & address of the building 2. Building comprised of Ground plus one upper floor 3. Type of Occupancy Educational 4. Type of Case Renewal 5. Details of Previous NOC F.6/DFS/MS/School/2018/SZ/1940 dated 23/08/2018 Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 6. Fire Safety directives letter No 7. Date of inspection 06/03/2023 8. Name of Inspecting Officer A.D.O. R.K. Yadav 9. Name and designation of officers Sh. Yashpal Singh (Principal) From the building side 10. Year of Construction 2013 11. Applicant's letter No. Nil dated 18/02/2023 Remarks Provided at Requirement Minimum Standards on fire prevention and MR/NMR as per FSC dt. fire safety U/R 33 23.08.2018 1. Access to building MR 12 m 06 m Road width MR, being old case 3.9 m 4.5 m Gate width N/A N/A N/A Width of internal road 2. Number, Width, Type & Arrangement of Exits a. Number of staircases MR 02 no.'s Upper Floors 02 no.'s **Basements** N/A N/A N/A b. Width of staircases Upper Floor 1.30 to 1.25 m (02 MR 1.50 & .75 m Basements no.'s) N/A N/A N/A c. Protection of exits N/A N/A N/A Fire check door N/A N/A N/A Pressurization d. No. of continuous staircases to N/A N/A N/A terrace N/A N/A N/A Width of Corridor MR 1.0 m 1.18 m (double door) Door Size 3. Compartmentation N/A N/A N/A Fire check door Sealing of electrical shafts N/A N/A N/A Fire Rating of shaft door N/A N/A N/A Water Curtain N/A N/A N/A Fire Dampers N/A N/A N/A 4. Smoke Management System N/A N/A N/A Basements Required Natural Ventilation Upper floors MR provided Fire Extinguishers 5. Total numbers 04 No's Provided MR Types ABC/CO2 type Provided MR ISI marked IS marking ISI marked MR First-Aid Hose Reels Total numbers on each floor N/A N/A N/A Length of hose reel hose N/A N/A N/A Nozzle diameter N/A N/A N/A 0,

6.

60

	Automatic fire detection and alarming system		NT/A	N/A
	Type of detectors	N/A	N/A	-
	<ul> <li>Location of Main Panel</li> </ul>	N/A	N/A	N/A
	Location of Repeater Panel	N/A	N/A	N/A
	<ul> <li>Alternate source of power</li> </ul>	N/A	N/A	N/A
	<ul> <li>Hooters' Location</li> </ul>	N/A	N/A	N/A
•	MOEFA	N/A	N/A	N/A
١.	Public Address System	N/A	N/A	N/A
0.	Automatic Sprinkler System			
υ.	Basement	N/A	N/A	N/A
	Ground Floor	N/A	N/A	N/A
	Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants			
	Size of riser/down-comer	N/A	N/A	N/A
	<ul> <li>Number of hydrants per floor</li> </ul>	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
12.	Yard Hydrants	T 57/2	NI/A	N/A
	<ul> <li>Total number of hydrants</li> </ul>	N/A	N/A	N/A
	Hose Box	N/A	N/A	IN/A
13.	Pumping Arrangements			
	Ground Level     Discharge of main Pump	N/A	N/A	N/A
	<ul><li>Discharge of main Pump</li><li>Head of Main pump</li></ul>	0000000	N/A	N/A
	> Number of main pumps	N/A		2497976-15X
	> Jockey Pump out put	N/A	N/A	N/A
	Jockey pump head	N/A	N/A	N/A
	Standby Pump out put	N/A	N/A	N/A
	> Standby Pump Head	N/A	N/A	N/A
	Auto Starting/Manual Stopping	N/A	N/A	N/A
		N/A	N/A	N/A
	2 2 2	N/A	N/A	N/A
	> Pump House Access			
	<ul> <li>Terrace level</li> <li>Discharge of pump</li> </ul>	N/A	N/A	N/A
	> Head of the pump	N/A	N/A	N/A
	> Power Supply	N/A	N/A	N/A
	> Auto Starting of pump	N/A	N/A	N/A
14.	Captive Water Storage for fire fighting			
	Underground tank capacity	N/A	N/A	N/A
	Draw-off connection	N/A	N/A	N/A
	> Fire service inlet	N/A	N/A	N/A
	Access to tank	N/A	N/A	N/A
	Overhead Tank capacity	N/A	N/A	N/A
15.	Exit Signage.	N/A	N/A	N/A
16.	Provision of Lifts.			(No Lift)
	Pressurization of Lift Shaft	N/A	N/A	N/A
	Pressurization of Lift lobby	N/A	N/A	N/A
	Communication In lift Car	N/A	N/A	N/A
	<ul> <li>Fireman's Grounding Switch</li> </ul>	N/A	N/A	N/A
	<ul> <li>Lift Signage</li> </ul>	N/A	N/A	N/A
	a. II aman aunniy	N/A	N/A	N/A
17.	Standby power supply	- 1000		
18.	Refuge Area.			
		N/A	N/A	N/A
	> Total Area	IN/A	1.07.1	- 7.55

of special Risks, if any:

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F.6/DFS/MS/School/2018/SZ/1940 dated 23/08/2018 renewal in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Signature of Inspect

Name: - R.K. Yadav

Designation:- Asstt. Divisional Officer

Divisional Officer (South West) Dineeta