

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI-110001**

No. F.6/DFS/MS/EH/2023/SZ/106

Dated 20/03/2023

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the name & style of **M/s Chilis Grill and Bar** located at Unit No **R-308, 3rd Floor**, Ambience Mall, Plot No. 2, Nelson Mandela Marg, Vasant Kunj, New Delhi-110070 in the building comprised of 03 tier Basement, Ground plus Three upper floors owned/occupied by A Unit of Paramount Restaurant Pvt Ltd was issued Fire Safety Certificate by this department vide letter no. F6/DFS/MS/EH/SZ/2020/85 dated 20/04/2020. The restaurant premise was re-inspected by the officer concerned of this department on 03/03/2023 in the presence of Mr. Devashish and found that the said premise have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy **Class D "Assembly Building" (Restaurant at Third Floor only)** with effect from 20/03/2023 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 20/03/2023 at New Delhi by

**ATUL GARG
DIRECTOR
DELHI FIRE SERVICE**

Copy to: -

1. The Dy. Health Officer, Public Health Department, South Zone, Green Park, Delhi-110016 (Ref. MHA Portal ID 2023022702749 dated 27/02/2023)

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
3. All the staff members must know the correct method of operation of fire fighting system.
4. The basement shall be used as per the provisions of BBL /NBC Part- IV.
5. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."

INSPECTION REPORT

1	Name & Address of the Building	M/s Chilis Grill and Bar (unit of Paramount Restaurant Pvt Ltd) at Unit No R-308, 3 rd Floor, Ambience Mall, Plot No. 2, Nelson Mandela Marg, Vasant Kunj, New Delhi-110070		
2	Type of Occupancy	Assembly Building -D (Restaurant)		
3	Building Comprised of	Three tier Basement, Ground + 03 upper floors (Restaurant running at 3 rd Floor)		
4	Type of Case	Renewal / Name Change		
5	Details of Previous NOC	F6/DFS/MS/EH/SZ/2020/85 dated 20/04/2020		
6	Fire Safety Directives Letter No	Nil		
7	Date of Inspection	03/03/2023		
8	Name of the Inspecting Officers	DO (South) & ADO (BCP)		
9	Name & Designation of Officers from the building side	Mr. Devashish		
10	Year of construction	2008		
11	Applicant letter No.	MHA Portal ID 2023022702749 dated 27/02/2023		
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	Requirement/ Existing Fire Protection	Provided at Site	Remarks MR/NMR
1	Access to Building. FSC No.F.6/DFS/MS/Mall/2023/SZ/35 Dated 25/01/2023 of Ambience Mall			
	• Road width	9m	Provided *	MR
	• Gate width	5m	Provided *	MR
	• Width of internal road	6m	Provided *	MR
2	Number, width, type and arrangements of exits.			
	a. Number of Staircase	Provided & Maintained by Ambience Mall		
	• Upper floors	02 Nos	17 Provided *	MR (old case)
	• Basement floor	02 Nos	Provided *	MR
	b. Width of Staircase	Provided & Maintained by Ambience Mall		
	• Upper floors	1.50 mtr	Provided *	MR
	• Basement floor	Required	Provided *	MR
	c. Protection of exits	Provided & Maintained by Ambience Mall		
	• Fire check door	Required	Provided *	MR
	• Pressurization	Required	Provided *	MR
	d. No. of continuous staircase to terrace	Required	Provided *	MR
	e. Width of corridor	N/A	N/A	N/A
	f. Door size	Required	1.50 mtr & 1.17 mtr	MR (old case)
3	Compartmentation.	Provided & Maintained by Ambience Mall		
	• Fire check door.	Required	Provided *	MR
	• Sealing of electrical shafts.	Required	Provided *	MR
	• Fire rating of shaft door.	N/A	N/A	N/A
	• Water curtain	N/A	N/A	N/A
	• Fire dampers.	N/A	N/A	N/A
4.	Smoke Management system.	Provided & Maintained by Ambience Mall		
	• Basement	Required	Provided *	MR
	• Upper floors	Required	Exhaust fans provided	MR
5.	Fire Extinguishers.			
	• Total numbers	06 Nos	06 Nos.	MR
	• Types		ABC-04, W.CO ₂ -02	MR
	• ISI Marking	ISI marked	Provided	MR
6.	First Aid Hose Reels.	Provided & Maintained by Ambience Mall		
	• Total numbers on each floor.		05 Each floor	MR
	• Length of hose-reel hose.	Hose Reel	30m	MR

(Handwritten signature)

N/14

	• Nozzle Diameter		5mm	MR
7	Automatic Fire Detection and Alarming system. (Provided & Maintained by Ambience Mall)			
	• Type of detectors	Required	Smoke & Heat	MR
	• Location of Main Panel	Required	Provided *	MR
	• Location of Repeater Panel	N/A	N/A	N/A
	• Alternate source of power	Required	Provided *	MR
	• Hooter's location	Required	Provided *	MR
8.	MOEFA	Required	Provided *	MR
9.	Public Address System	Required	Provided *	MR
10.	Automatic Sprinkler System			
	Provided & Maintained by Ambience Mall			
	• Basement	Required	Provided *	MR
	• Upper floors	Required	Provided *	MR
	• Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants.			
	Provided & Maintained by Ambience Mall			
	• Size of Riser/Down-comer	Required	Provided *	MR
	• Number of Hydrant per floor	Required	Provided *	MR
	• Hose box.	Required	Provided *	MR
12.	Yard Hydrants.			
	Provided & Maintained by Ambience Mall			
	• Total number of hydrants.	N/A	N/A	N/A
	• 2. Hose box.	N/A	N/A	N/A
13.	Pumping arrangements.			
	Provided & Maintained by Ambience Mall			
	• Ground Level			
	➤ Discharge of main pump.	4500 LPM	Provided *	MR
	➤ Head of main pump.	70 mtr	Provided *	MR
	➤ Number of main pumps.	Two	Provided *	MR
	➤ Jockey Pump output.	450 LPM	Provided *	MR
	➤ Jockey Pump head.	70 mtr	Provided *	MR
	➤ Standby Pump output.	4500 LPM	Provided *	MR
	➤ Standby Pump head.	70 mtr	Provided *	MR
	➤ Auto Starting / Manual Stopping.	Required	Provided *	MR
	➤ Access to pump house	Required	Provided *	MR
	• Terrace Level			
	➤ Discharge of pump.	N/A	N/A	N/A
	➤ Head of pump.	N/A	N/A	N/A
	➤ Power supply.	N/A	N/A	N/A
	➤ Auto starting of pump.	N/A	N/A	N/A
14.	Captive water storage for Fire Fighting.			
	Provided & Maintained by Ambience Mall			
	• Underground tank capacity.	5,00,000 Ltrs	Provided *	MR
	➤ Draw-off connection.	Required	Provided *	MR
	➤ Fire Service Inlet.	Required	Provided *	MR
	➤ Access to tank.	Required	Provided *	MR
	• Overhead tank capacity.	20,000 Ltrs	Provided *	MR
15.	Exit Signage.	Required	Provided *	MR
16.	Provision of Lifts.			
	Provided & Maintained by Ambience Mall			
	• Pressurization of lift shaft.	N/A	N/A	N/A
	• Pressurization of lift lobby.	N/A	N/A	N/A
	• Communication in lift car.	N/A	N/A	N/A
	• Fireman's switch.	N/A	N/A	N/A
	• Lift signage.	N/A	N/A	N/A
17	Standby Power Supply	Required	Provided (DG Set)	MR
18.	Refuge Area			
	• Total area	N/A	N/A	N/A
	• Location	N/A	N/A	N/A

19.	Fire Control Room. <ul style="list-style-type: none"> • Detector System Panel. • Flow Switch Panel. • PA system Panel. • Battery backup • Building floor plan 	Provided & Maintained by Ambience Mall		
		N/A	As above	N/A
		N/A	As above	N/A
		N/A	As above	N/A
		N/A	As above	N/A
		N/A	As above	N/A
20.	Special Fire Protection System for the Protection of special Risk, if any :	N/A	As above	N/A

Note-* Fire safety arrangement provided and maintained by Ambience Mall, Plot No. 2, Nelson Mandela Marg, Vasant Kunj, New Delhi-110070

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/EH/SZ/2020/85 dated 20/04/2020, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Manoj
 Signature of the Inspection Officer
 Name: Sh. Manoj Kumar Sharma
 Design: DO (South)

Rajesh
 Signature of the Inspecting Officer
 Name: Sh. Rajesh Kumar
 Design: ADO (BCP)

CFO (HQ)

14/3/2023
 Director

*my Pls Bkr
 outw do of my of
 & poben*

15/03/23

fips

*As approved, f.i. letter is
 for your signature pl.*

Any B/O
 Director

16/3/2023

Uploaded
 22/3/23