

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001

No.F6/DFS/MS/2023/ School/ 205

Dated: 23 q.7/2023

FIRE SAFETY CERTIFICATE

Certified that the Atal Adarsh Prathmik Vidyalaya located at R.K. Ashram Marg, New Delhi comprises of Ground + 01 Upper floor only was earlier granted FSC by this department vide letter No. F6/DFS/MS/2020/School/38 dated 31/01/2020. Now, the premises was re-inspected by the officer concerned of this department on 09-03-2023 in the presence of Sh. N.K. Gaur (Fire Officer) and found that school have deemed complied with the fire prevention and fire safety requirements in accordance with Circular No. F.16/Estate/CC/Fire Safety/2011/3298-3398 dated 01/03/2011 issued by Director of Education and the building premises is fit for occupancy of class Group B "Educational Building" (Sub-Div. B-I) with effect from2.3.\[\langle a \frac{3}{2} \ldots \ld

Issued on 23 103 12023. at New Delhi by.

DIRECTOR Delhi Fire Service

Copy to:-

- 1. Director of Education, Govt. of NCT, Delhi.
- 2. The Principal, N.P. Primary School at R.K. Ashram Marg, New Delhi.
- Sh. N.K. Gaur (Fire Officer) Fire Department, NDMC, Palika Kendra, New Delhi.

Conditions for the validity of Fire Safety Certificate

- 1. All the means of escape shall be kept free of all types of obstruction all the time.
- 2. All the fire safety arrangements provided there in shall be maintained in good working condition at all time.
- Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- The compliance with regards to electrical installation, structural stability, set back area, occupancy and any deviation in construction etc. shall be verified from authority concerned.
- Basement shall be used as per NBC/BBL 1983.
- 6. Any deviation w.r.t construction etc. shall be verified by the concerned building sanctioning authority.
- This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.
- Any flammable material for interior decoration shall strictly prohibited.

INSPECTION REPORT 1. Name & address of the building:-

N.P. Primary School at R.K. Ashram Marg,

New Delhi

2. Type of occupancy:-Educational Group B-I, Gr.+01 Upper Floor 3. Type of case:-

4. Details of previous NOC:-No. F6/DFS/MS/2020/School/38 dated

31/01/2020

5. Fire safety directives No.-N/A

6. Date of inspection:-09/03/2023

7. Name of the inspecting officer:-Sh. Ravinder Singh (ADO/CC)

8. Name & designation of officer From the building side:-

Sh. N.K. Gaur (Fire Officer)

9. Year of construction:-2005

Applicant's letter No:email id fo@ndmc.gov.in_dated_04/02/2023

S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement NBC	Provided at site	Old Case Remarks MR/NMR		
1.	Access to Building					
	1) Road width	12 mtr.	12 mtr.	MR		
	2) Gate width	05mtr.	05 mtr.	MR		
	3)Width of internal road	NA	NA NA			
2.			INA	NA		
	Number, Width Type & Arrangement of Exits A. Number of staircases					
	1. Upper floors	02	02 8 01	MD		
	2. Basements	N/A	02 & 01 ramp N/A	MR		
	B. Width of staircase	13//4	IN/A	N/A		
	1. Upper floors	1.5mtr	1.4 mtr., 1.50 mtr. (Iron) & ramp 1.60 mtr.	MR /		
	2. Basements	N/A	N/A	N/A		
	C. Protection of exits			1.07.1		
	Fire check door	N/A	N/A	N/A		
	2. Pressurization	N/A	N/A	N/A		
	D. No. of continuous staircase to terrace	N/A	N/A	N/A		
	E. Width of corridor	N/A	N/A	N/A		
	F. Door size	1 mtr.	1 mtr.	MR		
3.	Compartmentation					
	Fire check door	N/A	N/A	N/A		
	2) Sealing of electrical shafts	N/A	N/A	N/A		
	Fire rating of shaft door	N/A	N/A	N/A		
	4) Water curtain	N/A	N/A	N/A		
	5) Fire Dampers	N/A	N/A	N/A		
4.	Smoke Management System					
	1) Basements	N/A	N/A	N/A		
	2) Upper floors	N/A	N/A	N/A		
5.	Fire Extinguishers					
	1) Total numbers	06 Nos.	08 Nos.	MR		
	2) Types	ABC & CO2	ABC & CO2	MR		
	3) ISI marking	N/A	N/A	N/A		
6.	First-Aid Hose Reel			1		

V 4

N/16

	,			1			
	Total number of each floor	N/A	02	N/A			
	2) Length of hose reel hose	N/A	MR	N/A			
	Nozzle diameter	N/A	MR	N/A			
7.	Automatic Fire Detection & Alarming System						
	Type of detectors	N/A	N/A	N/A			
	2) Location of main panel	N/A	N/A	N/A			
	3) Location of repeater panel	N/A	N/A	N/A			
	4) Alternate source of power	N/A	N/A	N/A			
	5) Hooter's Location	N/A	N/A	N/A			
	MOEFA	N/A	Provided	N/A			
	Public Address System	N/A	Provided	N/A			
0.	Automatic Sprinkler System						
	1) Basement	N/A	N/A	N/A			
	2) Upper floors	N/A	N/A	N/A			
	 Sprinkler above false ceiling 	N/A	N/A	N/A			
1.	Internal Hydrants						
	1) Size of riser/down-comer	N/A	N/A	N/A			
	Number of hydrants per floor	N/A	N/A	N/A			
	3) Hose box	N/A	N/A	N/A			
2.	Yard Hydrants						
	1) Total number of hydrants	N/A	N/A	N/A			
	2) Hose box	N/A	N/A	N/A			
3.	Pumping Arrangement						
	Ground level	N/A	N/A	N/A			
	 a) Discharge of main pump 	N/A	N/A	N/A			
	 b) Head of main pump 	N/A	N/A	N/A			
	 c) Number of main pump 	N/A	N/A	N/A			
	 d) Jockey pump out put 	N/A	N/A	N/A			
	e) Jockey pump head	N/A	N/A	N/A			
	f) Stand by pump output	N/A	N/A	N/A			
	g) Stand by pump head	N/A	N/A	N/A			
	h) Auto starting/Manual stopping	N/A	N/A	N/A			
	2) Terrace level						
	a) Discharge of pump	N/A	450 LPM '	N/A			
	b) Head of pump	N/A	30 mtr. /	N/A			
	c) Power supply	N/A	Provided	N/A			
	d) Auto starting of pump	N/A	Provided	N/A			
4.	Captive Water Storage for Fire Fighting						
	Under ground tank capacity	N/A	N/A	N/A			
	a) Draw-off connection	N/A	N/A	N/A			
	b) Fire service inlet	N/A	N/A	N/A			
	c) Access to tank	N/A	N/A	N/A			
	d) Over head tank capacity	N/A	2500 ltr. /	N/A			

~ W. 50/

5.	Exit Signage.	Required	Provided	MR
6.	Provision of Lifts.	,	Fieriaca	IVIK
	a) Pressurization of lift shaft	N/A	N/A	N/A
	 b) Pressurization of lift lobby 	N/A	N/A	N/A
	 c) Communication in lift car 	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	N/A	N/A	N/A
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection Syste any:	m for Protection	of special Risk, if	N/A

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, if approved, we may renew the FSC issued vide letter no F6/DFS/MS/2020/School/38 dated 31/01/2020, under rule 35 of the Delhi Fire Service rules 2010. Accordingly, DFA is put up for kind perusal and signature please.

Signature of the Inspecting Officer

Name: - Ravinder Singh Designation: - ADO (CC)

Dala

Dycho broz

Ho. Muss

Anucca