



FORM 'H': FORM FOR ISSUING FIRE SAFETY CERTIFICATE
[See sub-rule (1) of rule 35]

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/Hospital/2023/NDZ/159

Dated 28/03/2023

FIRE SAFETY CERTIFICATE

Certified that the Leprosy Mission Hospital located at Nand Nagari, Shahdara, Delhi-110093, building comprised of Ground Floor & Two Upper Floors only owned / occupied by Leprosy Mission Hospital was granted FSC by this department vide letter No. F6/DFS/MS/Hospital/2020/NDZ/141 dated 06/03/2020. The premises was re-inspected by the officer concerned of this department on 10/03/2023 in the presence of Dr. Rajeev joy Nathan and found that the said Building have deemed complied with the fire prevention and Fire Safety requirements in accordance with rule 33 of the Delhi Fire Service rules, 2010 and that the building / premises is fit for occupancy Class "Institutional" (Hospital) Group-C with effect from 28/03/2023 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of conditions under 38 of the Delhi Fire Service rules, 2010.

Issued on 28/03/2023 at New Delhi.


(ATUL GARG)
DIRECTOR
DELHI FIRE SERVICE.

Copy to :-

1. Dr. Rajeev joy Nathan, Leprosy Mission Hospital located at Nand Nagari, Shahdara, Delhi-110093.
2. The Director of Health Services, M.O. I/C Nursing Home Cell, Govt. of NCT Delhi, F-17, Karkardooma, Delhi.

Conditions for the validity of Fire Safety Certificate:-

1. All the fire safety arrangement provided there in shall be maintained in good working conditions at all times.
2. Loss of life or property due to non- functional fire safety measure shall be at the responsibility of the management.
3. The trained fire- fighting staff should be available round the clock.
4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
6. "The owner / Occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."
7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on WWW.dfs.Delhigovt.nic.in.

INSPECTION REPORT

N/20

1. Name & address of the building: **Leprosy Mission Hospital, Nand Nagari, Shahdara, Delhi-110093.**
2. Type of Occupancy : **Institutional Building**
3. Building comprised of : **Ground plus Two upper floors**
4. Type of Case : **Renewal**
5. Details of previous NOC : **F6/DFS/MS/Hospital/2020/NDZ/141** dated 6/3/20
6. Fire Safety directives Letter No. : **NBC (Part-IV)**
7. Date of inspection : **10/03/2023**
8. Name of the Inspecting Officer : **A.K. Jaiswal, D.O. (East)**
9. Name and designation of Officer
10. from the building side : **Dr. Rajeev joy Nathan**
11. Year of Construction : **1997**
12. Applicant's letter No Nil out door diary No. **11758** dated 28/02/2023

S No	Minimum standards on fire prevention and fire safety U/R 33	NBC Requirements	Provided at site	Remarks MR/NMR
1.	Access of building			
	• Road width	6 m	15m	MR
	• Gate width	4.5 m	4.5m	MR
	• Width of internal road	N/A	N/A	N/A
2.	Number, width, Type & Arrangements of exits			
	a. Number of staircases			
	• Upper floors	1	2	MR
	• Basements	N/A	N/A	N/A
	b. Width of staircases			
	• Upper floors	2m & 1.43m	2m & 1.43m	MR
	• Basements	N/A	N/A	N/A
	c. Protection of exits			
	• Fire check door	N/A	N/A	N/A
	• Pressurization	N/A	N/A	N/A
	d. No of continuous staircase to terrace	1	Provided	MR
	e. Width Of Corridor	2m	2m	MR
	f. Door Size	2m	2m	MR
3.	Compartmentation			
	• Fire check door	N/A	N/A	N/A
	• Sealing of electrical shafts	N/A	N/A	N/A
	• Fire Rating of shaft door	N/A	N/A	N/A
	• Water Curtain	N/A	N/A	N/A
	• Fire Dampers	N/A	N/A	N/A
4.	Smoke managements System			
	• Basements	N/A	N/A	N/A
	• Ground Floor	N/A	N/A	N/A
5.	Fire Extinguishers			
	• Total numbers	12	15	M/R
	• Types	ISI marked ABC/CO ₂	ABC/CO ₂	M/R
	• IS marking	Required	Provided	M/R

(Signature)

(Signature)

(Signature)

N/21

6.	First - Aid Hose Reels			
	• Total numbers on each floor	1	1	MR
	• Length of hose reel hose	30m	30m	MR
	• Nozzle diameter	5mm	5mm	MR
7.	Automatic fire detection and alarming system			
	• Type of detector	N/A	N/A	N/A
	• Location of Main Panel	N/A	N/A	N/A
	• Location of Repeater Panel	N/A	N/A	N/A
	• Alternate source of power	N/A	N/A	N/A
	• Hooters' Location	N/A	N/A	N/A
8.	MOEFA	N/A	N/A	N/A
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System			
	• Basement	N/A	N/A	N/A
	• Upper Floor	N/A	N/A	N/A
	• Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants			
	• Size of riser/down-comer	100 mm	Provided	MR
	• Number of hydrants per floor	1nos.	Provided	MR
	• Hose Box	1nos.	Provided	MR
12.	Yard Hydrants			
	• Total number of hydrants	N/A	3	N/A
	• Hose Box	N/A	3	N/A
13.	Pumping Arrangements			
	• Ground Level			
	➤ Discharge of main pump	N/A	N/A	N/A
	➤ Head of main pump	N/A	N/A	N/A
	➤ Number of main pumps	N/A	N/A	N/A
	➤ Jockey pump out put	N/A	N/A	N/A
	➤ Jockey pump head	N/A	N/A	N/A
	➤ Standby Pump out put	N/A	N/A	N/A
	➤ Standby Pump Head	N/A	N/A	N/A
	➤ Auto Starting/Manual stopping	N/A	N/A	N/A
	➤ Pump House Access	N/A	N/A	N/A
	• Terrace level			
	➤ Discharge of pump	900 LPM	Provided	MR
	➤ Head of the pump	40 m	Provided	MR
	➤ Power supply	Required	Provided	MR
	➤ Auto starting of pump	Required	Provided	MR
14.	Captive water Storage for fire fighting			
	• Underground tank capacity	1,00,000 ltr	1,00,000 ltr	MR
	➤ Draw of connection	N/A	N/A	N/A
	➤ Fire service inlet	N/A	N/A	N/A
	➤ Access to tank	N/A	N/A	N/A
	• Overhead Tank capacity	20,000 Ltr	25,000 Ltr	MR

N/22

		Required	Provided	MR
15	Exit Signage			
16	Provision of Lifts			
	➤ Pressurization of Lift Shaft	N/A	N/A	N/A
	➤ Pressurization of lift lobby	N/A	N/A	N/A
	➤ Communication in lift Car	Required	Provided	MR
	➤ Fireman's Grounding Switch	Required	Provided	MR
	➤ Lift Signage	N/A	N/A	N/A
17	Standby power supply	Required	Provided	MR
18	Refuge Area	N/A	N/A	
	➤ Total area	N/A	N/A	N/A
	➤ Location	N/A	N/A	N/A
19	Fire control room			
	➤ Detector system panel	N/A	N/A	N/A
	➤ Flow Switch Panel	N/A	N/A	N/A
	➤ PA System Panel	N/A	N/A	N/A
	➤ Battery backup	N/A	N/A	N/A
	➤ Building Floor Plans	N/A	N/A	N/A
20	Special Fire Protection Systems for Protection of special Risks, if any,	N/A	Provided Local Application	N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection. MCB and Conduit Metal Wiring have also been provided.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter No **F6/DFS/MS/Hospital/2020/NDZ/141** dated **06/03/2020** renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

A.K. Jaiswal
13/03/2023

Signature of the Inspecting Officer
Name A K Jaiswal
Designation D O (East)

Sy. CFO (NDZ)

RMP
14/03/23

C.F/O.

15/03/2023

Director (M)
14/03/23

OLP/NA

RMP
17/03/23

DO (E/O)

F.T. is placed opposite for sign-
Director (M)
18/03/23