



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No F 6/DFS/MS/2023/SZ/173

Dated 06/04 /2023

FIRE SAFETY CERTIFICATE

Issued on 06 / 04 /2022 at New Delhi by

DIRECTOR

DELHI FIRE SERVICE

Copy to: -

 The Chief Development Officer-Dial, New Udaan Bhawan, Opposite-Terminal- 3, 1G1 Airport New Delhi 110037.

 Head Cargo, DIAL, Public Amenities Complex, City Side, Cargo Complex, Delhi International Airport, New Delhi-110057

Conditions for the validity of Fire Safety Certificate -

- 1 All the means of escape/entry/exit shall be kept free from any obstruction.
- 2 All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the management.
- 3 All the staff members must know the correct method of operation of fire-fighting system.
- 4 The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5 This fire safety certificate may not in any way be treated as regularization (Clause 2 8 of UBBL-2016) of unauthorized construction or alteration (Clause 1 4 3 of UBBL-2016), if any
- 6 "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry"

N/2



		TION REPORT		0.1	
1	Name & Address of the Building	Public Amenities Complex, City Side, Cargo Complex, Delhi International Airport, New Delhi 110057			
2	Type of Occupancy	Mixed occupancy (Assembly/Mercantile & Business)			
3	Building Comprised of	Ground plus Two upper floors			
4	Type of Case	New case			
5	Details of Previous NOC	Nil			
	Fire Safety Directives Letter No	F6/DFS/MS/BP/2021/278 dated 17/06/2021 f			
6	Fire Salety Directives Detter No	ground plus four floor but constructed Ground plus two upper floors only			
7	Date of Inspection	29/03/2023	The second second second second		
8	Name of the Inspecting Officers	DO(SD) & ADO (BCP)	12	
9	Name & Designation of Officers from the building side	Mr. Vipin Kumar			
10	Year of construction	2021			
11	Applicant letter No.	Outdoor diary no	12563 dated 24/03/20		
S.	Minimum standards on Fire Prevention	NFPA	Provided at Site	Remarks	
No.	and Fire Safety U/R 33	Requirements		MR/NMF	
1	Access to Building.		4.12	1.00	
	Road width	9m	11.5 mtr	MR MR	
	Gate width	6m NA	Provided	-	
	Width of internal road		NA	NA	
2	Number, width, type & arrangement of ex	its.			
	a) Number of Staircase	00.37.	02 Nos	MR	
	> Upper floors. > Basement floor.	02 Nos	N/A	N/A	
		N/A	IVA	IVA	
	b) Width of Staircase > Upper floors	1.50 mtr	1.50 mtr	MR	
	> Basement floor	N/A	N/A	N/A	
	c) Protection of exits				
	> Fire check door	Required	Provided	MR	
	> Pressurization	N/A	N/A	N/A	
	d) No. of continuous staircase to terrace	Required	Provided	MR	
	e) Width of corridor	N/A	N/A	N/A	
	f) Door size	1.50 mtr	1.50 mtr	MR	
3	Compartmentation.		n : 11	MR	
	Fire check door.	Required	Provided Provided	MR	
	 Sealing of electrical shafts. Fire rating of shaft door. 	Required N/A	N/A	N/A	
	Water curtain	N/A N/A	N/A	N/A	
	Fire dampers.	N/A	N/A	N/A	
4	Smoke Management system.				
	Basement	30 ACPH	N/A	N/A	
	Upper floors	12 ACPH	Mechanical type	MR	
5	Fire Extinguishers.	Decoised.	20 Mar	100	
	Total numbers	Required ABC/CO ₂	30 Nos ABC & CO ₂	MR MR	
	Types ISI Marking	Required	Provided	MR	
6	First Aid Hose Reels.		TOTICAL	IVER	
-	Total numbers on each floor.	02 at each floor	Provided	MR	
	Length of hose-reel hose.	30m	Provided	MR	
	Nozzle Diameter	5mm	Provided	MR	
	The state of the s				
7	Automatic fire detection & alarming system	m.			
7	Automatic fire detection & alarming system Type of detectors	Required	Smoke & heat	MR	
7			Smoke & heat Provided	MR MR	

C Mu

M13

7-		10
//-		
आज़ादी व अमृत 1	ा महोत्सव	

	 Alternate source of power 	Required	Provided	MD
	 Hooter's location 	Required	Provided	MR
8	MOEFA	Required	Provided	MR
9	Public Address System	Required	Provided	MR
0	Automatic Sprinkler System		Tiorided	MR
	Basement	N/A	N/A	2111
	 Ground floor to fourth floor 	Required	Provided	N/A
	 Sprinkler above false ceiling 	Required	Provided	MR
11	Internal Hydrants.		riovided	MR
	Size of Riser/Down-comer	150mm	Provided	
	 Number of Hydrant per floor 	02 Nos	Provided	MR
	Hose box.	02 Nos	Provided	MR
12	Yard Hydrants.	02 1103	riovided	MR
	Total number of hydrants.	05 Nos	D '111	
	Hose box.	05 Nos	Provided	MR
13	Pumping arrangements.	03 1408	Provided	MR
	Ground Level			
	Discharge of main pump.	2050 1 754		
	Head of main pump.	2850 LPM	Provided	MR
	Number of main pumps.	70m	Provided	MR
	Jockey Pump output.	03 Nos. 2 x 180 LPM	Provided	MR
	Jockey Pump head.	70m	Provided	MR
	Standby Pump output.	2850 LPM	Provided	MR
	Standby Pump head.	70m	Provided	MR
	Auto Starting/Manual Stopping.	Required	Provided	MR
	Pump house access.	Required	Provided	MR
	Terrace Level	Required	Provided	MR
	Discharge of pump.	N/A	N/A	
	Head of pump.	N/A	N/A	N/A
	Power supply.	N/A	N/A	N/A
	Auto starting of pump.	N/A	N/A	N/A
14	Captive water storage for fire fighting.		IVA	N/A
	 Underground tank capacity. 	2, 00, 000 Ltrs	2, 00, 000 Ltrs	MR
	Draw-off connection.	Required	Provided	MR
	Fire Service Inlet.	Required	Provided	MR
	Access to tank.	Required	Provided	MR
15	Overhead tank capacity.	20,000 ltr	Provided	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			
	Pressurization of lift shaft.	Required	Provided	MR
	Pressurization of lift lobby. Communication in lift core	Required	Provided	MR
	communication in fitt car.	N/A	N/A	N/A
17	• Fireman's switch.	N/A	N/A	N/A
	Lift signage. Standby Power Supply	N/A	N/A	N/A
18	Refuge Area	Required	Provided	MR
	Total area	****		
19	Location	N/A	N/A	N/A
	Fire Control Room.	N/A	N/A	N/A
	Detector system panel.	 		
	Flow switch panel.	Required	Provided	MR
	PA system panel.	Required	Provided	MR
		Required	Provided	MR
		Required	Provided	MR

0

W

अमृत महोत्राव

	Battery backup. Building floor plan.	Required	Provided	MR
20	Special Fire Protection System for the Protection of special Risk, if any.	Required	Provided	MR

The Fire protection systems provided in the building were test checked at random and found functional at the time of inspection.

Keeping in view of the substantially satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 (3) of the Delhi Fire Service Rules, 2010

Accordingly DFA is put up for approval and signature please.

Signature of inspecting Officer Name Sh. M.K Sharma

Designation: DO (South)

Signature of the Inspecting Officer

Name: Sh. Rajesh Kumar Designation: ADO (BCP)

CFO (HQ)

F.1. Letter is protop for John