

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F.6/DFS/MS/BNQT/WZ/2023/ 16

Dated: 10/04/2023

FIRE SAFETY CERTIFICATE

Certified that the M/s. Ananda Banquet Hall located at 33/33A, Shivaji Marg, Najafgarh Road, New Delhi-110015, comprised of Basement, Ground plus 02 upper floors. was granted fire safety certificate by this department vide letter no. F6/DFS/MS/BANQ/WZ/2022/65 dated 05/12/2022 to M/s. Ananda Banquet for Ground floor only. Now, The Owner have added 2nd & 3rd floor (FSC was issued for all floors in 2011). The premises was re-inspected by the officer concerned of this department on 03-03-2023 in the presence of Sh. Ishant Harjai (Owner) and found that the Fire prevention and fire safety arrangements provided in the building, found in good working condition. The premises have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire service Rules, 2010 and that the building / premises is fit for occupancy class "Assembly" Group D with effect from 10/04/2023 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010 conditions printed overleaf.

Issued on 10/04/2023 at New Delhi by


(Anil Garg)
Director

Copy to :-

1. The owner/ Occupier, M/s. Ananda Banquet Hall located at Ground floor, 33/33A, Shivaji Marg, Najafgarh Road, New Delhi-110015. (Online Application ID No. 2023021902286 dated 19/02/2023)
2. The Dy. Health Officer, MCD, West Zone, Vishal Enclave, Rajouri Garden, New Delhi - 110027. dhowestzone@gmail.com

INSPECTION REPORT

1. Name & address of the building	Ananda Banquets, located at GF, FF & SF, Plot no. 33/33A, Shivaji Marg, Najafgarh Road, New Delhi-110015.
2. Type of Occupancy	Banquet Hall (Assembly)
3. Type of Case	New, Addition of 1 st & 2 nd floor (Earlier FSC was issued for ground floor only vide depts. letter F6/DFS/MS/BANQ/WZ/2023 dtd 05.12.2022)
4. Details of previous NOC	F6/DFS/MS/WZ/2018/2737 dated 19/12/2018 for GF only
5. Fire Safety directives letter No	F6/DFS/MS/BP/2011/839 dated 09/05/2011
6. Date of inspection	03/03/2023
7. Name of the Inspecting Officers	Sarabjeet Singh ADO (MN)
8. Name and designation of officers from the building side	Sh. Ishant Harjai (Owner)
9. Year of Construction	2011 (As per Prev. Insp. report dated 02/12/2018)
10. Applicant's letter No.	Online Application ID No. 2023021902286 dated 19/02/2023

The Said Banquet Hall is running at Ground, First & Second floor in a Building comprised of Basement + Ground + 02 upper floors & Kitchen is running at 2nd floor.

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	BBL /NBC Requirement	Provided at site	Remarks MR/NMR
1	Access to building			
	<ul style="list-style-type: none"> • Road width • Gate width • Width of internal road 	12 m 5 m NA	Provided On Main Road NA	MR MR NA
2	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases			
	<ul style="list-style-type: none"> • Upper Floors • Basements 	02 02	Provided Provided	MR MR
	b. Width of staircases			
	<ul style="list-style-type: none"> • Upper Floors • Basements 	1.5mtr & 1.25mtr 1.5m, & 1.25m	Provided 1 x 1.25m & 1x 2m	MR MR
	c. Protection of exits			
	<ul style="list-style-type: none"> • Fire check door • Pressurization 	Required NA	Provided NA	MR NA
	e. No. of continuous staircases to terrace	02	Provided	MR
	f. Width of Corridor	NA	NA	NA
	g. Door Size	2m x 2	Provided	MR
3	Compartmentation.			
	<ul style="list-style-type: none"> • Fire check door • Sealing of electrical shafts • Fire Rating of shaft door • Water Curtain • Fire Dampers 	Required NA NA NA NA	Provided NA NA NA NA	MR NA NA NA NA
4	Smoke Management System.			
	<ul style="list-style-type: none"> • Basements • Upper floors 	Required Required	Provided Provided	MR MR
5	Fire Extinguishers			
	<ul style="list-style-type: none"> • Total numbers • Types • IS marking 	20 nos. CO ₂ , ABC type ISI marked	Provided Provided Provided	MR MR MR

(Signature)

(Signature)

6	First-Aid Hose Reels.			
	• Total numbers on each floor	01	Provided	MR
	• Length of hose reel hose	30m	Provided	MR
	• Nozzle diameter	5mm	Provided	MR
7	Automatic fire detection and alarming system.			
	• Type of detectors	Smoke & Heat	Provided	MR
	• Location of Main Panel	Required	Provided	MR
	• Location of Repeater Panel	Required	Provided	MR
	• Alternate source of power	Required	Provided	MR
	• Hooters' Location	Required	Provided	MR
8	MOEFA	Required	Provided	MR
9	Public Address System.	NR	NR	NR
10	Automatic Sprinkler System.			
	• Basement	Required	Provided	MR
	• Upper Floor	NR	Provided	NR
	• Sprinkler above false ceiling	NR	Provided	NR
11	Internal Hydrants			
	• Size of riser/down-comer	100 mm	Provided	MR
	• Number of hydrants per floor	01	Provided	MR
	• Hose Box	01	Provided	MR
12	Yard Hydrants.			
	• Total number of hydrants	NR	NR	NR
	• Hose Box	NR	NR	NR
13	Pumping Arrangements.			
	• Ground Level	Provide at Terrace		
	➤ Discharge of main Pump	2280 LPM	Provided	MR
	➤ Head of Main pump	45 MH	Provided	MR
	➤ Number of main pumps	02	Provided	MR
	➤ Jockey Pump out put	180 LPM	Provided	MR
	➤ Jockey pump head	45 MH	Provided	MR
	➤ Standby Pump out put	2280 LPM	Provided	MR
	➤ Standby Pump Head	45 MH	Provided	MR
	➤ Auto Starting/ Manual stopping	Required	Provided	MR
	➤ Pump House Access	Required	Provided	MR
	• Terrace level			
	➤ Discharge of pump	NR	NR	NR
	➤ Head of the pump	NR	NR	NR
	➤ Power Supply	NR	NR	NR
	➤ Auto Starting of pump	NR	NR	NR
14	Captive Water Storage for fire fighting.			
	• Underground tank capacity	50,000	Provided at terrace	MR
	➤ Draw-off connection	NA	NA	NA
	➤ Fire service inlet	Required	Provided	MR
	➤ Access to tank	NA	NA	NA
	• Overhead Tank capacity	10,000 ltrs	Provided	MR
15	Exit Signage.	Required	Provided	MR

16	Provision of Lifts.			
	• Pressurization of Lift Shaft	NA	NA	NA
	• Pressurization of Lift lobby	NA	NA	NA
	• Communication In lift Car	Required	Provided	MR
	• Fireman's Grounding Switch	Required	Provided	MR
	• Lift Signage	Required	Provided	MR
17	Standby power supply	Required	Provided	MR
18	Refuge Area.			
	> Total Area	NA	NA	NA
	> Location	NA	NA	NA
19	Fire Control Room	Not Required		
	• Detector System Panel	NA	NA	NA
	• Flow Switch Panel	NA	NA	NA
	• PA System Panel	NA	NA	NA
	• Batter backup	NA	NA	NA
	• Building Floor Plans	NA	NA	NA
20	Special Fire Protection Systems for Protection of special Risks, if any:	NA	NA	NA

Note: As per the Guidelines issued vide this deptt. Letter no F6/DFS/MS/BP/2011/839 dtd 09.05.2011, three staircases are proposed for the basement floor. Now two staircase is provided which is approved by worthy Director at page N/44.

The fire protection systems provided in the building were checked & found functional at the time of inspection.

The shortcomings issued by this deptt. earlier vide letter no F6/DFS/MS/BANQ/WZ/2022/91 dtd 10.06.2022 & F6/DFS/MS/BNQT/WZ/2022/186 dtd 07.11.2022 have been complied.

Keeping in view the substantial compliance of the minimum standards on fire prevention & fire safety requirement under the rules it is recommended to grant Fire Safety Certificate under rule 35 of Delhi Fire Service Rules 2010.

DFA is put up for approval & signature please.

DO (West)

[Signature]
06/03/2023

[Signature]
06/03/2023

Signature of the Inspecting Officer
Sarabjeet Singh
ADO (Moti Nagar)

DO (DPA)
[Signature]
10/08/2023

CAO
[Signature]
10/31/2023

Director
[Signature]
10/09/23

[Signature]

DD/MN
03/2023

DO (WEST) 7.54
DATED 6/3/2023