## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001

No.F6/DFS/MS/GH/2023/ 74

Dated: 63/94. /2023

FIRE SAFETY CERTIFICATE

Certified that the A-10 International Guest House located at 3244, Gali School Wali, Pahar Ganj, New Delhi comprised of Ground + 04 Upper floors, Ground floor (02 guest rooms + reception), 1st floor ( 02 guest room ) 2nd to 3rd floor (03 guest rooms at each floor) 4th floor not in use as per affidavit dated 03.12.2019, total 10 guest rooms. The FSC was granted by this department vide letter No. F6/DFS/MS/GH/2020/NDZ/22 dated 16/01/2020 for 13 guest room up to third floor. Now, The premises was re-inspected by the officer concerned of this department on 21/03/23 in the presence of Manger and found that the said guest house building having been given an affidavit regarding not to use any floor above third floor by applicant dated 03/12/19, has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential Group A- Ground floor (02 guest rooms + reception), 1st floor (02 guest rooms ), 2nd to 3rd floor (03 guest rooms at each floor), total 10 guest rooms only up to third floor with effect from 03/04/2023 for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, mentioned below.

Issued 03/04/2027 at New Delhi by.

DIRECTOR

Delhi Fire Service

Copy to:-

- 1. The Commissioner of North, MCD, Civic Centre, New Delhi, to kindly ensure the occupancy as detailed above.
- 2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi online ID No. 2022121921513 dated 13.01.23
- The Manager.
  - A-10 International Guest House at 3244, Gali School Wali, Pahar Ganj, New Delhi.

Condition for the validity of Fire Safety Certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- The trained fire fighting staff should be available round the clock
- The compliance with regards to electrical installation, structural stability, set back area, occupancy and any deviation in construction etc. shall be verified from authority concerned
- This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any
- The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry
- Any flammable material for interior decoration is prohibited.

1. 1	Name & address of the building	M/S A-10	International Guest F School Wali, Pahar G	louse Gani.	
		3244, Gall	School Wan, Land	5. T.W.	
		New Delhi	Sub Division-A-1		
2.	Type of occupancy:-		- Core (total 10 times)	rooms)	
	5.2.		Desembles + II/ OHCM III	Dillar, t Hoor	
			- I to I Thought this built	I I UUIII J I WIMI	
		not in use as per affidavit dated 03/12/19.			
3.	Type of case:-	Renewal	S/MS/GH/2020/NDZ	J22 dated	
4.	Details of previous FSC:-	No. F6/DFS/MS/GH/2020/NDZ/22 dated 16/01/20.			
		N/A			
5.	Fire safety directives No	21/03/23			
6.	Date of inspection -		er Singh (ADO/CC)		
7.	Name of the inspecting officer.	Jil. Ital			
8.	Name & designation of officer	Manager			
	From the building side:-	2010	7.87527012712 W		
9.	Year of construction -	online ID No	. 2022121921513 da	Old Case	
10.	Applicant's letter No	79		Remarks	
2.31	Minimum Standards on fire	Requirement	Provided at site	MR/NMR	
S.No.	Prevention and fire safety	Existing fire		MICHAIN	
	U/R 33	safety arrangements			
	Access to Building				
1.		N/A	05 mtr Approx	MR	
	1) Road width	N/A	N/A	N/A	
	2) Gate width	N/A	N/A	N/A	
	3)Width of internal road		xits		
2.	Number, Width Type & Arr	angement of 2			
	A. Number of staircases	01 Nos.	01 Nos.	MR	
	1. Upper floors	N/A	N/A	N/A	
	2. Basements				
	B. Width of staircase	0.80 mtr.	1.30 to 1.45 mtr.	MR /	
	1. Upper floors	N/A	N/A	N/A	
	Basements     Protection of exits			51/4	
	1. Fire check door	N/A	N/A	N/A	
	2. Pressurization	N/A	N/A	N/A	
	D. No. of continuous	01	01	MR	
	staircase to terrace			N/A	
	E. Width of corridor	N/A	N/A 206 cms x 90 cms	N/A	
	F. Door size	N/A	206 CHS X 90 CHS	IVA	
3.	Compartmentation		NUA	N/A	
3.	1) Fire check door	N/A	N/A	N/A	
	2) Sealing of electrical shafts	N/A	N/A	N/A	
	3) Fire rating of shaft door	N/A	N/A N/A	N/A	
	4) Water curtain	N/A	N/A N/A	N/A	
	5) Fire Dampers	N/A	INCA		
4.	Smoke Management System	1 20 A CDL1	N/A	N/A	
	1) Basements	30 ACPH	Natural/exhaust	The second second second	
	2) Upper floors	12 a/c per	1 THEM OF STREET	- I was a second	

v.

ate

at it o /as gu ep

7in 3/1

th sic 3" 1 C

in

(

ì

rk al

1

1

W 64 50

		hour	fan		
5.	Fire Extinguishers				
	1) Total numbers	10 Nos.	10 Nos.	MR	
	2) Types	ABC & CO2	ABC & CO2	MR	
	3) ISI marking	Required	Provided	MR	
5.	First-Aid Hose Reel	ringuirea	Tiovided	IVIX	
	1) Total number of eachfloor	01	01	MR	
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR	
	3) Nozzle diameter	05 mm	05 mm	MR	
7.	Automatic Fire Detection & Alarming System				
	1) Type of detectors Co type	Required	Provided	MR	
	2) Location of main panel	Ground floor	Provided	MR	
	3) Location of repeater panel	N/A	N/A	N/A	
	4) Alternate source of power	Required	Provided	MR	
	5) Hooter's Location	at each floor	Provided	MR	
3.	MOEFA	N/A	N/A	N/A	
).	Public Address System	Required	Provided	MR	
10.	Automatic Sprinkler System		Flovided	MK	
	1) Basement	N/A	N/A	N/A	
	2) Upper floors	N/A	N/A	N/A N/A	
	3) Sprinkler above false	N/A	N/A	N/A	
	ceiling	1.00	NA	IN/A	
1.	Internal Hydrants				
	1) Size of riser/down-comer	N/A	N/A	N/A	
	2) Number of hydrants per	N/A	N/A	N/A	
	floor	****	1000	IN/A	
	3) Hose box	N/A	N/A	N/A	
2.	Yard Hydrants			1.072	
	1) Total number of hydrants	N/A	N/A	N/A	
	2) Hose box	N/A	N/A	N/A	
13.	Pumping Arrangement				
	Ground level	N/A	N/A	N/A	
	a) Discharge of main	N/A	N/A	N/A	
	pump	1 1000	AMOR		
	b) Head of main pump	N/A	N/A	N/A	
	c) Number of main pump	N/A	N/A	N/A	
	d) Jockey pump out put	N/A	N/A	N/A	
	e) Jockey pump head	N/A	N/A	N/A	
	f) Stand by pump output	N/A	N/A	N/A	
	g) Stand by pump head	N/A	N/A	N/A	
	h) Auto starting/Manual stopping	N/A	N/A	N/A	
	2) Terrace level				
	<ul> <li>a) Discharge of pump</li> </ul>	450 LPM	450 LPM	MR	
	b) Head of pump	30 mtr.	30 mtr.	MR	
	c) Power supply	Required	Provided	MR	
	d) Auto starting of pump	Required	Provided	MR	

J W, SO

14.	Captive Water Storage for Fire Fighting					
	Under ground tank capacity	N/A	N/A	N/A		
	a) Draw-off connection	N/A	N/A	N/A		
	b) Fire service inlet	N/A	N/A	N/A		
	c) Access to tank	N/A	N/A	N/A		
	d) Over head tank capacity	5000 ltr.	5,000 ltr.	MR		
15.	Exit Signage.	Required	Provided	MR		
16.	Provision of Lifts.			i-ux		
	Pressurization of lift shaft	N/A	N/A	N/A		
	<ul> <li>Pressurization of lift lobby</li> </ul>	N/A	N/A	N/A		
	<ul> <li>c) Communication in lift car</li> </ul>	N/A	N/A	N/A		
	d) Fireman's switch	N/A	N/A	N/A		
	e) Lift signage	N/A	N/A	N/A		
17.	Stand by Power Supply	Required	Provided	MR		
18.	Refuge Area	N/A	N/A	N/A		
	Total area location	N/A	N/A	N/A		
19.	Fire Control Room	N/A	N/A	N/A		
	a) Detector system     panel	N/A	N/A	N/A		
	b) Flow switch panel	N/A	N/A	N/A		
	c) PA system panel	N/A	N/A	N/A		
	d) Battery backup	N/A	N/A	N/A		
	e) Building floor plan	N/A	N/A	N/A		
20.	Special Fire Protection System for Protection of special Risk, if any: One ABC type fire extinguisher found provided near elect. Panel.					

The fire protection systems provided in the guest house building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, if approved we may renew the FSC issued vide letter no F6/DFS/MS/GH/2020/NDZ/22 dated 16/01/2020, up to third floor only under rule 35 of the Delhi Fire Service rules 2010. Accordingly, DFA is put up for kind perusal and signature please.

Signature of the Inspecting Officer

Name: - Ravinder Sing Designation: - ADO (CC)