

No. F6/DFS/MS/EH/2023/SZ/ | 19

FIRE SAFETY CERTIFICATE

Certified that the M/s House of Punjab (A unit of Exxotica Foods) restaurant running at ground & first floor only, in a building comprised of ground & first floor (restaurant), second floor (vacant) & third floor open hall located at E-68, Guru Nanakpura Jail Road, New Delhi-110058, owned/occupied by M/s House of Punjab (A unit of Exxotica Foods) restaurant have complied with the fire prevention and fire safety requirements in accordance with Rules 33 of the Delhi Fire Service Rules 2010 and verified by the officer concerned of this department on 20/03/2023 in the presence of Sh. Romy Arora (Owner) of the restaurant and that the building is fit for occupancy class "D" 'Assembly Building' (Ground & first floor only) with effect from \(\Omega\)5/04/2013 for a period of three years in accordance with the Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010, printed below.

Issued on ... 05/04/2023..... at New Delhi by

Director Delhi Fire Service

Copy to:-

- 1 Sh. Romy Arora (Owner), M/s House of Punjab (A unit of Exxotica Foods), E-68, Guru Nanakpura Jail Road, New Delhi-110058.
- 2 The Additional Commissioner of Police, Licensing Unit 1st Floor Police station, Defence Colony, New Delhi.

Following fire safety directives must be adhered to:-

- 1. This NOC is valid only for ground & first floor.
- All the means of escape shall be kept free of all type of obstruction all the time.
- All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.
- This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction /unauthorized use of land if any.
- The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.
- The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form
 'J' [sub rule (1) of rule (37)] along with a copy of this Certificate, six months prior to its expiry.

INSPECTION REPORT 1. Name & address of the building: M/s House of Punjab, E-68, ground & first floor, Gurunanakpura Jail Road, New Delhi-110058. 2. Building is comprised of : Ground plus three upper floors But Restaurant is running at ground & first floor only. Type of Occupancy Group 'D' Assembly Building Type of Case New 5. Details of Previous FSC : Nil 6. Fire Safety directives letter No : N/A Date of inspection : 20/03/2023 8. Name of Inspecting Officer : A.D.O. R.K. Yadav & DO Vedpal Chhikara 9. Name and designation of officers From the building side : Sh. Romy Arora (Owner) 10. Year of Construction : 1997 11. Applicant's letter No. : ID No. 2023031303513 dated 13/03/2023 Minimum Standards on fire prevention | Requirements | Provided at Remarks and fire safety U/R 33 site MR/NMR Access to building Road width 12 m Provided M/R N/A Open to road MR Gate width N/A N/A N/A Width of internal road Number, Width, Type & Arrangement of Exits a. Number of staircases 2 Nos. MR Upper Floors 2 Nos N/A N/A Basements N/A b. Width of staircases Upper Floor 1.5 M each MR 1.5 M each N/A N/A N/A Basements c. Protection of exits MR Provided Required Fire check door N/A N/A N/A Pressurization d. No. of continuous staircases to N/A N/A terrace N/A e. Width of Corridor N/A N/A N/A f. Door Size MR 18 M. 170M & 2X1 50 m 15 M Compartmentation N/A N/A N/A Fire check door N/A N/A N/A Sealing of electrical shafts N/A N/A Fire Rating of shaft door N/A N/A N/A Water Curtain N/A N/A N/A Fire Dampers N/A Restaurant is running at ground & First floor only Smoke Management System

4. N/A N/A N/A Basements MR Provided Required Upper floors

Fire Extinguishers MR Provided 5. 08 no.'s Total numbers MR Provided ABC & CO2 type MR Types Provided ISI marked IS marking

S.

No.

1.

2.

3.



)6	First-Aid-Hose Reels.		Provided	MR		
-	Total numbers on each floor	01 No.	Provided	MR		
	Length of hose reel hose	30 m	Provided	MR		
	Norte diameter	05 mm	11011000			
07	Automatic Fire Detection and Alarming System.					
		Smoke	Provided	N/A		
	Type of detectors	N/A	N/A	N/A		
	Location of main panel Location of repeater panel	N/A	N/A	N/A		
	of power	N/A	N/A	N/A		
	l to the territory	N/A	N/A	MR		
		Required	Provided			
08	MOEFA Public Address System.	N/A	N/A	N/A		
09						
10	Automatic Sprinkler System.					
	Basement	N/A	N/A	N/A		
	 upper floor 	N/A	N/A	N/A		
	 sprinkler above false ceiling 	N/A	IVA			
11	Internal Hydrants	100.1414	Provided	MR		
	 size of riser/down-comer 	100 MM 01 No.	Provided	MR		
	 Number of hydrants per floor 		Provided	MR		
	Hose box	01 No.	Titviaca			
12	Yard Hydrants.		21/4	N/A		
	 Total number of hydrants 	N/A	N/A	N/A		
	Hose box	N/A	N/A	NA		
13	Pumping Arrangements.					
_	> Ground Level					
	Discharge of main pump	N/A	N/A	N/A		
	Head of Main pump	N/A	N/A	N/A		
	Number of main pumps	N/A	N/A	N/A		
	Jockey pump out put	N/A	N/A	N/A		
	 Jockey pump head 	N/A	N/A	N/A		
	 Standby pump out put 	N/A	N/A	N/A		
	 Standby pump head 	N/A	N/A	N/A		
	 Auto starting /manual stopping 	N/A	N/A	N/A		
	 Pump house access 	N/A	N/A	N/A		
	> Terrace Level					
	 Discharge of pump 	450 Lpm	Provided	MR		
	 Head of the pump 	40 M	Provided	MR		
	 Power supply 	Required	Provided	MR		
	Auto starting of pump	Required	Provided	MR		
14	Captive Water Storage for Fire Fighting.					
	 Underground tank capacity 	N/A	N/A	N/A		
	Draw-off connection	N/A	N/A	N/A		
	Fire service inlet	N/A	N/A	N/A		
	Access to tank	N/A	N/A	N/A		
	Overhead tank capacity	20,000 Ltrs.	20,000 Ltrs	MR		
15	Exit Signage.					
16	Provision of Lifts.					
	Pressurization of lift Shaft	N/A	N/A	N//		
	 Pressurization of lift lobby 	N/A	N/A	N/A		
	 Communication in lift car 	N/A	N/A	N/		
	 Firemen's grounding switch 	N/A	N/A	N/		
	 Lift signage 	N/A	N/A	N/A		

K

17	Standby Power Supply	Required	Provided	MR		
18	Refuge Area.					
	Total area	N/A	N/A	N/A		
	Location	N/A	N/A	N/A		
19	Fire Control Room					
	Detector system panel	N/A	N/A	N/A		
	 Flow switch panel 	N/A	N/A	N/A		
	PA system panel	N/A	N/A	N/A		
	Battery backup	N/A	N/A	N/A		
	Building floor Plans	N/A	N/A	N/A		
20	Special Fire Protection Systems for Protection of Special Risks, if any:	N/A	N/A	N/A		

Building is comprised of ground & first floor (restaurant), second floor (vacant) & third floor Open hall.

The fire protection systems provided in the building were tested/checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rule 2010.

Signature of Hisperting Officer

Name: - R.K. Yadav

Designation:- Asstt. Divisional Officer

Signature of Inspecting Officer

Name:- Vedpal chhikara

Designation:- Divisional Officer

the great It and both How you

E.

1,

sib atio

of

he

)ire its