



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F.6/DFS/MS/Indl./2023/SZ/ 190 Dated 20 104 /2023

FIRE SAFETY CERTIFICATE

Certified that the Fizzaro Collection Pvt Ltd, located at C-53, Okhla Phase-II, New Delhi-110020 comprised of Basement, Ground, plus Three upper floors (3rd floor closed by the management) owned / occupied by Fizzaro Collection Pvt Ltd was issued FSC by this department vide letter No F6/DFS/MS/Industrial/SZ/2017/2367 dated 26/12/2019. The premise was re-inspection by officer concerned by this department on 05/04/2023 in the presence of Mr. Sham Sharma & Mr. Ajay Shrivastava and observed that the premise have deemed complied with the fire prevention and fire safety requirements in accordance with rules 33 of Delhi Fire Service Rules, 2010 and that the premises is fit for (Basement, Ground plus Two Upper Floors only) occupancy class Group "Industrial Building" with effect from 20/04/2023 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhir Fire Service Rules, 2010.

Issued on 20 / 0 11 /2023 at New Delhi by

Copy to: -

- by to:
 1. The Executive Engineer (Bldg) Central Zone, MCD, Jal Vihar, Kajpat Nagar, New Delhi
- 2. Mr. Sham Sharma, (Director) Fizzaro Collection Pvt Ltd, located at C-53, Okhla Phase-II, New Delhi-110020

Conditions for the validity of Fire Safety Certificate: -

- All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the management.
- All the staff members must know the correct method of operation of fire-fighting system.
- The basement shall be used as per the provisions of UBBL-2016.
- The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first Fire Service Rules 2010. schedule of Delhi The form is www dfs delhigovt nie in
- 6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- 7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."
- 8. The 3rd floor of the building is closed it shall be used only after got clearance from Delhi Fire Service and MCD.



INSPECTION REPORT

: Fizzaro Collection Pvt Ltd, at C-53, Okhla Phase-II, New Delhi-110020 1. Name & address of the building

: Industrial "Group-G" 2. Type of Occupancy

: Renewal 3. Type of Case

: Basement + Ground + 3 Upper Floor (3rd Floor Not in use) 4. Comprised of

: F6/DFS/MS/Industrial/SZ/2017/2367 dated 26/12/2019 for B+G+2 5. Details of Previous NOC

: F6/DFS/MS/BP/2001/1168 dated 19/06/2001 6. Fire Safety directives letter No

: 05/04/2023 7. Date of inspection

: DO (South) & ADO (BCP) 8. Name of Inspecting Officer

9. Name and designation of officer

0

· Mr. Sham Sharma & Mr. Ajay Shriyastaya

		no 12230 dated 28/0	Provided at site	Remarks				
S. No.	Minimum Standards on fire prevention	IN A STORAGE VICTOR	Floyided at site	MR/NMF				
	and fire safety U/R 33	Requirement						
1	Access to building	9m	12m	MR				
	Road width	5m	5m	MR				
	Gate width	NA NA	NA.	NA				
	Width of internal road		- Additional					
2.	Number, Width, Type & Arrangement of Exits							
	a. Number of staircases	Three	Four	MR				
	Upper Floors	Three	Four	MR				
	Basements Width of staircases	Three	100	1,111				
	b. Width of staircases	100	2 of 1.56m, one of	MR				
	Upper Floor	1.25m	1.52m & one of 1.5m	MIK				
	Opper rious	1.25m	2 of 1.56m, one of	MR				
	Basements	1.23III	1.52m & one of 1.5m					
	c. Protection of exits							
	Fire check door	Required	Provided	MR				
	Pressurization	NA	NA	NA				
	d. No. of continuous staircases to terrace	Three	Four	MR				
	e. Width of Corridor	NA	NA	NA				
	f. Door Size	1m	1m (final exit)	MR				
3.	Compartmentation	F 1 F 2 F 2 F 2 F 2 F 2 F 2 F 2 F 2 F 2						
) .	The same distriction of the sa	Required	Provided	MR				
	Fire check door Sealing of electrical shafts	Required	Provided	MR				
	Sealing of electrical sharts Fire Rating of shaft door	NA	NA	NA				
	Water Curtain	NA	NA	NA				
	Fire Dampers	NA	NA	NA				
l.	Smoke Management System			111 -1277-1-				
	Basements	30 ACPH	Exhaust Fan Provided	MR				
	Upper floors	12 ACPH	Exhaust Fan Provided	MR				
i.	Fire Extinguishers							
*1	Total numbers	30 No's	36 Nos	MR				
	Types	ISI marked	ABC/W CO ₂ /CO ₂ -	MR				
	IS marking		12/12/12 Nos					
		1	Yes	MR				
	First-Aid Hose Reels	Two	Provided	MR				
	Total numbers on each floor	30m	Provided					
	Length of hose reel hose Newledgemeter	5mm		MR				
	Nozzle diameter		Provided	MR				
•	Automatic fire detection and alarming syste	Smoke & Heat	Provided	MR				
	Type of detectors Location of Main Panel	Oround Ploor	Provided	MR				
	- Location of Main Panel	0	riovided	WIIV				



	•			Elector 1	
	 Location of Repeater Panel 	NA	NA	NA	
	 Alternate source of power 	Required	Provided	MR	
	 Hooters' Location 	Every Floor	Provided	MR	
l.	MOEFA	Required	Provided	MR	
),	Public Address System	NA	NA	NA	
0.	Automatic Sprinkler System				
	Basement	Required	Provided	MR	
	Upper Floors	Required	Provided	MR	
	 Sprinkler above false ceiling 	NA	NA	NA	
11.	Internal Hydrants				
	Size of riser/down-comer	100mm	Provided	MR	
	 Number of hydrants per floor 	Two	Provided	MR	
	Hose Box	Two	Provided	MR	
12.	Yard Hydrants				
	Total number of hydrants	04 Required	Provided	MR	
	Hose Box	04 Required	Provided	MR	
13,	Pumping Arrangements	777777	1.071404	.,,,,	
	Ground Level				
	Discharge of main Pump	2280 LPM	Provided	MR	
	> Head of Main pump	60m	Provided	MR	
	Number of main pumps	One	Provided	MR	
	Jockey Pump out put	180 LPM	Provided	MR	
	Jockey pump head	60m	Provided	MR	
	Standby Pump out put	2280 LPM	Provided	MR	
	Standby Pump Head	60m	Provided	MR	
	Auto Starting/Manual Stopping	Required	Provided	MR	
	> Pump House Access	Required	Provided	MR	
	Terrace level Discharge of purpose				
	 Discharge of pump Head of the pump 	NA	NA	NA	
	> Power Supply	NA NA	NA NA	NA	
	➤ Auto Starting of pump	NA NA	NA NA	NA	
14.	Captive Water Storage for fire fighting	INA	INA	NA	
17.	Underground tank capacity	1,00,000 Lts	1,00,000 Lts	MR	
	> Draw-off connection	Required	Provided	MR	
	Fire service inlet	Required	Provided	MR	
	Access to tank	Required	Provided	MR	
	Overhead Tank capacity	20,000 Lts	Provided	MR	
15.	Exit Signage.	Required	Provided	MR	
16.	Provision of Lifts. (No passenger lift, only one	goods is communicat	ing between basement t	o 2 nd Floor	
- 110	Pressurization of Lift Shaft	NA	NA	NA	
	Pressurization of Lift lobby	NA	NA	NA	
	Communication In lift Car	NA	NA	NA	
	Fireman's Grounding Switch	NA	NA	NA	
	Lift Signage	NA	NA	NA	
17.	Standby power supply	Required	Provided	MR	
18.	Refuge Area.				
. 0.	> Total Area	NA	NA	NA	
	> Location	NA	NA	NA	
19.	Fire Control Room				
•••	Detector System Panel	NA	NA	NA	
	Detector by stem?			The second secon	

Building Floor Plans	NA	NA No LT panels exist. HT is	MR
Batter backup Building Floor Plans			
	NA		NA
PA System Panel	NA		NA NA
	PA System Panel	PA System Panel	PA System Panel NA

The fire protection system provided in the building were randomly checked and found functional at the time of inspection. The 3rd floor of the building is closed it shall be used only after got clearance from Delhi Fire Service and MCD.

Further, the party has complied all the observation / Shortcoming already issued & communicated by this department vide letter of even no 126 dated 20/01/2023.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/Industrial/SZ/2017/2367 dated 26/12/2019, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please

Signature of the Inspection Officer Name: Sh. Manoj Kumar Sharma

Design: DO (South)

Signature of the Inspecting Officer

Name: Sh. Rajesh Kumar Design: ADO (BCP)

CFO (#Q)

1/mg/ 12 41 (2023

Denectar

Mondy F-1

approved, 1-

Jone synature P

tetter in putup

1 / /

1 814