



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001

No.F6/DFS/MS/C-Hall/2023/NDZ/ | 9 |

Dated: 20/04/2023

FIRE SAFETY CERTIFICATE

Certified that the Ideal Palace Community Hall located at Plot No. 32 X-PSP-18, Karkardooma Institutional Area, Delhi-110092, building comprised of basement, ground plus three upper floors, owned/occupied by Ideal Education and Welfare Society was issued FSC vide letter No. F.6/DFS/MS/School/2018/NDZ/943 dated 08/05/18. The premises was inspected by the officer concerned of this department on dated 31/03/2023 in the presence of Mr. Praveen Jain and observed that all the fire prevention and fire safety arrangements provided in the premises found in good working condition. The premises have therefore deemed complied with rule 33 of the Delhi Fire Service Rules, 2010 and observed that the building/premises is fit for occupancy Group D "Assembly" with effect from 20 24 2023 for a period of three years in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010, printed below.

Issued on 20 04 2023 at New Delhi by

DELHI FIRE SERVICE

OIC C

To.

1. Ms. Reena Jain

Plot No. 32 X-PSP-18, Karkardooma Institutional Area, Delhi-110092

2. The Joint Commissioner (Lic.)

1st floor Police Station Defence Colony, New Delhi

MHA ID No. 2023031703780

Conditions for the validity of Fire Safety Certificate

1. All the means of escape shall be kept free of all type of obstruction all the time.

All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.

- All the fire fighting equipment shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.

This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction /unauthorized use of land if any.

 The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

 The owner / occupier shall apply for renewal of this Fire Safety Certificate of the Director in Form 'J' [sub rule (1) of rule (37)] along with a copy of this Certificate, Six Months prior to its expiry.

	22	INSPECTION RI	EPORT					
1.	Name & address of the building	: Ideal Palace Community Hall at 32 X-PSP-18						
2.	Building is comprised of	Karkardooma Institutional Area, Delhi-92 Basement, ground plus three upper floor						
3.	Type of Occupancy	: Commu	nity Hall (Assembly Bi	uildine)				
4.	Type of Case	: Renewa						
5.	Details of Previous NOC letter	F6/DFS/	MS/School/2018/NDZ	/943				
		dated 08	/05/2018					
6.	Fire Safety directive letter No	: F.6/MS/	DFS/BP/2002/2425 Da	ted: 17/12/200				
7.	Date of Inspection	: 31/03/2023 : ADO Deepak Kumar						
8.	Name of the Inspecting officers							
9.	Name and designation of Officer							
	from the building side	: Mr. Pradeep jain						
10.	Year of Construction	: 2002						
11.	Applicant's application No.	: 2023031703780 dated 17/03/2023						
Sr.	Minimum Standards on fire	Directive	Provided at Site	Remarks				
No	prevention and fire safety U/R33	Requirement		MR/NMR				
01	Access to building.							
	 Road width 	12m	18m	MR				
	 Gate width Width of internal road 	4.50m	05m	MR				
02	Number, Width, Type and Arrange	N/A ment of Exits	N/A	N/A				
	a. Number of Staircases							
	Upper Floor	02 nos.	02 nos.	MR				
	 Basement 	02 nos	02 nos. /	MR				
	B. Width of Staircases							
	Upper Floor	1.25m	1.25m & 1.20m /	MR(accepted earlier)				
	Basement	1.25m	1.25m	MR(accepted earlier)				
	Protection of exits Fire check door							
	Pressurization	Required N/A	Provided N/A	MR N/A				
	d. No. of continuous staircases	01 no.	01 no.	MR				
	to terrace e. Width of Corridor	N/A	N/A	N/A				
	f. Door Size	1.50m	1.50m	MR				
03	Compartmentation.							
	Fire check door	Required	Provided	MR				
	 Sealing of electrical shafts 	Required	Sealed	MR				
	 Fire rating of shaft door 	N/A	N/A	N/A				
	Water curtain	N/A N/A	N/A	N/A				
04	Fire Dampers Smoke Management System.	N/A	N/A	N/A				
	Basement	Required	Provided	VID				
	Upper floor	N/A	N/A	MR N/A				
5.	Fire Extinguishers.			14/0				
	Total numbers	08 nos.	10 nos	MR				
	Total numbers types	08 nos. ABC /CO ₂	ABC/CO ₂	MR				

0.70 C

11/18

,	First-aid-Hose Reels.	01	01 no.	MR				
	Total numbers on each floor	01 no.	30m	MR				
	 Length of hose reel hose 	30m	05 mm	MR				
	Nozzle diameter	05 mm	U3 min	IVIIC				
7	Automatic fire detection and alarming system.							
-	Type of detectors	Smoke/Heat	Provided	MR				
	Location of main panel	N/A	Ground Floor	MR				
	Location of repeater panel	N/A	N/A	N/A				
	Alternate source of power	Required	Provided	MR				
	Hooter's location	Staircase	Provided	MR				
8	MOEFA	N/A	Provided	MR				
9	Public address System.	N/A	Provided	MR				
0	Automatic Sprinkler System.							
	Basement	N/A	Provided	MR				
	upper floor	N/A	N/A	N/A				
	sprinkler above false ceiling	N/A	N/A	N/A				
11	Internal Hydrants							
1.12	size of riser/down-comer	100 mm	100 mm	MR				
	Number of hydrants per floor	01 no.	01 no.	MR				
	Hose Box	01 no.	01 no.	MR				
12	Yard Hydrants							
4.70	ALTERNATION OF THE PROPERTY OF	N/A	N/A	N/A				
	Total number of hydrants	N/A	N/A	N/A				
13	Hose Box Pumping Arrangements.	11/71		1				
150	1000 CONTROL OF CONTRO							
	Ground Level Disabases of main Pump	900 LPM	900 LPM /	MR				
	Discharge of main Pump Head of Main Pump	39 m	39 m /	MR				
	Number of main pumps	01 no.	01 no.	MR				
	> Jockey pump out put	N/A	N/A	N/A				
-	> Jockey pump head	N/A	N/A	N/A				
	> Standby pump out put	N/A	N/A	N/A				
	> Standby pump Head	N/A	N/A	N/A				
	> Auto Starting /Manual stopping	Required	Provided	MR				
-	Pump House Access	Required	Provided	MR				
	Terrace Level	require	/	,				
	➤ Discharge of pump	450 LPM	450 LPM	MR				
	➤ Head of the Pump	39 m	39 m	MR				
	> Power supply	Required	Provided	MR				
	> Auto Starting of pump	Required	Auto	MR				
14	Captive Water Storage for Fire Fighting.							
	Underground tank capacity	50,000 Ltr.	50,000 Ltr.	MR				
	 Draw-off connection 	Required	Provided	MR				
	➤ Fire service inlet	Required	Provided	MR				
	Access to tank	Required	Provided	MR				
	Overhead Tank capacity	5,000 Ltr.	5,000 Ltr	MR				
15	Exit Signage	Required	Provided	MR				
16	Provision of Lifts.							
	Pressurization of Lift Shaft	N/A	N/A	N/A				
	 Pressurization of Lift lobby 	N/A	N/A	N/A				
	Communication in lift car	Required	Provided	ME				
	 tiremen's grounding switch 	Required	Provided	ME				
1	Lift Signage	Required	50 9305	MI				



17	Standby power supply	D					
18	Refuge Area	Required	Provided	MR			
	Total area	N/A	N/A	N/A			
19	• Location	N/A	N/A				
	Fire Control Room N/A N/A N/A						
	Detector system and						
	Detector system panel Flow switch panel	Required	Provided	MR			
	Trow switch panel	N/A	N/A	N/A			
	PA system panel	Required	Provided	MR			
	Battery backup	Required	Provided	MR			
_	Building Floor Plans	N/A		-			
20	Special Fire Protection systems for		N/A	N/A			
	protection of special Risks, if any:	N/A	N/A	N/A			

The fire protection systems provided in the building were tested/checked and found functional at the time of inspection. The shortcomings was issued vide letter no. F.6/DFS/MS/2021/NDZ/688 dated 24/03/2021 have been rectified now.

Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules. The FSC vide letter no. F.6/DFS/MS/School/2018/NDZ/943 dated 08/05/18 renewal under rule 35 of the Delhi Fire Service Rule, 2010 is recommended.

Signature of the Inspecting Officer
Name :- Deepak Kumar
Designation :- ADO(Shah.)

DOTED) Submitted for afformal please.

ph cto (MDE)

05/04/2013

10 41 3023

Director Mt 97

04 RD ALASHOOD 13 04/2023

four kind singuature please

utur Please Delle 13/04/202