

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001



No. F.6/DFS/MS/WZ/2023/ | 9 |

Dated: 20 64/2023

FIRE SAFETY CERTIFICATE

Certified that the J.R. Sood & Co. Pvt. Ltd, located at Shivaji Palace, Rajouri Garden, New Delhi-110027 in a mall comprised of 02 Basement + Ground + 04 upper floors was issued FSC vide letter no. F6/DFS/MS/HQ/2020/95 dated 06/02/2020. The premises was inspected by the officers concerned of this department on 24/03/2023 in the presence of Sh. Ashok Yadav and found that the said building have deemed complied with fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire service Rules, 2010 & found that the premises is fit for Mixed occupancy (Class "Assembly & Educational) with effect from 20 54 2023 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010 conditions mentioned below.

Issued on 20 04 2023. at New Delhi by.

Aul Gargi Director

Copy to: -

 The Authorized Signatory, J.R. Sood & Co. Pvt. Ltd, located at Shivaji Palace, Rajouri Garden, New Delhi New Delhi-110027.

Following fire safety directives must be adhered to:-

- All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- The trained staff should be available round the clock.
- Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- Basement shall be used as per building bye laws.
- The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.
- The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.

INSPECTION REPORT

1. Name & address of the building

: J.R. Sood & Co. Pvt. Ltd, Plot No.-10, Shivaji Palace,

Rajouri Garden, New Delhi New Delhi-110027.

2. Type of Occupancy

: Mixed (Assembly & Educational)

Type of Case

: Renewal

4. Details of previous NOC

: F6/DFS/MS/HQ/2020/95 dated 06/02/2020

5. Fire Safety directives letter No

: F6/DFS/MS/BP/2019/3912 dated 03/07/2019

6. Date of inspection

: 24/03/2023

7. Name of the Inspecting Officers : DO (West) & ADO(MN)

8. Name and designation of officers

from the building side

: Sh. Ashok Yadav

9. Year of Construction

: 2007 (As per Prev. insp. report dtd.-27/01/2020)

Applicant's letter No.

: Letter No. Nil, dated 25/02/2023

* The Mall is comprised of 02 Basements + Ground + 04 Upper Floor, was issued FSC by this

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Clause no. 35(6) of l Rules 2010/ As per F insp. report dtd27/01	rev.	at site	Remarks MR/NMR			
1	Access to building							
	 Road width 	24 mts	Provided		MR			
	Gate width	On main Road	Provided		MR			
	Width of internal road	NA	As per control di	rawing	NA			
	Number, Width, Type & Arrangement of Exits							
	a. Number of staircases							
	 Upper Floors 	04	Provided		MR			
	 Basements 	11	Provided		MR			
	b. Width of staircases		Section of the sectio					
	• Upper Floors	1.5 mtr. each	Provided	MR	being old case			
	Basements Protection of exits	1.5 mtr. each	Provided	MR	being old case			
	• Fire check door	P . 1			MR			
	• Pressurization	Required		Provided				
	e. No. of continuous staircases to terrae	Required	Provided					
	f. Width of Corridor	Required	Provided		MR			
	g. Door Size	1.5 mtr.	Provided	MR	being old cas			
		1.2 mtr/1.5mtr	Provided		MR			
-	Compartmentation.							
	Fire check door	Required	Provided		MR			
- 1	 Sealing of electrical shafts 	Required	Provided		MR			
	 Fire Rating of shaft door 	Required	Provided		MR			
	• Water Curtain	Required	Provided		MR			
-	• Fire Dampers	Required	Provided		MR			
-	Smoke Management System.							
	 Basements 	Required	Provided		MR			
-	• Upper floors	Required	Provided		MR			
+	Fire Extinguishers							
	Total numbers	90 nos.	Provided		MR			
	Types	CO2, Wco2 type	Provide	Provided				
	IS marking	ISI marked		Provided				

T	First-Aid Hose Reels.			100		
		04	Provided	MR		
	Total numbers on each floor Total numbers on each floor	30 mm	Provided	MR		
	Length of hose reel hoseNozzle diameter	05 mm	Provided	MR		
7	Type of detectors	Smoke & Heat	Provided	MR MR		
	Location of Main Panel	Required	Provided	MR		
	T of Peneater Panel	Required	Provided Provided	MR		
	Alternate source of power	Required	Provided	MR		
	Hooters' Location	Required	Provided	MR		
0	MOEFA	Required	Provided	MR		
9	Public Address System.	Required				
	Automatic Sprinkler System.		Provided	MR		
10	Basement	Required	Provided	MR		
	Upper Floor	Required	Provided	MR		
	Sprinkler above false ceiling	Required	Tiovidea			
11	Internal Hydrants		Provided	MR		
11	Size of riser/down-comer	150 mm	Provided	MR		
	Number of hydrants per floor	Required	Provided	MR		
	Hose Box	Required				
12	Yard Hydrants.		Provided	MR		
12	Total number of hydrants	04	Provided	MR		
	II Doy	04	Provided			
	Pumping Arrangements.					
13	Ground Level		Provided	MR		
	a: Large of main Pump	4500 lpm		MR		
	. ca (-in numn	70 MH	Provided	The same of the sa		
	Comain numps	02	Provided	MR		
	Number of main pumps	2 X 180 lpm	Provided	MR		
	Jockey Pump out put	70 MH	Provided	MR		
	> Jockey pump head	4500 lpm	Provided	MR		
	Standby Pump out put	70 MH	Provided	MR		
	Standby Pump Head	Required	Provided	MR		
	Auto Starting/ Manual stopping	Required	Provided	MR		
	Pump House Access					
	Terrace level	NA	NA	NA		
	Discharge of pump	NA	NA	NA		
	Head of the pump	NA	NA	NA		
	Power SupplyAuto Starting of pump	NA	NA	NA		
	Auto Starting of party					
14	Captive Water Storage for fire fighti	2,00,000 litres	Provided	MR		
	 Underground tank capacity 	Required	Provided	MR		
	> Draw-off connection	Required	Provided	MR		
	Fire service inlet	Required	Provided	MR		
	Access to tank	20, 000 litres	Provided	MR		
	 Overhead Tank capacity 	Required	Provided	MR		
				1.1		

X

Provision of Lifts. Lift lobby is not required in (2 lifts) being capsule lift							
	Pressurization of Lift Shaft	Required	Provided	MR			
	Pressurization of Lift lobby	Required(Basement ,G.F.4 th floor	Provided	MR			
	 Communication In lift Car Fireman's Grounding Switch Lift Signage 	Required	Provided	MR			
		Required	Provided	MR			
		Required	Provided	MR			
		Required	Provided	MR			
Standby power supply							
	Refuge Area.	NA	NA	NA			
	Total Area Location	NA NA	Provided at 2 nd floor	NA			
	Fire Control Room	Required	Provided	MR			
	Detector System Panel	Required	Provided	MR			
	Flow Switch Panel	Required	Provided	MR			
	PA System Panel	Required	Provided	MR			
	Batter backup	Required	Provided	MR			
	Building Floor Plans	NR	NR	NR			
	Special Fire Protection Systems for Protection of special Risks, if any:		55-4534				

The fire protection systems provided in the building were checked and found functional at the time of inspection. The shortcomings pointed out by this department vide letter dated: 15/02/2023 have been rectified by the management.

In view of the deemed compliance of the minimum standards on fire prevention and fire safety as required under the rules, the NOC issued vide letter No. F6/DFS/MS/HQ/2020/95 dated 06/02/2020, renewal under rule 35 of the Delhi Fire Service Rules 2010, is recommended.

30 03 2023 Signature of the Inspecting Officer

Name: - M. K. Chattopadhyay Designation: - DO (West) Signature of the Inspecting Officer Name: - Sarabjeet Singh

2013/023

Designation: - ADO (MN)

Sto (DPB)

(0)4/mm

1 Tu | 200

Director of 104/2

13/4

ADO (MN)