GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELIII FIRE SERVICE: NEW DELIII- 110001



So. F6/DFS/MS/Hospital/WZ/2023 194

FIRE SAFETY CERTIFICATE

Dated: 21/04/2023

Certified that the M/s. Olmec Health Care LLP, Located at A-1/10, Prashant Vihar, Rohini, Delhi-110085 comprised of Basement + Stilt + Ground + 03 Upper Floors owned / occupied by M/s. Olmec Health Care LLP, was issued Fire Safety Certificate vide Letter No. F6/DFS/MS/Hospital/2020/WZ/201 dated 29.05.2020. The said premise was re-inspected by the officer concerned of this department on 12.04.2023 in the presence of Dr. Sunanda Kaushik (Managing Director) & Sh. Deepak Sahni (Liaison Officer) and found that the building/premises have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010, and that the premises/building is fit for occupancy class "Institutional Building" Group C Sub Division C-1 with effect from 10 1/2 0 1/

Issued on 2104 2023 at New Delhi by.

Director Delhi Fire Service

Copy to: -.

1. The Director General of Health Services Govt. of NCT of Delhi, F-17 Karkardooma, Delhi.

 Dr. Sunanda Kaushik (Managing Director), M/s. Olmec Health Care LLP, A-1/10, Prashant Vihar, Rohini, Delhi-110085.

Following fire safety directives must be adhered to:-

- All the means of escape shall be kept free of all type of obstruction all the time. It should not bolt /locked.
- All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- All the fire fighting equipments shall be maintained in perfect working condition all the time and any loss of life any property due to the non-functional of any fire safety measures, management shall be held responsible.
- Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
- The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
- 6. All comments / directions of building Department shall always be permitted and followed.
- The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.

INSPECTION REPORT

1. Name & address of the building : M/s Olmee Health Care LLP, located at Prashant

Vihar, Rohini Delhi-110085

2. Type of Occupancy : Institutional

: Institutional, B+Stilt+GF+03 UFs (4th floor two rooms no

occupancy)

Type of Case

: Renewal

4. Details of previous NOC

: F6/DFS/MS/Hospital/2020/WZ/201 dated 29.05 2020

5. Fire Safety directives letter No

: F6/DFS/MS/BP/2019/6249 dated 01.08.2019

6. Date of inspection

: 12.04.2023

7. Name of the Inspecting Officers

: Aman Kumar Lathar, ADO (JWP)

8. Name and designation of officers

from the building side

: Dr. Sunanda Kaushik (Managing Director) & Sh. Deepak

Sahni (Liaison Officer)

9. Year of Construction

: NA

i.	Minimum Standards on fire prevention and fire safety U/R 33	NBC Requirement/ as per FSC dated 29.05.2020	Provided at site	Remarks MR/NMR		
	Access to building					
	Road width	Accessible	60 m	MR		
	Gate width	Accessible	Provided	MR		
	Width of internal road	N/A	N/A	N/A		
2	Number, Width, Type & Arrangement of Exits					
_	a. Number of staircases					
	Upper Floors	02	Provided	MR		
	Basements	02	Provided	MR		
	b. Width of staircases					
	Upper Floors	2.0 m x 1 1.5 m x 1	2.0 m x 1 & 1.65 m x 1			
	Basements	2.0 m x 1 1.5 m x 1	2.0 m x 1 & 1.65 m x 1	n MR		
	c. Protection of exits					
	Fire check door	Required	Provided	MR		
	 Pressurization 	N/A	N/A	N/A		
	e. No. of continuous staircases to terrace	02	Provided	MR		
	g. Width of Corridor	2.40 m	2.40 m & 1.5 m	MR		
	h. Door Size	2.0 m & 1.5 m	Provided	MR		
3	Compartmentation.					
	 Fire check door Sealing of electrical shafts Fire Rating of shaft door Water Curtain 	Required	Provided	MR		
		Required	Provided	MR		
		Required	Provided	MR		
		N/A	N/A	N/A		
	Fire Dampers	N/A	N/A	N/A		

(Va

-	Basements	30 a/c per hour	Provided	MR		
	Upper floors	12 a/c per hour	Natural ventilation	MR		
	TORREST COMMENTS OF STREET	12 a/c per nour	Natural ventilation	IVIIX		
5	Fire Extinguishers	10	Provided	MR		
	Total numbers	10 nos.		MR		
	• Types	ABC, CO ₂ type	Provided	MR		
	IS marking	ISI marked	Provided	MIK		
6	First-Aid Hose Reels.					
	 Total numbers on each floor 	01	Provided	MR		
	 Length of hose reel hose 	30 m	Provided	MR		
	Nozzle diameter	5 mm	Provided	MR		
7	Automatic fire detection and alarming system					
	 Type of detectors 	Required	Provided	MR		
	 Location of Main Panel 	G.F	Provided	MR		
	 Location of Repeater Panel 	Required	Provided	MR		
	 Alternate source of power 	Required	Provided	MR		
	Hooters' Location	Required	Provided	MR		
8	MOEFA	Required	Provided	MR		
9	Public Address System.	Required	Provided	MR		
10	Automatic Sprinkler System					
	Basement	Required	Provided	MR		
	 Upper floors 	N/A	N/A	N/A		
	 Sprinkler above false ceiling 	N/A	N/A	N/A		
11	Internal Hydrants					
	Size of riser/down-comer	100 mm wet	Provided	MR		
		riser				
	 Number of hydrants per floor 	01 no each	Provided	MR		
	Hose Box	01 no each	Provided	MR		
12	Yard Hydrants.					
12	 Total number of hydrants 	N/A	N/A	N/A		
1	Hose Box	N/A	N/A	N/A		
13	Pumping Arrangements					
	Ground Level					
į.	 Discharge of main Pump 	1620 lpm	Provided	MR		
	Head of Main pump	60 m	Provided	MR		
	Number of main pumps	01	Provided	MR		
	Jockey Pump out put	180 lpm	Provided	MR		
	> Jockey pump head	60 m	Provided	MR		
	> Standby Pump out put	1620 lpm	Provided	MR		
	 Standby Pump Head Auto Starting/ Manual 	60 m	Provided	MR		
	stopping	Required	Provided	MR		
	> Pump House Access	Required	Provided	MR		
	Terrace level					
	 Discharge of pump 	N/A	N/A	N/A		

		10122				
T	> Power Supply	N/A	N/A	N/A		
	Auto Starting of pump	N/A	N/A	N/A		
Ca	aptive Water Storage for fire fight	ing				
	 Underground tank capacity Draw-off connection Fire service inlet Access to tank 	75,000 ltrs.	Provided	MR		
		Required	Provided	MR		
		Required	Provided	MR		
		Required	Provided	MR		
	Overhead Tank capacity	10,000 ltrs.	Provided	MR		
5 H	Exit Signage.	Required	Provided	MR		
-	Provision of Lifts.					
-	Pressurization of Lift Shaft	N/A	N/A	N/A		
	Pressurization of Lift lobby	N/A	N/A	N/A		
	Communication In lift Car	N/A	N/A	N/A		
	 Fireman's Grounding Switch Lift Signage 	Required	Provided	MR		
		Required	Provided	MR		
17	Standby power supply	Required	Provided	MR		
18	Refuge Area.					
	> Total Area	N/A	N/A	N/A		
	> Location	N/A	N/A	N/A		
19	Fire Control Room					
	Detector System Panel	N/A	N/A	N/A		
	Flow Switch Panel	N/A	N/A	N/A		
	 PA System Panel 	N/A	N/A	N/A		
	Batter backup	N/A	N/A	N/A		
	 Building Floor Plans 	N/A	N/A	N/A		
20	Special Fire Protection Systems for	N/A	N/A	N/A		

Protection of special Risks, if any:

The fire protection systems provided in the building were checked and found functional at the time of inspection.

In view of the deemed compliance of minimum standards on fire prevention and fire safety requirements under the rules, renewal of Fire Safety Certificate issued vide letter no. F6/DFS/MS/Hospital/2020/WZ/201 dated 29.05.2020 is recommended under rule 37 of the Delhi Fire Service Rule, 2010 under DFS Act 2007.

Accordingly DFA is prepared put up for approval please.

20(DPB)

Aman Kumar Lathar ADO (JWP)

19 4 2002 19 4 2012

AMU JOHNS