

e15

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE
NEW DELHI- 110 001

No.F6/DFS/MS/School/2023/SZ/ 270

Dated: 17/04/2023

FIRE SAFETY CERTIFICATE

Certified that the **Vikas Valley Public School, S-11, 12, 13-S-Block, Vikas Nagar, Hastal, New Delhi**, comprised of ground plus two upper floor owned/occupied by Vikas Valley Public School was issued FSC vide letter No. F6/DFS/MS/School/2013/843 dated 28/02/2013 (for G+1). The school building was re-inspected by the officer concerned of this department on 06/04/2023 in the presence of Sh. Sameer Arora (Principal) of the school and found that the building have deemed complied with the fire prevention and fire safety requirements in accordance with Circular F16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01/03/11 issued by Director of Education and the school building is fit for occupancy class "B" 'Educational Building' with effect from 17/04/2023 for a period of **three** years, subject to conditions, printed below.

Issued on.....17/04/2023.....at New Delhi by


(Atul Garg)
Director

Delhi Fire Service


Copy to:-

1. The Manager, Vikas Valley Public School, S-11, 12, 13-S-Block, Vikas Nagar, Hastal, New Delhi.
2. Director of Education, GNCT of Delhi old secretariat, New Delhi-110054.

Following fire safety directives must be adhered to:-

1. All the means of escape shall be kept free of all type of obstruction all the time.
2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.
5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction /unauthorized use of land if any.
6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
7. The owner / occupier shall apply for renewal of this Fire Safety Certificate of the Director in Form 'J' [sub rule (1) of rule (37)] along with a copy of this Certificate, Six Months prior to its expiry.

- M12
1. Name & address of the building : Vikas Valley Public School, S-11, 12, 13-S-Block, Vikas Nagar, Hastal, New Delhi.
 2. Building is comprised of : Ground plus two upper floors.
 3. Type of Occupancy : Educational
 4. Type of Case : Addition/Alteration
 5. Details of Previous FSC letter : F6/DFS/MS/School/2013/843 dated 28/02/2013 *for G+1*
 6. Fire Safety Circular No. : DOE Circular No.F.16/Estate/CC/FS/2011/3298 to 3398 dated-01.03.11
 7. Date of Inspection : 06/04/2023
 8. Name of the Inspecting officers : ADO R.K. Yadav
 9. Name and designation of Officer from the building side : Sh. Sameer Arora (Principal)
 10. Year of Construction : 2010 & 2014
 11. Applicant's letter No : VVPS/04/2023 Dated 14/03/2023

N O.	Minimum Standards on fire prevention and fire safety U/R33	Requirement	Provided at Site	Remarks
1	Access to building	06 Mtrs.	06 Mtrs.	MR
	• Road width	N/A	N/A	N/A
	• Gate width	N/A	N/A	N/A
	• Width of internal road	N/A	N/A	N/A
2	Number, Width, Type and Arrangement of Exits			
	a. Number of Staircases	02 Nos.	02 Nos.	MR
	• Upper Floor	N/A	N/A	N/A
	• Basement			
	B. Width of Staircases	1.5 m	1.5 m & 1.35 M	MR
	• Upper Floor	N/A	N/A	N/A
	• Basement			
	c. Protection of exits	N/A	N/A	N/A
	• Fire check door	N/A	N/A	N/A
	• Pressurization	N/A	N/A	N/A
	e. No. of continuous staircases to terrace	1.5 m	1.80 M	MR
	g. Width of Corridor	1.0 M	1.0 M	MR
	h. Door Size			
	Compartmentation	N/A	N/A	N/A
	• Fire check door	N/A	N/A	N/A
	• Sealing of electrical shafts	N/A	N/A	N/A
	• Fire rating of shaft door	N/A	N/A	N/A
	• Water curtain	N/A	N/A	N/A
	• Fire Dampers	N/A	N/A	N/A
4	Smoke Management System.	N/A	N/A	N/A
	• Basement	N/A	N/A	N/A
	• Upper floor			
5	Fire Extinguishers	06 Nos	06 Nos	MR
	• Total numbers	ABC & Co2	ABC & Co2	MR
	• types	ISI marked	ISI marked	MR
	• IS marking			

ts *h*

Q

6	First-aid-Hose Reels.		Provided	MR
	Total numbers of each floor	2 No.	Provided	MR
	• Length of hose reel hose	30 M	Provided	MR
	• Nozzle diameter	05 MM	Provided	MR
7	Automatic fire detection and alarming system.			
	• Type of detectors	N/A	N/A	N/A
	• Location of main panel	N/A	N/A	N/A
	• Location of repeater panel	N/A	N/A	N/A
	• Alternate source of power	N/A	N/A	N/A
	• Hooter's location	N/A	N/A	N/A
8	MOEFA	N/A	N/A	N/A
9	Public address System.	N/A	N/A	N/A
10	Automatic Sprinkler System.	N/A	N/A	N/A
	• Basement	N/A	N/A	N/A
	• upper floor	N/A	N/A	N/A
	• sprinkler above false ceiling	N/A	N/A	N/A
11	Internal Hydrants	N/A	N/A	N/A
	• size of riser/down-comer	N/A	N/A	N/A
	• Number of hydrants per floor	N/A	N/A	N/A
	• Hose Box	N/A	N/A	N/A
12	Yard Hydrants.	N/A	N/A	N/A
	• Total number of hydrants	N/A	N/A	N/A
	• Hose Box	N/A	N/A	N/A
13	Pumping Arrangements.	N/A	N/A	N/A
	• Ground Level	N/A	N/A	N/A
	➤ Discharge of main Pump	N/A	N/A	N/A
	➤ Head of Main Pump	N/A	N/A	N/A
	➤ Number of main pumps	N/A	N/A	N/A
	➤ Jockey pump out put	N/A	N/A	N/A
	➤ Jockey pump head	N/A	N/A	N/A
	➤ Standby pump out put	N/A	N/A	N/A
	➤ Standby pump Head	N/A	N/A	N/A
	➤ Auto Starting /Manual stopping	N/A	N/A	N/A
	➤ Pump House Access	N/A	N/A	N/A
	• Terrace Level		Provided	MR
	➤ Discharge of pump	450 LPM	Provided	MR
	➤ Head of the Pump	40 M	Provided	MR
	➤ Power supply	Required	Provided	MR
	➤ Auto Starting of pump	Required	Provided	MR
14	Captive Water Storage for Fire Fighting.	N/A	N/A	N/A
	• Underground tank capacity	N/A	N/A	N/A
	➤ Draw-off connection	N/A	N/A	N/A
	➤ Fire service inlet	N/A	N/A	N/A
	➤ Access to tank	N/A	N/A	N/A
	• Overhead Tank capacity	10,000 ltrs	Provided	MR
		Required	Provided	MR
15	Exit Signage.			

[Handwritten signature]

[Handwritten mark]

f6	Provision of Lifts.	N/A	N/A	N/A
	• Pressurization of Lift Shaft	N/A	N/A	N/A
	• Pressurization of Lift lobby	N/A	N/A	N/A
	• Communication in lift car	N/A	N/A	N/A
	• Firemen's grounding switch	N/A	N/A	N/A
	• Lift Signage	N/A	N/A	N/A
17	Standby power supply	N/A	N/A	N/A
18	Refuge Area.	N/A	N/A	N/A
	• Total area	N/A	N/A	N/A
	• Location	N/A	N/A	N/A
19	Fire Control Room	N/A	N/A	N/A
	• Detector system panel	N/A	N/A	N/A
	• Flow switch panel	N/A	N/A	N/A
	• PA system panel	N/A	N/A	N/A
	• Battery backup	N/A	N/A	N/A
	• Building Floor Plans	N/A	N/A	N/A
20	Special Fire Protection systems for protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection. The Shortcomings issued vide letter No.F6/DFS/MS/School/2022/SZ/761 dated 30/05/2022 has been complied.

Keeping in view the substantial compliance of the minimum standards of fire prevention and fire safety measures under Rule 35 of the Delhi Fire Service Rules 2010 it is recommended to grant Fire Safety Certificate.

R. K. Yadav
6/4/2023

Signature of the Inspecting Officer
Name: R. K. Yadav
Designation: ADO (JKP)

DO(SW) *[Signature]*
11/4/23

(FO/S2) *[Signature]*
11/4/2023

Director *[Signature]*
11/04/23

[Signature]