



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

7/5
आज की
अमृत महोत्सव

No. F6/DFS/MS/EH/WZ/2023/ 132

Dated: 26/04/2023

FIRE SAFETY CERTIFICATE

Certified that the M/s. Daryaganj (A unit of Saaj Foods and Hospitality Pvt. Ltd.), Unit No. 11, Second Floor of Pacific Metro Mall comprised of two tier basement, ground plus four upper floors and projection room located at Khayala, Subhash Nagar Metro Station, New Delhi, owned/occupied by Saaj Foods & Hospitality Pvt. Ltd., was granted fire safety certificate vide letter No. F6/DFS/MS/WZ/2020/44 dated 19.02.2020. The premises was re-inspected by the officers concerned of this department on 19.04.2023 in presence of Sh. Kishore (Liaison Manager) and found that the owner have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class- 'D' Assembly (Restaurant only) with effect from 26/04/2023 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed overleaf.

Issued on 26/04/2023 at New Delhi by.

(Atul Garg)
Director

Copy to:-

1. Sh. Tanush Bhalla, M/s. Daryaganj (A unit of Saaj Foods and Hospitality Pvt. Ltd.), Unit No. 11, Second Floor, Pacific Metro Mall, Khayala, between Subhash Nagar Metro Station, New Delhi.
2. The Deputy Health Officer, Delhi Municipal Corporation, West Zone, Rajouri Garden, New Delhi.
3. The Joint Commissioner of Police (Lic), 1st Floor, Police Station Defence Colony, New Delhi- 110024.

INSPECTION REPORT

1. Name & address of the building : M/s. Daryaganj (A unit of Saaj Foods and Hospitality Pvt. Ltd.), located at unit No. 11, Second Floor, Pacific Mall, Khayala, Subhash Nagar Metro Station, Delhi.
2. Type of Occupancy : Assembly (Restaurant)
3. Type of Case : Renewal
4. Details of previous NOC : F6/DFS/MS/WZ/2020/44 dated 19.02.2020
5. Fire Safety directives letter No : N/A
6. Date of inspection : 25.06.2021
7. Name of the Inspecting Officers : DO (West) & ADO (MN)
8. Name and designation of officers from the building side : Sh. Rajnish Verma (Manager)
9. Year of Construction : 2011
10. Applicant's letter No. : ID- 2023032504231

The said restaurant is running at Second Floor of Pacific Metro Mall comprised of 02 tier basements, ground plus four upper floors and projection room.

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Requirement as UBBL / NBC-IV	Provided at site	Remarks MR/NMR
1	Access to building			
	• Road width	12 mts	Provided (60)	MR
	• Gate width	06 mts	Provided	MR
	• Width of internal road	06 mts	Provided	MR
2	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases	-	-	-
	• Upper Floors	02 Nos.	11 Nos. (Provided by Mall)	MR
	• Basements	N/A	N/A	Restaurant running at SF
	b. Width of staircases	-	-	-
	• Upper Floors	1.50 mts each	Provided	MR
	• Basements	N/A	N/A	Restaurant running at SF
	c. Protection of exits	-	-	-
	• Fire check door	N/A	Provided by Mall	---
	• Pressurization	N/A	Provided by Mall	---
	e. No. of continuous staircases to terrace	Required	Provided by Mall	MR
	g. Width of Corridor	N/A	N/A	N/A
	h. Door Size	2.0, 1.5 mts.	2.6 mts x 02, 1.5mts x 01	MR
3	Compartmentation.			
	• Fire check door	N/A	Provided by Mall	---
	• Sealing of electrical shafts	N/A	Provided by Mall	---
	• Fire Rating of shaft door	N/A	Provided by Mall	---
	• Water Curtain	N/A	Provided by Mall	---
	• Fire Dampers	N/A	Provided by Mall	---
4	Smoke Management System.			
	• Basements	N/A	N/A	Restaurant running at SF only
	• ground floor	Provided	Provided	MR

5	Fire Extinguishers			
	<ul style="list-style-type: none">Total numbersTypesIS marking	06 CO ₂ , ABC type ISI marked	Provided	MR
			Provided	MR
			Provided	MR
6	First-Aid Hose Reels.			
	<ul style="list-style-type: none">Total numbers on each floorLength of hose reel hoseNozzle diameter	01 30 m 5 mm	Provided by Mall near restaurant	MR
			Provided	MR
			Provided	MR
7	Automatic fire detection and alarming system.			
	<ul style="list-style-type: none">Type of detectorsLocation of Main PanelLocation of Repeater PanelAlternate source of powerHooters' Location	Smoke & Heat	Provided & connected with Mall	MR
		Required at GF	Provided	MR
		Required	Provided	MR
		Required	Provided by Mall	MR
		Required	Provided in restaurant & Mall	MR
8	MOEFA	Required	Provided in restaurant & Mall	MR
9	Public Address System.	Required	Provided by Mall	MR
10	Automatic Sprinkler System.			
	<ul style="list-style-type: none">BasementEntire RestaurantSprinkler above false ceiling	N/A	Provided by Mall	----
		Required	Provided by Mall	MR
		Required	Provided by Mall	MR
11	Internal Hydrants			
	<ul style="list-style-type: none">Size of riser/down-comerNumber of hydrants per floorHose Box	150 mm	Provided near restaurant & Mall	MR
		01	Provided	MR
		01	Provided	MR
12	Yard Hydrants.			
	<ul style="list-style-type: none">Total number of hydrantsHose Box	N/A	N/A	N/A
		N/A	N/A	N/A
13	Pumping Arrangements.			
	<ul style="list-style-type: none">Ground Level<ul style="list-style-type: none">➤ Discharge of main Pump➤ Head of Main pump➤ Number of main pumps➤ Jockey Pump out put➤ Jockey pump head➤ Standby Pump out put➤ Standby Pump Head➤ Auto Starting/ Manual stopping➤ Pump House AccessTerrace level<ul style="list-style-type: none">➤ Discharge of pump➤ Head of the pump➤ Power Supply➤ Auto Starting of pump	---	---	---
		2850 LPM	Provided by Mall	MR
		60 m	Provided by Mall	MR
		02	Provided by Mall	MR
		180 LPM	Provided by Mall	MR
		60 m	Provided by Mall	MR
		2850 LPM	Provided by Mall	MR
		60 m	Provided by Mall	MR
		Required	Provided by Mall	MR
		Required	Provided by Mall	MR
		-----	-----	-----
		450 LPM	Provided by Mall	MR
		30 mts	Provided by Mall	MR
		Required	Provided by Mall	MR
		Required	Provided by Mall	MR

14	Captive Water Storage for fire fighting.			
	• Underground tank capacity	2,00,000 lts	Provided by Mall	MR
	➤ Draw-off connection	Required	Provided by Mall	MR
	➤ Fire service inlet	Required	Provided by Mall	MR
	➤ Access to tank	Required	Provided by Mall	MR
	• Overhead Tank capacity	30,000 lts	Provided by Mall	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			
	• Pressurization of Lift Shaft	Required	Provided by Mall	MR
	• Pressurization of Lift lobby	Required	Provided by Mall	MR
	• Communication In lift Car	Required	Provided by Mall	MR
	• Fireman's Grounding Switch	Required	Provided by Mall	MR
	• Lift Signage	Required	Provided by Mall	MR
17	Standby power supply	Required	Provided	MR
18	Refuge Area.			
	➤ Total Area	N/A	N/A	N/A
	➤ Location	N/A	N/A	N/A
19	Fire Control Room			
	• Detector System Panel	Required	Provided by Mall	MR
	• Flow Switch Panel	Required	Provided by Mall	MR
	• PA System Panel	Required	Provided by Mall	MR
	• Batter backup	Required	Provided by Mall	MR
	• Building Floor Plans	Required	Provided by Mall	MR
20	Special Fire Protection Systems for Protection of special Risks, if any:	Required	Fire protection system provided in kitchen hood	MR

The fire protection systems provided in the building were randomly test checked and found functional at the time of inspection.

In view of the deemed compliance of minimum standards on fire prevention and fire safety requirements under the rules, renewal of Fire Safety Certificate issued vide letter no. F6/DFS/MS/WZ/2020/44 dated 19.02.2020 is recommended under Rule 37 of the Delhi Fire Service Rules, 2010 under DFS Act 2007.

Accordingly DFA is put up for approval please.

Signature of the Inspecting Officer
Name: - M. K. Chattopadhyay
Designation: - DO (West)

Signature of the Inspecting Officer
Name: - Sarabjeet Singh
Designation: - ADO (MN)

(Signature)
CFO (DPB)

(Signature)
CFO 20/4/2023

(Signature)
20/4/2023

(Signature)
Director 24/4/23

(Signature)
DO (MN)