

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No.F6/DFS/MS/School/2023/ 2 11

Dated: 27/03/2023

FIRE SAFETY CERTIFICATE

Certified that the Nigam Pratibha Vidyalaya located at Bharola Village, Azadpur, Delhi-110033 comprised of Ground & First floor only owned/occupied by Nigam Pratibha Vidyalaya was granted FSC by this department vide letter no. No.F6/DFS/MS/School/2019/2162 dated 15.11.2019. The premises was re-inspected by the officer concerned of this department on 16.03.2023 in presence of Smt. Padmini (Incharge) and observed that all the fire safety arrangements as provided in the premises found in good working condition. The premises have deemed complied with requirements of circular issued by Director of Education vide letter no 3298-3398 dated 01.03.2011 and the building/ premise is fit for occupancy class "Group B Educational" with effect from 2.7/03/2023. for a period of three years, subject to compliance of the conditions mentioned below:

Issued on 27 03 2023 at New Delhi by

Director

Ph.-011-23414000

Copy to: -

The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi - 110054.

2. The Principal, Nigam Pratibha Vidyalaya located at Bharola Village, Azadpur, Delhi-

Conditions for the validity of Fire Safety Certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection.

3. Any loss of life or property due to non-functional fire safety measures shall be at the

4. All the staff members must know the correct method of operation of firefighting system.

5. The owner / occupier shall submit a declaration every year in Form "K" provided in the first Rules http://delhi.gov.in/wps/wcm/connect/doit fire/FIRE/Home/Forms. 2010. The form

6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-

2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any

7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its

NIS

INSPECTION REPORT

1. Name & address of the building : M.C Primary Co-Ed. School at Bharola Village, Azadpur, Delhi-110033.

2. Type of Occupancy : Educational

3. Composition of building : Ground plus first floor only

4. Type of Case : Renewal

5. Details of previous NOC : F6/DFS/MS/School/2019/2162 dated: 15/11/2019

6. Fire Safety directives letter No : Ni

7. Date of inspection : 16.03.2023
8. Name of the Inspecting Officers : ADO (RN)

9. Name and designation of officers

from the building side : Smt. Padmini (Incharge)

10. Year of Construction : 2008

11. Applicant's letter No. : Nil Diary No.001 Dated-02.03.2023

S.No	Minimum Standards on fire prevention and fire safety U/R 33	Director of Edu Circular dated 01 requiremen	.03.2011	Provided at site	Remarks MR/NMF			
l	Access to building							
	Road width	Accessible	Accessible		MR			
	Gate width	Accessible	A	ccessible	MR			
	Width of internal road	NA		NA	NA			
	Number, Width, Type & Arrangement of Exits							
	a. Number of staircases			1,11,116,11-22,1573				
	Upper Floors	02		02	MR			
	Basements							
	b. Width of staircases							
	Upper Floors	1.50 m	1.80	0m &1.90m	MR			
	Basements	NA		NA	NA			
	c. Protection of exits							
	Fire check door	NA		NA	NA			
	Pressurization	NΛ		NA	NA			
	d. No. of continuous staircases to terrace	NA		NA	NA			
	e. Width of Corridor	NA		NA	NA			
	f. Door Size	1 m	1.10m	each double door	MR			
	Compartmentation.							
1	Fire check door	NA		NA	NA			
	Sealing of electrical shafts	NA		NA	NA			
	Fire Rating of shaft door	NA		NA	NA			
	Water Curtain	NA		NA	NA			
	Fire Dampers	NΛ		NA	NA			
	Smoke Management System.							
-	Basements	12 a/c per hour		NA	NA			
	Upper floors	12 a/c per hour	Natura	al Ventilated	MR			
-	Fire Extinguishers			10	MR			
	Total numbers	10nos		10nos	- 317 (12)			
	• Types	ABC/Co2	4240	ABC-10	MR			
	ISI marking	ISI Marked	P	rovided	MR			

ly to e

6	First-Aid Hose Reels.		NA	NA			
	Total numbers on each floor	NA	NA	NA NA			
	Length of hose reel hose	NA	NA				
	Nozzle diameter	NA	NA	NA			
7	Automatic fire detection and alarming system.						
	Type of detectors	NA	NA NA	NA NA			
	Location of Main Panel	NA	NA	NA NA			
	Location of Repeater Panel	NA	NA				
	Alternate source of power	NA	NA	NA			
	Hooters' Location	NA	NA	NA			
_		NA	NA	NA			
8	MOEFA		NA	NA			
9	Public Address System.	NA	NA .				
10	Automatic Sprinkler System.	NIA	NA	NA			
	Basement	NA NA	NA NA	NA			
	Upper Floor	NA	80333				
	Sprinkler above false ceiling	NA	NA	NA			
11	Internal Hydrants.			214			
	Size of riser/down-comer	NA	NA NA	NA NA			
	 Number of hydrants per floor 	NA	NA	1000000			
	Hose Box	NA	NA	NA			
12	Yard Hydrants.						
	Total number of hydrants	NA	NA	NA			
	Hose Box	NA	NA	NA.			
	-						
13	Pumping Arrangements.						
	Ground Level Distance of main Rump	SVA	N/A	N/A			
	 Discharge of main Pump Head of Main pump 	N/A		10/2000			
	 Head of Main pump Number of main pumps 	N/A	N/A	N/A			
	> Jockey Pump out put	N/A	N/A	N/A			
	> Jockey pump head	N/A	N/A	N/A			
	> Standby Pump out put	N/A	N/A	N/A			
	> Standby Pump Head	N/A	N/A	N/A			
	> Auto Starting/ Manual stopping	N/A	N/A	N/A			
	> Pump House Access		1000 to				
	Terrace level	N/A	N/A	N/A			
	 Discharge of pump 						
	> Head of the pump	NΛ	N/A	NA			
	> Power Supply	NA	N/A	NA			
	> Auto Starting of pump	N/A	N/A	N/A			
		N/A	N/A	N/A			
14	Captive Water Storage for fire fighting.						
	Underground tank capacity	NA	NA	NA			
	> Draw-off connection	NA	NA	NA			
	> Fire service inlet	NA NA	NA NA	NA NA			
	> Access to tank	NA NA	NA NA	NA NA			
	500 E45 5-665 20.06900000000	×1.76.5)	224.3				

W

0				214					
-	. NA		N/A	NA					
	Overhead Tank capacity	NA	N/A	NA					
5 Exit Signa	Exit Signage.	,							
6	Provision of Lifts.								
10	Lanco Sciperio and a company of the	N/A	N/A	N/A					
	Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car	N/A	N/A	N/A					
		N/A	N/A	N/A					
	Fireman's Grounding Switch	N/A	N/A	N/A					
	Lift Signage	N/A	N/A	N/A					
	Standby power supply	N/A	N/A	N/A					
17									
18	Refuge Area.								
	> Total Area	N/A		N/A					
	> Location	N/A	N/A						
19	Fire Control Room								
	Contem Panel	N/A	N/A	N/A					
	Detector System Panel Flow Switch Panel	N/A	N/A	N/A					
	PA System Panel	N/A	N/A	N/A					
	Batter backup	N/A	N/A	N/A					
	 Building Floor Plans 	N/A	N/A	N/A					
	Special Fire Protection Systems for	N/A	N/A	N/A					

The fire protection systems provided in the building were tested/ checked randomly and found in good working condition at the time of inspection. The management has complied all the shortcomings issued and communicated by this department vide letter of even no. 725 dated 01.12.2022.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in director of education Circular dated 01.03.2011, it is recommended to renewal of fire safety certificate issued vide this department letter of even no. 2162 dated 15.11.2019.

Signature of the Inspecting Name:-C.L. Meena

Designation:- ADO/RN