

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/2023/ 211

Dated 04 /65 /2023

FIRE SAFETY CERTIFICATE

Certified that the M2K Victoria Gardens (M/s Negolice India Ltd.) located at Ring Road Azadpur, New Delhi comprised of Ground & 02 Upper floors only (Community Centre) owned/ occupied by M2K Victoria Gardens (M/s Negolice India Ltd.) was issued Fire Safety Certificate by this department vide letter no. F6/DFS/MS/CGHS/2020/236 dated 03.07.2020. The premises was re-inspected by the officers concerned of this department on 03.04.2023 in the presence of Mr. Ravi Bhinda have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premise is fit for occupancy class 'D' Assembly (Community Centre) for ground & 02 upper floors only with effect from ... Question of three years in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010

Issued on 04/05/2003 at New Delhi

Director b -0/1-23414000

0/00


Copy to: -

 The Authorized Signatory, M2K Victoria Gardens, (M/s Negolice India Ltd.). Ring Road Azadpur, New Delhi-110033.

Conditions for the validity of Fire Safety Certificate:

- This Fire Safety Certificate is valid only for community centre at ground & 02 upper floors for assembly occupancy only. In case of any violation, this FSC will be treated as null & void.
- 2. All the means of escape/entry/exit shall be kept free from any obstruction.
- All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection.
- Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 5. All the staff members must know the correct method of operation of firefighting system
- The owner / occupier shall submit a declaration every year in Form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on http://delhi.gov.in/wps/wcm/connect/doit fire/FIRE/Home/Forms.
- This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBI -2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

			N/43			
- 9		NSPECT	ION REPORT			
ŧ	Name & address of the building	lice India Lid V-v n	KIN 81 F			
		M2K Victoria Gardens, (M/s Negolice India Ltd.) at Ring Road. Azadpur, New Delhi-110033				
2	Type of Occupancy	Assembly (C	Community Hall)			
3	Type of Case	Renewal				
4	Composition of building	Single block, Ground & 02 upper floors only F6/DFS/MS/CGHS 2020 236 dated 03 07 2020				
5	Details of previous NOC					
6	Fire Safety directives letter No	F 6/DFS/MS	S/BP/2011/1102 dated 03/06/2011 &			
7	Date of inspection	F 6 DFS MS	CGNS/2012/4284 da	te 16/11/2012		
8	Name of the Inspecting Officers	03.04.2023				
9	Name and designation of officers	ADO (RN)				
100	from the building side	### ¥ 1 × \$10 × 721				
10	Year of Construction	Sh Ravi Bhi	nda			
	Applicant's letter No	letter no Nat	A. Target and			
		letter no. Nil. dated 16 03 2023 Dairy No. 12346 Dated 17 03 2023				
	Minimum Standards on fire pres	vention and	NBC/ BBL	Provided at site		
4	fire safety U/R 33		Requirement	. rorace at site	Remarks MR/NMF	
I	Access to building					
1	Read width		45m	45m	MR	
1	Gate width		06m	6 79m		
	 Width of internal road 		06m	SANAWA	MR.	
100	Number, Width, Type & Arrange	ment of Exits	Oom	06m	MR	
1	a Number of staircases					
	 Upper Floors 		02	02	140	
ï	 Basements 		NA.	NA NA	MR	
1				100	NA.	
	b Width of staircases					
	 Upper Floors 		02nos of 1.5m	1 50m each	MR	
1	 Basements 		NA	DESAMO VIENT		
9	c Protection of exits		2013/	NA	NA	
	Fire check door		Required	10		
	 Pressurization 		NA NA	Provided	MR	
	d No of continuous staircases to te	ггасе	02	NA 02	NA	
	TO MICKEY WASTERS			0.29	MR	



-		100 100	District Control	140				
	• Types	ABC & Co2	Provided	MR				
	ISI marking	Yes	Yes	MR				
	First-Aid Hose Reels.							
	Total numbers on each floor	01 community centre	01	MR				
	Length of hose reel hose	30m	30m	MR				
	Nozzle diameter	Smus	Simm	MR				
	Automatic fire detection and alarming system.							
	Type of detectors	Required	Provided	MR				
	Location of Main Panel	GF	Provided	MR				
	 Location of Repeater Panel 	NA NA	NA	NA.				
	Alternate source of power	Required	Provided	MR				
	Hooters' Location	NA	NA	NA				
8	MOEFA	Required	Provided	MR				
9	Public Address System.	Required	Provided	MR				
10	Automatic Sprinkler System.	· · · · · · · · · · · · · · · · · · ·						
	Basement	NA.	NA	NA				
	Upper Floor	Required	Provided	MR				
	Sprinkler above false ceiling	NA	NA	NA.				
H	Internal Hydrants	1.00	1808/	NA.				
***	NAME OF THE OWNER OW			1000				
	Size of riser/down-comer	150mm /100mm	Provided	MR				
	Number of hydrants per floor	community centre 01 each floor	Provided	MR				
	Hose Box	community centre 01	Provided	MR				
12	Yard Hydrants.							
	Total number of hydrants	01	Provided	Mik				
	Hose Box	01	Provided					
13	Pumping Arrangements also connected with	00,00	ALL SALES AND ASSESSED.	MR				
	Pumping Arrangements also connected with M2K Victoria Gardens, (M/s Negolice India Ltd.) fire system as per fire safety directives issued to M2K Victoria Gardens vide letter no. F6/DFS/MS/BP/2011/1102 date 03/06/2011 & F6/DFS/MS/CGNS/2012/4284 date 16/11/2012 • Ground Level							
	Discharge of main Pump	2850 LPM	Provided	MD				
	- Head of Main pump	120m	Provided	MR				
	Number of main pumps	02	Provided	MR				
	Jockey Pump out put	180 LPM	Provided	MR				
	Jockey pump head	120m						
	> Standby Pump out put	1	Provided	MR				
	> Standby Pump Head	Required	Provided	MR				
	Auto Starting/ Manual stopping	Required	Provided	MR				
	 Pump House Access 	Required	Provided	MR				
	Terrace level On the second							
	 Discharge of pump 	450lpm community centre	Provided	MR				
	 Head of the pump 	40m	40m	Mik				
			Provided	6373				
	 Power Supply 	Required	7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	MR				
	 Power Supply Auto Starting of pump 	536000000000000000000000000000000000000	7.5005 (VAPS)					
	➤ Auto Starting of pump	Required	Provided	MR.				
	➤ Auto Starting of pump	536000000000000000000000000000000000000	7.5005 (VAPS)					

	>	Draw-off connection	Required	Provided	MR		
	7	Fire service inlet	Required	Provided	MR		
	>	Access to tank	Required	Provided	MR		
	(6)	Overhead Tank capacity	10,000ltr for community centre	Provided	MR		
15	Exit Signage.		Required	Provided	MR		
16	Provision of Lifts.						
	.00	Pressurization of Lift Shaft	N/A	N/A	NA		
		Pressurization of Lift lobby	N/A	NA	N/A		
		Communication In lift Car	N/A	N/A	N/A		
	ĕ	Fireman's Grounding Switch	Required	Provided	MR		
	•	Lift Signage	Required	Provided	MR		
17	Standby	power supply	Required	Provided DG Set	MR		
18	Refuge	Area.			25555		
	>	Total Area	N/A	N/A	N/A		
	>	Location	N/A	N/A	N/A		
19	Fire Control Room						
	•	Detector System Panel	Required	Provided	MR		
		Flow Switch Panel PA System Panel	Required	Provided	MR		
		Batter backup	Required	Provided	MR		
	/(€)	Building Floor Plans	Required	Provided	MR		
20	Special	Design O	Required	Provided	MR		
- 14	opecial F	re Protection Systems for n of special Risks, if any	NA	NA	NA		

The fire protection systems provided in the building were tested/ checked and found in good working order at the time of inspection.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules. It is recommended to renew Fire Safety vide this department letter of even no 236 dated 03.07.2020. Certificate under rule 37(3) of Delhi Fire Service Rules 2010.

DONW - OH MREST

DO (wet)

Signature of the Inspecting Unit

Name: - C.L. Meena

Designation - ADO/RN

put up o' f'k' form

en)

12/4

Sir As per your direction form 11' KK' affected in File c/120, c/121 11. Resubmitted

104 25 04 2023