



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/EH/NDZ/2023/215

Dated: 04/05/2023

FIRE SAFETY CERTIFICATE

Certified that Somras Bar & Restaurant (Bhavya Infoway Pvt. Ltd.) running at ground floor only located at Shop No. 10A, Ground Floor, Plot No. 01 A, Star City Mall, Mayur Vihar, District Centre Delhi - 110091, building comprised of Basement, Ground & Two upper floors owned / occupied by Somras Bar & Restaurant (Bhavya Infoway Pvt. Ltd.), was earlier issued Fire Safety Certificate by this department vide letter No. F6/DFS/MS/EH/2020/NDZ/84 Dated 09/04/2020. The premises was re-inspected by the officer concerned of this department on 27/04/2023 in the presence of Sh. Ravi Gupta and observed that all the Fire prevention and Fire Safety arrangements provided in the premises found in good working condition. The premises have therefore, deemed complied with rule 33 of the Delhi Fire Service rules, 2010 and that the building / premises is fit for occupancy Class "Assembly" (Group-D) and valid upto 31.03.2026 (**Three years**) in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of conditions under 38 of the Delhi Fire Service rules, 2010.

Issued on 04/05/2023 at New Delhi by


(ATUL GARG)
DIRECTOR
DELHI FIRE SERVICE

Copy to:-

1. Sh. Ravi Gupta, Somras Bar & Restaurant (Bhavya Infoway Pvt. Ltd.), Shop No. 10A, Ground Floor, Plot No. 01 A, Star City Mall, Mayur Vihar, District Centre Delhi - 110091.
2. The Joint Commissioner of Police (Licensing), 1st Floor, Police Station Defence Colony, New Delhi-110024. w.r.t. Online Application ID no. 2022121021245 dated 17/04/2023.

Conditions for the validity of Fire Safety Certificate:

1. All the fire safety arrangement provided there in shall be maintained in good working conditions at all times.
2. Loss of life or property due to non-functional fire safety measure shall be at the responsibility of the Management.
3. The trained fire fighting staff should be available round the clock.
4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
6. Basement shall be used strictly as per Building By-Laws 1983.
7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
8. "The owner / Occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [subrule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
9. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building: Somras Bar & Restaurant (Bhavya Infoway Pvt. Ltd.)
Shop No. 10A, Ground Floor, Plot No. 01 A,
Star City Mall, Mayur Vihar, District Centre,
Delhi - 110091.
2. Building is comprised of : Basement, Ground & Two upper floors,
(Restaurant is running on Ground Floor only).
3. Type of Occupancy : Assembly
4. Type of Case : Renewal
5. Details of previous NOC : F6/DFS/MS/EH/2020/NDZ/84 Dated 09/04/2020
6. Fire Safety directives Letter No.: F6/DFS/MS/BP/2004/1969 Dated 30/08/2004
7. Date of inspection : 27/04/2023
8. Name of the Inspecting Officer : D.O. (E.D.)
9. Name and designation of Officer
from the building side : Sh. Ravi Gupta
10. Year of Construction : 2004
11. Applicant's letter received through MHA portal ID-2022121021245 dated 17/04/2023

S.No.	Minimum Standards on fire prevention and fire safety U/R 33	Requirement	Provided at Site	Remark
1	Access to building			
	• Road width	12 m	13 m ✓	MR
	• Gate width	4.5 m	6.0 m ✓	MR
	• Width of internal road	6.0 m	6.0 m ✓	MR
2	Number, Width, Type and Arrangement of Exits			
	a. Number of Staircases			
	• Upper Floor	N/A	N/A	N/A
	• Basement	N/A	N/A	N/A
	b. Width of Staircases			
	• Upper Floor	N/A	N/A	N/A
	• Basement	N/A	N/A	N/A
	c. Protection of exits			
	• Fire check door	Required in Kitchen	Provided ✓	MR
	• Pressurization			
	d. No. of continuous staircases to terrace	N/A	N/A	N/A
	e. Width of Corridor	N/A	N/A	N/A
	f. Door size	N/A	N/A	N/A
		2.0 m & 1.5 m	2.0 m x 2	MR
3	Compartmentation			
	• Fire check Door	N/A	N/A	N/A
	• Sealing of electrical Shafts	Required	Sealed	MR
	• Fire rating of Shaft Door	N/A	N/A	N/A
	• Water Curtain	N/A	N/A	N/A
	• Fire Dampers	N/A	N/A	N/A
4	Smoke Management System			
	• Basement	N/A	N/A	N/A
	• Upper Floor	Required	Provided	MR
5	Fire Extinguishers			
	• Total Numbers	2 nos.	4 nos. ✓	MR
	• Types	ABC & Co2	ABC & Co2	MR
	• IS Marking	ISI Marked	ISI Marked	MR

[Signature]

80/2

N117

6	First-aid-Hose Reels	01 nos.	01 nos.	MR
	Total numbers of each floor	30 m	30 m	MR
	• Length of hose reel hose	05 mm	05 mm	MR
	• Nozzle diameter			
7	Automatic fire detection and alarming system (Entire mall)			
	• Type of detectors	Heat/Smoke	Provided	MR
	• Location of main panel	Control Room in Basement	Provided	MR
	• Location of repeater panel	Security Room	Provided	MR
	• Alternate source of power	Battery & DG Set	Provided	MR
	• Hooter's Location	Different Location	Provided	MR
8	MOEFA	Required	Provided	MR
9	Public address System	Required	Provided	MR
10	Automatic Sprinkler System			
	• Basement	N/A	N/A	N/A
	• Upper Floor	Required	Provided	MR
	• Sprinkler above false Ceiling	Required	Provided	MR
11	Internal Hydrants	(Entire mall)		
	• Size of rise/down-comer	100 mm	100 mm	MR
	• Number of Hydrants per Floor	01 nos.	01 nos.	MR
	• Hose Box	02 nos.	02 nos.	MR
12	Yard Hydrants			
	• Total number of Hydrants	N/A	01	N/A
	• Hose Box	N/A	01	N/A
13	Pumping Arrangement	(Entire mall)		
	• Terrace Level			
	➤ Discharge of main Pump	4500 LPM	4500 LPM	MR
	➤ Head of Main Pump	50 m	50 m	MR
	➤ Number of main Pumps	02	02	MR
	➤ Jockey pump output	450 LPM	180 LPM	MR
	➤ Jockey pump head	50 m	60 m	MR
	➤ Standby pump output	4500 LPM	4500 LPM	MR
	➤ Standby pump head	50 m	60 m	MR
	➤ Water curtain pump	N/A	N/A	N/A
	➤ Auto starting/Manual stopping	Required	Provided	MR
	➤ Pump house access	Required	Provided	MR
	• Ground Level			
	➤ Discharge of pump	N/A	N/A	N/A
	➤ Head of the pump	N/A	N/A	N/A
	➤ Power supply	N/A	N/A	N/A
	➤ Auto Starting of pump	N/A	N/A	N/A
14	Captive Water Storage for Fire Fighting	(Entire mall)		
	• Underground tank capacity	2,00,000 ltrs	2,00,000 ltrs	MR
	➤ Draw-off connection	Required	Provided	MR
	➤ Fire service inlet	Required	Provided	MR
	➤ Access to tank	N/A	N/A	N/A
	• Overhead Tank capacity	25,000 Ltrs	25,000 ltrs	MR
15	Exit Signage	Required	Provided	MR

SD/

N/18

16	Provision of Lifts			
	• Pressurization of Lift Shaft	N/A	N/A	N/A
	• Pressurization of Lift lobby	N/A	N/A	N/A
	• Communication in lift car	N/A	N/A	N/A
	• Firemen's grounding switch	N/A	N/A	N/A
	• Lift Signage	N/A	N/A	N/A
17	Standby power supply	N/A	N/A	N/A
18	Refuge Area			
	• Total area	N/A	N/A	N/A
	• Location	N/A	N/A	N/A
19	Fire Control Room			
	• Detector system panel	N/A	N/A	N/A
	• Flow switch panel	N/A	N/A	N/A
	• PA system panel	N/A	N/A	N/A
	• Battery backup	N/A	N/A	N/A
	• Building floor plans	N/A	N/A	N/A
20	Special Fire Protection systems for protection of special Risks, if any:	Required	HT & LT Panel protected with local Co2 applications	MR

Note:- Shortcomings issued by this department vide letter No. F6/DFS/MS/2023/NDZ/178 dated 11/04/2023 have been complied.

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, The Fire Safety Certificate issued vide letter no. F6/DFS/MS/EH/2020/NDZ/84 Dated 09/04/2020 renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

Approved
28/04/23

Signature of the Inspecting Officer
Name : A.K. Jaiswal
Designation : DO (ED)

Dy. C.F.O. (NDZ)

Dir
01/05/23

C.F.O.

11/05/2023

Director

11/05/23

DO/ED

F.T. is added for sign. pl.

Director

04/05/2023