Dated: 08 /05 /2023



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/2023/School/302

FIRE SAFETY CERTIFICATE

Certified that the City Montessary School located at 588/2, Pradhan Enclave Marg, Burari, Delhi-110084 comprised of Ground plus 02 upper floors only owned/occupied by City Montessary School was issued Fire Safety Certificated vide this office letter no.F6/DFS/MS/2018/1305 dated 05.06.2018. The premise was re-inspected by the officer concerned of this department on 27.04.2023 in the presence of Mr. Rajesh Kr. Tomar (Principal) and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with Rules 33 of the Delhi Fire Service Rules, 2010 and building premises is fit for occupancy class "Group B Educational" with effect from .08/05.12023.... for a period of three years in accordance with the Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40, subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010,

Issued on 08/05/2023 at New Delhi by

Ph:-011-23414000

Copy to : -

- 1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi 110054.
- The Principal, City Montessary School located at 588/2, Pradhan Enclave Marg, Burari, Delhi-110084.

Conditions for the validity of Fire Safety Certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection.
- Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 4. All the staff members must know the correct method of operation of firefighting system.
- The owner / occupier shall submit a declaration every year in Form "K" provided in the
 first schedule of Delhi Fire Service Rules 2010. The form is available on
 http://delhi.gov.in./wps/wcm/connect/doit fire/FIRE/Home/Forms.
- This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry"

INSPECTION REPORT

Name & address of the building : City Montessary School at 588/2, Pradhan Enclave Marg, Burari, Delhi-84

2. Type of Occupancy Educational

3 Composition of building : Ground + 02 upper floors only

4 Type of Case : Renewal

5. Details of previous NOC : F6/DFS/MS/2018/1305 dated 05/06/2018

Fire Safety directives letter No : Nil

7. Date of inspection : 27.04.2023

8. Name of the Inspecting Officers : ADO (RN)

9. Name and designation of officers

from the building side : Mr. Rajesh Kr. Tomar (Principal)

10. Year of Construction 2005

11. Applicant's letter No. Letter No. Nil dated: 10.04.2023

Minimum Standards on fire prevention a fire safety U/R 33	nd BBU NBC Par Requirement		t site Remarks MR/NMI				
Access to building							
Road width	6m	9m	MR				
Gate width	Directly Accessible	Directly Accessible	MR				
Width of internal road	NA	NA	NA				
Number, Width, Type & Arrangement of Exits							
a. Number of staircases							
Upper Floors	01	03	MR				
Basements	NA NA	NA.	NA.				
b. Width of staircases	15/4	N/A	N/A				
Upper Floors	1.50m	1.55m, 1.28m & 1.18m	MR (Old case)				
Basements	NA	NA	NΛ				
c. Protection of exits							
Fire check door	NA	NA	NA				
Pressurization	NA	NA	NA				
d. No of continuous staircases to terrace	01	01	MR				
e. Width of Corridor	NΛ	NA	NA				
f. Door Size	01m	01m	MR				
Compartmentation,							
Fire check door	NA	NA NA	NA				
Sealing of electrical shafts	NA	NA	NA .				
Fire Rating of shaft door	NA	NA	NA .				
Water Curtain	NA	NA	NA				
Fire Dampers	NA	NA	NA				
Smoke Management System.							
Basements	12 a/c per hour	NA	NA				
Upper floors	12 a/c per hour	Natural Ventilation	MR				
Fire Extinguishers							
Total numbers	031105	Uenos	MR				
• Types	ABC/Co2	ABC-06	MR				
ISI marking	JSI Marked	Yes	MR				



	Cint Aid Hora Deals					
	First-Aid Hose Reels. Total numbers on each floor	01	01	MR		
	Total numbers on each floor Length of hose reel hose	30m	30m	MR		
				1507.20490		
		5mm	5mm	MR		
	Automatic fire detection and alarming system.	NA	NA	NA		
	Type of detectors	NA NA	NA NA	NA		
	Location of Main Panel	NA	NΛ	NΛ		
	Location of Repeater Panel					
	Alternate source of power	NA	NA	NΛ		
	Hooters' Location	NA	NA	NA		
	MOEFA	NΛ	NA	NA		
	Public Address System.	Required	Provided	MR		
	Automatic Sprinkler System.		•			
	Basement	NA	NA	NA		
	Upper Floor	NA	NA	NA		
	Sprinkler above false ceiling	NA	NA	NA		
-	Internal Hydrants					
	Size of riser/down-comer	NA	NA	NΛ		
	Number of hydrants per floor	NA	NΛ	NA		
	Hose Box	NA	NA	NA		
2	Yard Hydrants.					
	Total number of hydrants	NA NA	NA NA	NA NA		
	Hose Box	NA	N/I	3/4		
3	Pumping Arrangements.					
	Ground Level					
	Discharge of main Pump	N/A	NΛ	NA		
	Head of Main pump Number of main pumps	N/A	N/A	NA		
	> Jockey Pump out put	N/A	NA	NΛ		
	Jockey pump head	N/A	N/A	N/A		
	Standby Pump out put	N/A	N/A	· N/A		
	Standby Pump Head	N/A	N/A	NA		
	 Auto Starting/ Manual stopping 					
	 Pump House Access 	N/A	N/A	N A		
	Terrace level	NA NA	NA	NA		
	Discharge of pump	450lpm	450lpm	MR		
	- Head of the pump	40m	40m	MR		
	Power Supply	NA .	NA NA	NA		
1	Auto Starting of pump	NA	NA NA	NA		
	Captive Water Storage for fire fighting	NA	NA	\A		
	 Underground tank capacity Draw-off connection 	STORE	76.76			
	> Fire service inlet	NA NA	NA NA	NA NA		
	> Access to tank	NA NA	NA NA	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\		
	Overhead Lank capacity	10,000ltrs	Provided	MR		
		More Subsuctions 2	W. S. D. & ASSESS.			
-	Exit Signage.	Required	Provided	MR		
5	Provision of Lifts.	han day				

-				
	 Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	NΛ
		N/A	N/A	NA
	Standby power supply	N/A	N/A	NΑ
	100 _ 100 100 100 100 100 100 100 100 10			
	Refuge Area. Total Area	N/A	N/A	N/A
	Location	N/A	N/A	N/A
	Fire Control Room			
	Detector System Panel	N/A	N/A	NA
	Flow Switch Panel	N/A	N/A	N'A
	 PA System Panel 	N/A	N/A	NΛ
	Batter backup	N/A	N/A	NΛ
	Building Floor Plans	N/A	N/A	NΛ
)	Special Fire Protection Systems for Protection of special Risks, if any	N/A	N/A	N A

The fire protection systems provided in the building were tested/ checked randomly and found in good working condition, at the time of inspection.

Keeping in view the satisfactory compliance of the minimum standard on fire prevention and fire safety requirements as stipulated under the circular issued by BBL/NBC Part-IV, the FSC issued vide letter of even no. 1305 dated 05.06.2018 renewal under rule 37 of the Delhi Fire Service Rules, 2010

D. B. MURLEYE 2 57 3023

Directar M 6 7

Director (Offer) 2 2

Signature of the Inspecting Officer Name -C.L. Meena Designation: ADO/RN

As approved FT. letter is burup for your signature lo,

Cut of sel