GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELIII FIRE SERVICE: NEW DELIII- 110001



No.F6/DFS/MS/School/SZ/2023 308

Dated: 08 05 2023

FIRE SAFETY CERTIFICATE

Certified that the MCD Primary School No. 1 located at Devli, Durga Vihar, New Delhi-80, comprised of Ground + 1 upper floor, was granted Fire Safety Certificate (FSC) by this department vide letter no. F6/DFS/MS/School/2017/SZ/1131 dated 28.07.2017. The school building was re-inspected by Assistant Divisional Officer (M. Road) from this department on 24.04.2023 in the presence of Mr. Prem Singh (Principal) and found that the building/premises has deemed complied with the fire prevention and fire safety requirements in accordance with the circular no. 3298 to 3398 dated 01.03.2011 issued by the Directorate of Education and the building (Ground + 1 upper floor) is fit for occupancy of Group B "Educational Building" with effect from \(\text{0.8.} \) \(\text{0.9.} \) \(\text{2.03.} \)... renewed for a period of three years, subject to conditions printed below.

Issued on .. 08/05/2023 ... at New Delhi by.

Delhi Fire Service

Copy to:-.

- The Directorate of Education, Center Zone: Lajpat Nagar, New Delhi-110024.
- 2. The Principal, MCD Primary School No. 1 located at Devli, Durga Vihar, New Delhi-80.

Conditions for the validity of Fire Safety Certificate:-

- The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry
- All the means of escape shall be kept free of all the type of obstruction all the time.
- All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc. may be got verified from the authorities concerned.
- This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.

			ECTION REPORT MCD Primary Scho	ol No. 1 located at	Devli, Durg			
1	Na	ame and address of the building:	Vihar, New Delhi-80					
2	Bu	ilding is comprised of	Ground + 1 upper floo	(Crown B)				
3	1000	pe of occupancy	Educational Building	(Group -b)				
1		pe of case:	Renewal	and and and a	8 07 2017			
		etails of previous FSC:	F6/DFS/MS/School/2	017/SZ/1131 dated 2	0.07.2017			
		re safety directives no.:	F6/Estate/CC/Fire Sal	fety/2011/3298 to 33	70 dated			
1	1		01.03.2011					
,	Da	ite of inspection:	24.04.2023					
3		me of the inspecting officer:	ADO Rajesh Kumar S	Shukla (M. Road)				
)	Na	ame and designation of the officer om the building side:	Mr. Prem Singh (Prin	cipal)				
0		ar of construction:	2008					
1	100	ference letter no.:	Outdoor Diary no. 62:	5 dated 17.04.2023				
		inimum Standards on fire	Requirements	Provide at site	Remarks			
S,No	Pr	evention and fire safety quirements U/R 33	,		MR/NMR			
		cess to Building		Aibla	MR			
	A	Road width	Accessible	Accessible	NA			
	В	Gate width	NA	NA	NA NA			
	C	Width of internal roads	NA	NA	INA			
	Number, Width, Type & Arrangement of Exits							
	A	No. of staircase:						
	^		2 nos.	2 nos.	MR			
		a) Upper floor	NA	NA	NA			
	_	b) Basements						
	В	Width of the staircase: a) Upper floor	1 staircase of 1.5 mtrs	1.80 mtrs & 1.38	MR			
			or if main staircase width is < 1.5 mtrs an additional staircase of 0.75 mtrrs width is required.	mtrs				
		b) Pasaments	NA	NA	NA			
	_	Protection of exits	b) Basements NA					
	C	D. William St. Co. Co. Co. Co. Co. Co. Co. Co. Co. Co	NA	NA	NA			
		a) Fire check door	NA	NA	NA			
		b) Pressurization		1 no.	MR			
	D	No. of continuous staircase to	1 no.		5/8000000			
		terrace:	1.5 mtm	Provided	MR			
	F	Width of the corridor	1.5 mtrs	1.0 mtrs. (for	MR			
	E	Door size	1.0 mtrs. (for class room)	class room)				
3		mpartmentation:	TX1A	NA	NA			
	A	Fire check doors	NA		NA			
	В	Sealing of electrical shafts	NA	NA				
	C	Fire rating of shaft doors	NA	NA	NA			
	D	Water curtain	NA	NA	NA			
	E	Fire dampers	NA	NA	NA			
	Sm	oke Management System:						
	A	Upper floors	NA	NA	NA			
	В	Basements	NA	NA	NA			
-	1000	Extinguishers						
5	-		07 -00	00 ===	MD			
	A	Total numbers	07 nos.	08 nos.	MR			
	В	Types	CO ₂ & ABC	CO ₂ & ABC	MR			
	C	ISI marking	Required	Provided	MR			





+-	_		id Hose reel			
1	-	111 20 20 20	al no. at each floor	NA	NA	NA
1	3	Len	gth of hose reel	NA	NA	NA
(C	Noz	zzle diameter	NA	NA	NA
1	Aut	oma	atic Fire Detection and Alarm Sys	tem (ADAS)	-	
	A	Ту	pe of detectors	NA	NA	NA
	В	Loc	cation of main panel	NA	NA	NA
	C	Lo	cation of repeater panel	NA	NA	NA
	D	Alt	ternate power source	NA	NA	NA
	E	Ho	oter's location	NA	NA	NA
	MOEFA		NA	NA	NA	
	Pu	blic	Address System	NA	Provided	NA
0	and the second of the second o					
	A	Ba	asement	NA	NA	NA
1	В	U	pper floor	NA	NA	NA
	C		prinklers above false ceiling	NA	NA	NA
1	In	_	nal Hydrants		1	1
	A		ize of the riser/down comer	NA	NA	NA
	В	_	o. Of hydrants per floor	NA	NA	NA
	C		lose box	NA	NA	NA
12	Y	ard	Hydrants	1 523.53	11/1	INA
	A	_	otal no. of hydrants	NA	NA	NA
	В	-	lose box	NA	NA	NA
13	P	um	ping Arrangements			
	A		Ground Level			
			a) Discharge of main pump	NA	NA	NA
		-	b) Head of main pump	NA	NA	NA
			c) Number of main pump	NA	NA	NA
			d) Discharge of jockey pump	NA	NA	NA
		+	e) Head of jockey pump	NA	NA	NA
			f) Discharge of standby pump	NA	NA NA	NA
			g) Head of standby pump	NA	NA	NA
		-	h) Auto starting/ manual stopping		NA	NA
		В	Terrace Level	1.02		144
		+	a) Discharge of terrace pump	NA	NA	NA
		+	b) Head of terrace pump	NA	NA NA	NA
		t	c) Alternate power supply	NA	NA NA	NA
		t	d) Auto starting of pump	NA	NA	NA
1	4	Car	ptive Water Storage for Fire Fight	The second of th	1.77	
		A	Underground tank capacity	NA NA	NA	NA
	1	В	Draw off connection	NA	NA	NA
		C	Fire service inlet	NA	NA	NA
		E	Access to tank	NA	NA	NA
		D	Overhead tank capacity	NA	NA	NA
	15	Ex	it Signage	Required	Provided	MR
	16	_	ovision of lift	1202120		1,000
		A	Pressurization of lift shaft	NA	NA	NA
		B	Pressurization of lift lobby	NA	NA	NA
		C	Communication in lift car	NA	NA	NA
		D	Fireman switch	NA	NA	NA
		E	Lift signage	NA	NA	NA
-	17	St	andby Power Supply	NA	NA	NA

MCD Primary School No. 1 located at Devli, Durga Vihar, New Delhi-80

18	Refuge Area						
	A	location	NA	NA	NA		
	В	Total area	NA	NA	NA		
19	Fire Control Room						
	A	Fire detection system panel	NA	NA	NA		
	В	Flow switch panel	NA	NA	NA		
	C	P A system panel	NA	NA	NA		
	D	Battery backup	NA	NA	NA		
	E	Building floor plan	NA	NA	NA		
20	Special Fire Protection for special risk if any						

Meeting Requirement (MR), Not Meeting Requirement (NMR), Not Applicable (NA), Provided But Not Functional (PNF).

The fire protection systems provided in the building were tested checked and found properly functional at the time of inspection.

In view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required in Directorate of Education Circular no. 3298 to 3398 dated 01.03.2011, the FSC issued vide letter no. F6/DFS/MS/School/2017/SZ/1131 dated 28.07.2017 is recommended to be renewed.

Signature of the Inspecting Officer Name Rajesh Kumar Shukla Designation ADO (M. Road)

Director Oceans

Direct