

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001

No. F6/DFS/MS/School/2023/NDZ/313

Dated: 10/05/223

FIRE SAFETY CERTIFICATE

Certified that the Nursery School (Holy Trinity) Building located at I.P. Extn. Mandawali, Fazilpur, Delhi-110092, comprised of basement, stilt, ground plus two upper floors, owned/occupied by Nursery School Building was issued FSC vide letter no. F.6/DFS/MS/School/2017/NDZ/1040 dated 14/07/17. The premises was re-inspected by the officer concerned of fire service on 04/05/2023 in the presence of Mr. Sumit and observed that all the fire prevention and fire safety arrangements provided in the premises found in good working condition. The premises have therefore deemed complied with rule 33 of Delhi Fire Service Rules, 2010 and that the building/premises is fit for occupancy Class "Educational" (Group-B)' valid up to 31/03/2026 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010 & also conditions printed below.

Issued on 10/05/2013 at New Delhi by

DELHI FIRE SERVICE

ox so

To,

The Principal

Nursery School (Holy Trinity) Building located I P. Extn. Mandawali, Fazilpur, Delhi-110092 Copy:-

The Director of Education, MCD 15th Floor, E- Block, Dr. S.P. Mukherjee Civic Center, JLN Marg. New Delhi-110002

Conditions for the validity of Fire Safety Certificate

1. All the means of escape shall be kept free of all type of obstruction all the time.

 All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.

 All the fire fighting equipment shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.

 Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.

 This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction /unauthorized use of land if any.

 The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic in

 The owner / occupier shall apply for renewal of this Fire Safety Certificate of the Director in Form 'J' [sub rule (1) of rule (37)] along with a copy of this Certificate, Six Months prior to its expiry Name & address of the building

Building is comprised of

3 Type of Occupancy

Type of Case

5 Details of Previous NOC letter

6. Fire Safety directive letter No.

7. Date of Inspection

8. Name of the Inspecting officers

Name and designation of Officer from the building side

10. Year of Construction

11. Applicant's letter No

Nursery School (Holy Trinity) Building
I.P. Extn. Mandawali, Fazilpur, Delhi-110092
Basement, Stilt, Ground plus two upper floors

Educational

Renewal F.6/DFS/MS/School/2017/NDZ/1040 dated 14/07/17

F.6/DFS/BP/2012/4392 dated 27/11/12

:04/05/2023

DO, A.K. Jaiswal

: Mr. Sumit

2016

Nil dated 25/04/2023

Sr. No.	Minimum Standards on Fire Prevention and Fire Safety U/R33	NBC Part-IV Requirement	Provided at Site	Remarks MR/NMR			
01	Access to Building						
2000	Donad suidib	06mtr	31.80 mtr	MR			
	Road width	4.50 mtr	4.50 mtr	MR			
	Gate width	N/A	N/A	N/A			
02	Width of internal road N/A N/A						
	a Number of Staircases						
	Upper floor	02 nos	02 nos	MR			
	Basement	N/A	N/A	N/A			
	B. Width of Staircases • Upper floor	1.50 mtr & 1.25 mtr	1.50 mtr & ' 1.25 mtr	MR			
	Basement	1.50 mtr & 1.25 mtr	1.50 mtr & 1.25 mtr	MR			
	c. Protection of Exits			140			
	Fire check door	Required	Provided	MR			
	 Pressurization 	N/A	N/A	N/A			
	d. No. of Continuous Staircases to Terrace	02 nos	02 nos	MR			
	e. Width of Corridor	1.50 mtr.	02 mtr	MR			
	f. Door Size	01 mtr.	01 mtr /	MR			
03	Compartmentation.						
	Fire check door	Required	Provided	MR			
	Sealing of electrical shafts	N/A	N/A	N/A			
	Fire rating of shaft door	N/A	N/A	N/A			
	Water curtain	N/A	N/A	N/A			
	Fire dampers	N/A	N/A	N/A			
04	Smoke Management System						
	Basement	N/A	N/A	N/A			
	Upper floor	N/A	N/A	N/A			
05	Fire Extinguishers						
	Total numbers	08 nos	08 nos	MR			
	Types	ABC /CO2	ABC & CO2	MR			
	IS marking	ISI marked	Provided	MR			

w

)6	First-Aid-Hose Reels.		_				
	Total numbers on each floor	01 nos	01 nos	MR			
	 Length of hose reel hose 	30 mtr	30 mtr	MR			
	 Nozzle diameter 	05 mm	05 mm	MR			
07	Automatic Fire Detection and Alarming System.						
_	Type of detectors	N/A	N/A	N/A			
	 Location of main panel 	N/A	N/A	N/A			
08	 Location of repeater panel 	N/A	N/A	N/A			
	 Alternate source of power 	N/A	N/A	N/A			
	Hooter MOEFA	N/A N/A	N/A N/A	N/A N/A			
					09	Public Address System.	Required
10	Automatic Sprinkler System.						
	Basement	Required	Provided	MR			
	upper floor	N/A	N/A	N/A			
	sprinkler above false ceiling	N/A	N/A	N/A			
11	Internal Hydrants						
	size of riser/down-comer	N/A	N/A	N/A			
	Number of hydrants per floor	N/A	N/A	N/A			
	Hose box	N/A	N/A	N/A			
12	Yard Hydrants.						
	Total number of hydrants	N/A	N/A	N/A			
	Hose box	N/A	N/A	N/A			
13	Pumping Arrangements.						
	> Ground Level						
	Discharge of main pump	N/A	N/A	N/A			
	 Head of main pump 	N/A	N/A	N/A			
	 Number of main pumps 	N/A	N/A	N/A			
	 Jockey pump out put 	N/A	N/A	N/A			
	 Jockey pump head 	N/A	N/A	N/A			
	 Standby pump out put 	N/A	N/A	N/A			
	Standby pump head	N/A	N/A	N/A			
	Auto starting /manual stopping	N/A	N/A	N/A			
	Pump house access Terrace Level	N/A	N/A	N/A			
	33 (USA) 2019 (2019 - 2019 - 2019 - 2019 - 2019 - 2019 - 2019 - 2019 - 2019 - 2019 - 2019 - 2019 - 2019 - 2019		/				
	Discharge of pump	900 lpm	900 lpm ,	MR			
	Head of the pump Royar supply	40 M	40 M	MR			
	Power supply Auto starting of pump	Required	Provided	MR			
	Auto starting of pump	Required	Provided	MR			
14	Captive Water Storage for Fire Fighting.						
	Underground tank capacity	N/A	N/A	A./A			
	Draw-off connection	N/A	N/A N/A	N/A			
	Fire service inlet	N/A	N/A	N/A			
	Access to tank	N/A	N/A	N/A			
	 Overhead tank capacity 	15,000 ltr	15,000 ltr	N/A MR			
5	Exit Signage	Required	Provided	- Mineral C			
	N N N N N N N N N N N N N N N N N N N	required	riovided	MR			



16	Provision of Lifts.						
	Pressurization of lift shaft	N/A	N/A	N/A			
	 Pressurization of lift lobby 	N/A	N/A	N/A			
	 Communication in lift car 	N/A	N/A	N/A			
	 Firemen's grounding switch 	Required	Provided	MR			
	Lift signage	Required	Provided	MR			
17	Standby Power Supply	Required	Provided	MR			
18	Refuge Area						
	Total area	N/A	N/A	N/A			
	Location	N/A	N/A	N/A			
19	Fire Control Room						
	Detector system panel	N/A	N/A	N/A			
	Flow switch panel	N/A	N/A	N/A			
	PA system panel	N/A	N/A	N/A			
	Battery backup	N/A	N/A	N/A			
	Building floor plans	N/A	N/A	N/A			
20	Special Fire Protection Systems for Protection of Special Risks, if Any:	N/A	N/A	N/A			

The Fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Keeping in view of above. The deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules. The NOC / FSC issued vide letter No. F.6/DFS/MS/School/2017/NDZ/1040 dated 14/07/17 renewal under rule 35 of the Delhi Fire Service rules 2010 is may be considered.

Signature of the Inspecting Officer

Name

- A K Jaiswal

Designation

:- D.O (ED)

Dy. (FO (815Z)

CHO

Denetal My 5) on

,

F.T. letter is putupforsig.pd.

DARD OFFICE

L RIVER

W (Director) MJ 5/21

pag