

Dated: 10.10,5.72023

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HQS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No.F.6/DFS/MS/GH/2023/SZ/ 90

FIRE SAFETY CERTIFICATE

Certified that the Guest House in the name & style of THE JK located at A-5, Chittaranjan Park, New Delhi 110019 comprised of Basement (Storage), Stilt (Parking) Ground floor (Rec., Lobby, Pantry & Dinning) 1st to 3rd Floor (05 Guest room each) Total 15 guest rooms owned/occupied by A Unit of JK Associates was issued Fire Safety Certificate by this department vide letter No. F6/DFS/MS/GH/2018/SZ/876 dated 01/05/2018. The premise was re-inspected by the officer concerned of this department on 19/04/2023 in the presence of Mr. Maharaj Rawat and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Residential, Group-A" (Guest House running at 1st to 3rd floor with 15 Guest room) with effect from 04/05/2023 and valid upto 31/03/2026 in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 10 05 /2023 at New Delhi by

DELHI FIRE SERVICE

Copy to: -

opy to:
1. The Addl. Commissioner of Police (Lic.), 1st Floor, P.S. Defence Colony, New Delhi-110049 (Ref. MHA Portal ID 2023021101864 dated 30-03-2023)

Conditions for the validity of Fire Safety Certificate: -

All the means of escape/entry/exit shall be kept free from any obstruction. 1.

- All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- The basement shall be used as per the provisions of BBL /NBC Part- IV. 3.

All the staff members must know the correct method of operation of fire fighting system. 4.

- The owner/occupier shall submit a declaration every year in form 'K' provided in the first 5. schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any
- "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."



1	Name & Address of the Building	INSPECTION REPORT THE JK (A Unit of JK Associator) loc					
2	T	THE JK (A Unit of JK Associates) located at A-5 Chittaranjan Park, New Delhi 110019					
2	Type of Occupancy	Residential, Group 'A' (Guest House)					
4	Building Comprised of	Basement, Stilt, Ground + 03 upper floors					
5	Type of Case	Renewal					
	Details of Previous NOC	F6/DFS/MS/GH/2018/SZ/876 dated 01-05-2018					
7	Fire Safety Directives Letter No	Nil					
8	Date of Inspection	19-04-2023					
9	Name of the Inspecting Officers	ADO (BCP)					
	Name & Designation of Officers from the building side	Mr. Maharaj Rawat					
10	Year of construction	2015 Basement, (storage) Stilt (Parking) Ground F (Rec Lobby, Pantry & Dinning) 1 st Floor to Floor (05 G/Room each) Total 15 G/Rooms			I" Floor to 1		
11	Applicant letter No	MHA Portal ID 2023021101864 dated 30-03-2					
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	Requirements Pr		Provided at Site	Remarks		
1	Access to Building.				MR/NMR		
	Road width	Requ	urml T	00 :			
	Gate width			09 mtr	MR		
	Width of internal road	-NA-		-NA-	-NA-		
2	Number, width, type & arrangement of exits.	-NA-		-NA-	-NA-		
	a) Number of Staircase						
- 1	Upper floors	D					
	> Basement	Required		Provided	MR		
	b) Width of Staircase	Required		Provided	MR		
	 Upper floors 	1.25	mtr	160 0000			
	➢ Basement floor		mtr	1 58 m & 0.90 m	MR		
	c) Protection of exits	1.23	mu	1 60m & 1m	MR		
	Fire check door	-NA-		-NA-			
	Pressurization	-NA-		-NA-	-NA-		
	d) No. of continuous staircase to terrace	Required		02 No	-NA-		
	e) Width of corridor	Required		1.50 mtr	MR		
-	f) Door size	lm		1.60m (final exit)	MR		
3	Compartmentation.			1.00m (marexit)	MR		
	Fire check door.	-NA-		-NA-			
	 Sealing of electrical shafts. 	-NA-		-NA-	-NA-		
	 Fire rating of shaft door 	-NA-		-NA-	-NA-		
	Water curtain	-NA-		-NA-	-NA-		
-	Fire dampers	-N	A-	-NA-			
4	Smoke Management system.	As per clause 7.3		1 of UBBL 2016	-NA-		
	Basement	30 A	CPH	Exhaust fan provided	MD		
	Upper floors		CPH	Exhaust fan provided	MR		
5	Fire Extinguishers.	7		Extraust rain provided	MR		
	Total numbers			14 Nos			
	Types	ISI marked	arked	ABC & CO2	MR		
	ISI Marking		Provided	MR			
6	First Aid Hose Reels.			Flovided	MR		
	Total numbers on each floor	-N	Α-	01 nos	NA		
	 Length of hose-reel hose 	65.516	A-	30 mtr	-NA-		
_	Nozzle Diameter	-NA-		5m	-NA-		
7	Automatic fire detection & alarming system.	As per c	lause 7.31	of UBBL 2016	-NA-		
	Type of detectors	Required Co/Mo Det MR					



	Location of Main Panel	Required	Ground floor	MR
	 Location of Repeater Panel 	-NA-	-NA-	-NA-
	Alternate source of power	Required	Provided	MR
	Hooter's location	Required	Provided	MR
8	MOEFA	-NA-	-NA-	-NA-
9	Public Address System	-NA-	-NA-	-NA-
0	Automatic Sprinkler System			
_	Basement	Required	Provided	MR
	Upper floors	-NA-	-NA-	-NA-
	Sprinkler above false ceiling	-NA-	-NA-	-NA-
1	Internal Hydrants.			
-	Size of Riser/Down-comer	-NA-	-NA-	-NA-
	Number of Hydrant per floor	-NA-	-NA-	-NA-
	Hose box	-NA-	-NA-	-NA-
2	Yard Hydrants.			
_	Total number of hydrants.	-NA-	-NA-	-NA-
	Hose box	-NA-	-NA-	-NA-
3	Pumping arrangements.		2000 (N.Tex)	-
3	Ground Level			
	> Discharge of main pump.	-NA-	-NA-	-NA-
	> Head of main pump	-NA-	-NA-	-NA-
	Number of main pumps	-NA-	-NA-	-NA-
	> Jockey Pump output	-NA-	-NA-	-NA-
	➤ Jockey Pump head	-NA-	-NA-	-NA-
	➤ Standby Pump output.	-NA-	-NA-	-NA-
	> Standby Pump head	-NA-	-NA-	-NA-
	Auto Starting / Manual Stopping.	-NA-	-NA-	-NA-
	Pump house access.	-NA-	-NA-	-NA-
	Terrace Level			
	Discharge of pump	450 LPM	900 LPM	MR
	> Head of pump	26 m	Provided	MR
	➤ Power supply	Required	Provided	MR MR
	> Auto starting of pump.	Required	Provided	MK
14	Captive water storage for fire fighting.	274	-NA-	-NA-
	 Underground tank capacity. 	-NA-	-NA-	-NA-
	> Draw-off connection	-NA-	-NA-	-NA-
	> Fire Service Inlet. > Access to tank.	-NA-	-NA-	-NA-
	Overhead tank capacity.	5,000 ltr	5,000 ltrs	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			
	Pressurization of lift shaft.	-NA-	-NA-	-NA-
	Pressurization of lift lobby	-NA-	-NA-	-NA-
	Communication in lift car.	-NA-	-NA-	-NA-
	Fireman's switch.	Required	Provided	MR MR
	 Lift signage 	Required	Provided	
17	Standby Power Supply	Required	Provided	MR
18	Refuge Area	NA I	-NA-	-NA-
	Total area	-NA-	-NA-	-NA-
	Location	-NA-	-NA-	- NA-
19	Fire Control Room.	N	-NA-	-NA-
	Detector system panel.	-NA-	-NA-	-NA-
	Flow switch panel.	-NA-	-NA-	-NA-
	PA system panel			

*





	Battery backup. Building floor plan.	-NA-	-NA-	-NA-
20	Special Fire Protection System for the Protection of special Risk, if any.	-NA-	-NA-	-NA-

The fire protection system provided in the premises were checked, tested at random and found functional at the time of inspection. The occupancy per floor is equal / less than of 10 person, hence the requirements under clause 7.31 of UBBL is not applicable

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS MS/GH/2018/SZ/876 dated 01-05-2018, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly DFA is put up for approval and signature please.

Signature of the Inspecting Officer Name: - Rajesh Kumar Designation: - ADO/BCP

DO (SP)

Mersh y

Mugh Sorz

Denector

FIP

Anyour

As approved, F.T. Letter -u

Lettree u putup for jone

synature Pol

Directory My n

1/14

W

M21553