## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2023/SZ/ 327

Dated: 18/05/2023

## FIRE SAFETY CERTIFICATE

Certified that the New Gyan Jyoti Public School, Goyla Dairy, Qutab Vihar, New Delhi-110043, comprised of two blocks namely A-Block & B-Block interconnected at each floor level. Each block is having ground floor plus three upper floors, having total 13 rooms in A-Block & 04 rooms in Block-B (including class rooms, staff room, office & store etc.) owned/occupied by New Gyan Jyoti Public School was issued Fire Safety Certificate by this department vide letter no. F.6/DFS/MS/School/2020/SZ/159 dated 23/04/2020. The school building was inspected by the officer concerned of this department on 27/04/2023 in the presence of Sh. Naresh Kumar Gaur (Owner) and found that the School building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule-38 of the Delhi Fire Service Rules, 2010 printed as below.

Issued on 18/05/2023 at New Delhi.

DIRECTOR DELHI FIRE SERVICE

Copy to:-

1. The Manager, New Gyan Jyoti Public School, Goyla Dairy, Qutab Vihar, New Delhi-110043.

Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi - 110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.

3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management

The trained staff should be available round the clock.

- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in

8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

				110				
1			INSPECTIO	N REPORT				
4 5 6 7 8 9	Type of Occ Type of Cas Details of P Fire Safety Date of Ins Name and o	& address of the building ng comprised of Two blocks namely A & B Block Each block having ground plus three upper floors and interconnected at each floor level.  Educational Renewal F 6/DF S/MS/School/2020/SZ/159 dated 23/04/2020 N/A 27/04/20223  of Inspection A D O R K Yadav  Sh. Naresh Kumar Gaur (Owner) 2009-10 (A Block) & Before 2019 (B Block)						
	Applicant's	letter No.		2023/385 dated 25/0	Provided at site	Remarks		
No.	Minimum	Standards on fire pro	evention and	requirement	Provided at site	MR/NMR		
	fire safety			requirement				
	Access to	outlaing			410.000	140		
	• G	oad width ate width /idth of internal road		N/A N/A	Provided Directly accessible from road N/A	MR N/A N/A		
2.	Number,	Number, Width, Type & Arrangement of Exits						
	a. Numbe	er of staircases				140		
	. 1	Upper Floors		02 no 's in A & B	Provided	MR		
	• 1	Basements		N/A	N/A	N/A		
		of staircases Upper Floor		1.50 m	1 65 m, 1 50 m & 1 0 to 1 45 m in A & B blk	MR /		
	• 1	Basements		N/A	N/A	N/A		
	c Protec	tion of exits						
		Fire check door		N/A	NA	N/A		
		Pressurization		N/A	N/A	N/A		
				- Required	Provided	MR		
	11.75	f continuous staircases t	to	1 50 m	2 60 m in each	MR /		
	terrac	n of Corridor			blk			
		room Door Size		1.0 m in A blk & 1.20 m in B blk	1 0 m in A blk & 1 20 m in B blk	MR		
3.	Compar	tmentation						
	. 1	ire check door		N/A	N/A	N/A		
		Sealing of electrical shat		N/A	N/A	NA		
	177.			N/A	N/A	N/A		
		Water Curtain		N/A	N/A	N/A		
		ire Dampers		N/A	N/A	N/A		
4.	Smoke	Management System						
S E	. 1			N/A	N/A	N/A		
		Company of the compan		Required	Natural ventilation provided	MR /		
5.	Fire Ext	Fire Extinguishers						
	- 2	Total numbers on each f	loor	8 no's	Provided	MR		
	•		1 10 1/11	ABC CO <sub>2</sub> type				
		Types		1SI marked	Provided	MR		

h

6.

First-Ald Hose Reels

Total numbers on each floor

Length of hose reel hose

Nozzle diameter



One

30 mtrs

5 mm

Provided

Provided

Provided

MR

MR

MR

	Automatic fire detection and alarming system						
	Type of detectors	N/A	N/A	N/A			
1	Location of Main Panel	N/A	N/A	N/A N/A			
	<ul> <li>Location of Repeater Panel</li> </ul>	N/A	N/A				
	<ul> <li>Alternate source of power</li> </ul>	N/A	N/A	N/A			
	<ul> <li>Hooters' Location</li> </ul>	N/A	N/A	N/A			
	MOEFA	N/A	N/A	N/A			
	Public Address System	N/A	N/A	N/A			
0.	Automatic Sprinkler System						
	Basement	N/A	N/A	N/A			
	Ground Floor	N/A	N/A	N/A			
	Sprinkler above false ceiling	N/A	N/A	N/A			
1.	Internal Hydrants						
	<ul> <li>Size of riser/down-comer</li> </ul>	N/A	N/A	N/A			
	Number of hydrants per floor	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
12.	Yard Hydrants						
	Total number of hydrants	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
13.	Pumping Arrangements	· · · · · · · · · · · · · · · · · · ·					
	Ground Level			200			
	> Discharge of main Pump	N/A	N/A	N/A			
	<ul> <li>Head of Main pump</li> <li>Number of main pumps</li> </ul>	N/A	N/A	N/A			
	> Jockey Pump out put	N/A	N/A	N/A			
	Jockey pump head	N/A	N/A	N/A			
	Standby Pump out put	N/A	N/A	N/A			
	Standby Pump Head	N/A	N/A	N/A			
	<ul> <li>Auto Starting/Manual Stopping</li> </ul>	N/A	N/A	N/A			
		N/A	N/A	N/A			
(-1.5)		N/A	N/A	N/A			
	> Pump House Access	1.7.7		3,501			
	Terrace level	450 LPM	Provided	MR			
	<ul> <li>Discharge of pump</li> <li>Head of the pump</li> </ul>	30 mtrs	Provided	MR			
	> Power Supply	Required	Provided	MR			
	<ul> <li>Auto Starting of pump</li> </ul>	Required	Provided	MR			
14.	Captive Water Storage for fire fighting						
	Lindarmound took canacity	N/A	N/A	N/A			
	<ul> <li>Underground tank capacity</li> <li>Draw-off connection</li> </ul>	N/A	N/A	N/A			
	Fire service inlet	N/A	N/A	N/A			
	> Access to tank		N/A N/A	N/A			
	Overhead Tank capacity	N/A	The second secon				
		10000 ltrs	Provided Provided	MR MR			
15.	Exit Signage.	Required					
16.	Provision of Lifts.	No Lift					
	Pressurization of Lift Shaft	N/A	N/A	N/A			
	Pressurization of Lift lobby	N/A	N/A	N/A			
	Communication In lift Car     Grounding Switch	N/A	N/A	N/A			
	Fireman's Grounding Switch     Lift Signance	N/A	N/A	N/A			
	Lift Signage	N/A	N/A	N/A			
17.	Standby power supply	N/A	N/A	N/A			
18.	Refuge Area.  > Total Area	N/A	N/A	N/A			
		\$11.15 A 18 A	CONT. 1550	0.0000			
	Location	N/A	N/A	N/A			

5

b	Fire Control Room						
		Detector System Panel	N/A	N/A	N/A		
		Flow Switch Panel	N/A	N/A	N/A		
		PA System Panel	N/A	N/A	N/A		
		Battery backup Building Floor Plans	N/A	N/A	N/A		
	- 49		N/A	N/A	N/A		
	Special of speci	Fire Protection System for Protection al Risks, if any:	N/A	N/A	N/A		

The fire protection systems provided in the building were tested, checked and found

functional at the time of inspection.

20.

Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules the FSC issued vide letter No. F.6/DFS/MS/School/2020/SZ/159 dated 32/04/2020 renewal under the Rule 37 of the Delhi Fire Service Rules 2010 is recommended.

Signature of Inspecting Off

Name - R.K. Yadav

Designation - Asstt. Divisional Officer

Divisional Officer (South West)

As directed detail of school building in

9/6/2 Heedful done A.