

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE NEW DELHI-110001

No: F.6/DFS/MS/School/WZ/2023/359

Dated: 26 1 05 /2023

FIRE SAFETY CERTIFICATE

Certified that the Hansraj Model School, located at Road No-73, Punjabi Bagh, New Delhi-110026, In a building comprised of 03 blocks, Main Block & Yoga block is comprised of basement, ground plus three upper floors, Auditorium block is comprised of Basement, & First floor, and Primary Block is comprised of ground plus two upper floors, Owned/occupied by Hansraj Model School, was issued FSC vide letter No. F6/DFS/MS/School/2020/21 dated 24/01/2020. The premises was re- inspected by the officer concerned by this department on 09/05/2023 in the presence of Sh. Shakeel Ahmad and found that the premises/building have deemed complied with the fire prevention and fire safety requirements in accordance with the circular issued by DOE Circular No.- 3298-3398/ NBC Part -IV and that the premises is fit for occupancy class "Educational" Group-B, with effect from .26./05/2023...for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to the compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010 Condition mentioned below.

Issued on .26./05/2023, at New Delhi.

Copy to: -

The Principal M/s. Hansraj Model School, at Road No-73, Punjabi Bagh, New 1. Delhi-110026.

Director of Education, Old Secretariat, New Delhi-110054. Following fire safety directives must be adhered to:-

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.

2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.

3. The trained staff should be available round the clock.

4. Basement shall be used as per building by laws.

5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.

6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

7. The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.

8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on

www.dfs.delhigovt.nic.in.

9. Alternate exit opened at second floor terrace in science block shall not be closed, if it is closed the FSC/NOC will be null & void.

-		-		ION REP				
51	Name	& address of the building		Model Sc elhi-11002		ted at Road No-73, P	unjabi E	Bagh
2.	2. Type of Occupancy			onal				
			Renewa	al				
0			F6/DFS	S/MS/WZ/S	School/20	20/21 dated 24/01/20	20	
4.	Details of previous NOC F6/DFS/MS/WZ/School/2020/21 dated 24/01/2020 Fire Safety directives letter No DOE Circular No3298-3398 dated 01/03/2011							
			09/05/2	22.22.10				
_		of inspection	**********		DO A OD			
	Name of the Inspecting Officers Sarabjeet Singh ADO (MN) Name and designation of officers from the building side							
9.		f Construction	1981 (/	As per prev	inspection	on report dtd 08/01/	2020)	
10	Amalia	ant's letter No. mplex is having 03 block	Email o	dated -26/0	4/2023			
Prim S. No	Minin	ck is comprised of ground num Standards on fire ention and fire safety U/R 33	3398 dat	ircular No ted 01/03/2 inspection. 08/01/20	3296- .011/ As n report	Provided at site	Rema MR/N	
I	Access to building			- 100 Sec.		Provided	MR	
		Road width	-	6 m		Provided	MR	
	•	Gate width		4.5 m		NA	NA	
	•			NA		NA I	.4.350	
2	Numi	oer, Width, Type & Arran	gement	of Exits				
	(S) (A) T (A) (A)	a. Number of staircases • Upper Floors		& primary to 2		in Block & Yoga Block-04 up o 2 nd floor, 01 up to 3 rd floor liternate exit open at 2 nd floor terrace), Primary Block-03		ИR
	1	NE	+	NA		NA	1	NA
		Basements	-	TWV.			T	Pina
		dth of staircases Upper Floors		1.5 mts	.5 mts Main Block & Yoga Bloc 1 44,1 42,1 38,1 29 mts, Prima Block-1 70,1 27 & 1.23 mts			William The Park
		Basements		1.5 mts	1.65,1.16	Main Block & Yoga Bloc 1 65,1 16,mts, Primary Block-1 : & 0 89 mts		
	c. Pro	tection of exits		none was a Fill	basament	Provided	I N	MR
	*****/*****	Fire check door	-	Required in	basement	NA	1	NA
				NA 01		01 Provided	1	ИR
	e. No	of continuous staircases to te	rrace	1 5m Requ	ired	Provided		MR
	f. Width of Corridor g. Door Size			1 mtr class r 1.5 mts (A	rooms, Provided		ı	MR
6		partmentation.					N/	
3	-			NA		NA NA	N/	10.00
	•	a Una of electrical shaft	ts	NA		NA NA	N/	
		re paing of shaft door	ii	NA		NA NA	N/	
		Water Curtain Fire Dampers		NA NA		NA NA	N/	100
		18/75302						SHI



11	ı,	-
101	٧.	v

4	Smoke Management System.	/		William Co.		
-		Rec	uired	Provided		MR
	Basements		uired	Natural ventilation	n	MR
_	Upper floors	1100				
5	Fire Extinguishers		50	Provided		MR
	Total numbers				-	MR
	• Types	CO ₂ , AI ISI mar		Provided	-	
	IS marking	151 mar	keu	Provided	11 1	MR
6	First-Aid Hose Reels.				1	_
	Total numbers on each floor	Requi	red 02	Provided	11 1	MR
	Length of hose reel hose	30	m	Provided	N	иR
	Nozzle diameter	5n	nm	Provided	N	ИR
7	Automatic fire detection and alarm	lng system		The Continue of the		
	Type of detectors	N N	A	NA	II N	IA
	Location of Main Panel	N		NA		IA
	Location of Repeater Panel	N.		NA NA		A
	Alternate source of power	N.		NA NA	N	TATAL STREET
	Hooters' Location	N.		NA	N.	10,000
8	MOEFA	Requ	-	Provided	M	
9	Public Address System.	Requ		Provided		
0	Automatic Sprinkler System.		neu	Tiovided	M	K
200	Basement	D.		P 11 1		
	Upper Floor	Requ		Provided	MI	
	Sprinkler above false ceiling	N/		NA	N/	
1	Internal Hydrants					
	Size of riser/down-comer	T		and the same	50	
	Number of hydrants per floor	Requi	red	Provided	MR	1
	Hose Box	02		Provided	MR	1
2	Yard Hydrants.	02		Provided	MR	t
	Total number of hydrants	1				
	Hose Box	NR.		Provided	NR	
3	Pumping Arrangements.	NR		Provided	NR	_
Ca. I	The Control of the Co					
	Ground Level Discharge of main Page			4		_
	Discharge of main Pump Head of Main pump	NA		NA	T NA	_
2	> Number of main pumps	NA		NA	NA	
1	> Jockey Pump out put	NA NA		NA	NA	
	> Jockey pump head	NA NA	-	NA	NA	
	Standby Pump out put	NA NA	-	NA	NA	
	> Standby Pump Head	NA		NA	NA	-
	Auto Starting/ Manual stopping	NA	-	NA	NA	
	> Pump House Access	NA	-	NA	NA	
	Terrace level			NA	NA	
	➤ Discharge of pump	900 & 180	Main Di	in the state of th		
		lpm	Block-900	ock& Yoga Block and Au & 180 lpm, Primary Blo	di.	-
1	> Head of the pump	1000	4501	Dill Provided	ck- M	R
	Power Supply	40 m		Provided		-
	> Auto Starting of pump	Required Required		Provided	MI	_
-		Real		Provided	MI	

		W/39					
14	Captive Water Storage for fire fighting.						
-	Underground tank capacity	NA	NA	NA			
	> Draw-off connection	NA	NA	NA			
	> Fire service inlet	Required	NA	MR			
	Access to tank Overhead Tank capacity	NA	Provided	NA			
		15,000 ltrs	Main Block & Yoga Block and Audi. Block-15,000 ltrs, Primary Block- 10,000 ltrs provided	MR			
15	Exit Signage.	Required	Provided	MR			
16	Provision of Lifts.						
	Pressurization of Lift Shaft	NA	NA	NA			
	Pressurization of Lift lobby	NA	NA	NA			
	Communication In lift Car	NA	NA	NA			
	 Fireman's Grounding Switch 	NA	NA	NA			
	Lift Signage	NA	NA	NA			
17	Standby power supply	NA	NA	NA			
18	Refuge Area.						
	> Total Area	NA	NA	NA			
	> Location	NA	NA	NA			
19	Fire Control Room						
	Detector System Panel	NA	NA	NA			
	Flow Switch Panel	NA	NA	NA			
	PA System Panel	NA	NA	NA			
	Batter backup	NA	NA	NA			
	 Building Floor Plans 	NA	NA	NA			
20	Special Fire Protection Systems for Protection of special Risks, if any:	Required 02 ABC type fire extinguishers near elect. Pannel	Provided	MR			

The fire protection systems provided in the building were checked and found functional at the time of inspection. All the shortcomings issued by this department have been compiled by the management of school.

In view of the deemed compliance of minimum standards on fire prevention and fire safety as required under the rules the NOC issued vide letter no.F6/DFS/MS/School/2020/21 dated 24/01/2020 renewal under DOE Circular no. F16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01/03/2011 issued by Directorate of Education, Govt. OF NCT of Delhi, is recommended.

Signature of the Inspecting Officer

Name: - Sarabjeet Singh Designation: - ADO (MN)

DO (WEST)/908 DATED/9/05/2023

Directed Hings

Agym