



FORM 'H': FORM FOR ISSUING FIRE SAFETY CERTIFICATE

[See sub-rule (1) of rule 35]

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

75
आजादी का
अमृत महोत्सव

No. F6/DFS/MS/2023/NDZ/ 267

Dated: 01/06/2023

FIRE SAFETY CERTIFICATE

Certified that the Prime Honda Capital Pvt. Ltd. located at Plot No. 01, Patparganj Ind. Complex (Near Mother Dairy), Delhi-110092, comprised of Basement, Ground Floor & 1st Floor only owned / occupied by Prime Honda Capital Pvt. Ltd. has already been issued FSC by this department vide letter No. F6/DFS/MS/Indl./2020/NDZ/348 dated 07/09/2020. The premises was re-inspected by the officers concerned of this department on 22.05.2023 in the presence of Mr. Amrish Tyagi and found that building / premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building / premises is fit for occupancy class **Industrial Group (G)** and valid up to 31/03/2026 (Three Years) in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010.

Issued on 01/06/2023 **at New Delhi by.**

(ATUL GARG)
DIRECTOR

DELHI FIRE SERVICE.

O/c @

Copy to :-

1. Authorized Signatory, Prime Honda Capital Pvt. Ltd., Plot No. 01, Patparganj Ind. Complex (Near Mother Dairy), Delhi-110092.

Conditions for the validity of Fire Safety Certificate:

1. All the fire safety arrangement provided their in shall be maintained in good working conditions at all times.
2. Loss of life or property due to non-functional fire safety measure shall be at the responsibility of the management.
3. The trained fire fighting staff should be available round the clock.
4. Any deviation with regard to the construction etc. shall be verified by the concerned building sanctioning agency.
5. Basement shall be used strictly as per Building-By-Laws.
6. This certificate cannot be treated in any case for regularizations of unauthorized construction.
7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
8. "The owner / Occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule37] along with a copy of this Certificate, six months prior to its expiry".

INSPECTION REPORT

N/23

1. Name & address of the building : Prime Honda Capital Pvt. Ltd. Plot No. 01, Patparganj Ind. Complex (Near Mother Dairy), Delhi-110092
2. Building is comprised of : Basement, Ground & one upper floor only
3. Type of Occupancy : Industrial Building
4. Type of Case : Renewal (Showroom)
5. Details of previous NOC : F6/DFS/MS/Ind1/2020/NDZ/348 dated 07/09/2020
6. Fire Safety directives Letter No : NBC (Part-IV)
7. Date of inspection : 22/05/2023
8. Name of the Inspecting Officer : Yashwant Singh Meena, ADO(LN) & A K Jaiswal D.O (ED)
9. Name and designation of Officer from the building side : Mr. Amrish Tyagi
10. Year of Construction : 2009-2013
11. Applicant's email dated : 19/05/2023

S No	Minimum standards on fire prevention and fire safety U/R 33	Directive Requirements	Provided at site	Remarks MR/NMR
1.	Access of building			
	• Road width	12 mtr	12 m	MR
	• Gate width	05 mtr	05 mtr	MR
	• Width of internal road	5.50 mtr	5.50 mtr	MR
2.	Number, width, Type & Arrangements of exits			
	a. Number of staircases			
	• Upper floors	2	2	MR
	• Basements	2	3	MR
	b. Width of staircases			
	• Upper floors	1.25 mtr	1.25 mtr & 1.18 mtr	MR
	• Basements	1.25 mtr	1.25m, 1.18m & 1.20 m	MR
	c. Protection of exits			
	• Fire check door	Required	Provided	MR
	• Pressurization	N/A	N/A	N/A
	d. No of continuous staircase to terrace	2	2	MR
	e. Width Of Corridor	N/A	N/A	N/A
	f. Door Size	1 mtr	1 mtr	MR
3.	Compartmentation			
	• Fire check door	Required	Provided	MR
	• Sealing of electrical shafts	Required	Provided	MR
	• Fire Rating of shaft door	N/A	N/A	N/A
	• Water Curtain	Required	Provided	MR
	• Fire Dampers	N/A	N/A	N/A
4.	Smoke managements System			
	• Basements	Required	Provided	MR
	• Upper floors	Required	Provided	MR
5.	Fire Extinguishers			
	• Total numbers	15	18	MR
	• Types	ISI marked ABC/CO ₂ /WCO ₂	Provided	MR
	• IS marking	Required	Provided	MR

(1)

N/24

6.	First – Aid Hose Reels			
	• Total numbers on each floor	1	1	MR
	• Length of hose reel hose	30Mtr.	30Mtr.	MR
	• Nozzle diameter	5mm.	5mm.	MR
7.	Automatic fire detection and alarming system			
	• Type of detector	Smoke / Heat	Provided	MR
	• Location of Main Panel	Ground Floor	Provided	MR
	• Location of Repeater Panel	Ground Floor	Provided	MR
	• Alternate source of power	Battery & DG set	Provided	MR
	• Hooters' Location	Different Location	Provided	MR
8.	MOEFA	Required	Provided	MR
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System			
	• Basements	Required	Provided	MR
	• Upper Floor	Required	Provided	MR
	• Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants			
	• Size of riser/down-comer	100 mm	Provided	MR
	• Number of hydrants per floor	1	Provided	MR
	• Hose Box	1	Provided	MR
12.	Yard Hydrants			
	• Total number of hydrants	2	2	MR
	• Hose Box	2	2	MR
13.	Pumping Arrangements			
	• Ground Level			
	• Discharge of main pump	2280 LPM	Provided	MR
	> Head of main pump	40 m	Provided	MR
	> Number of main pumps	1	Provided	MR
	> Jockey pump out put	180 LPM	Provided	MR
	> Jockey pump head	40 M	Provided	MR
	> Standby Pump out put	2280 LPM	Provided	MR
	> Standby Pump Head	40 M	Provided	MR
	> Auto Staring/Manual stopping	Auto	Provided	MR
	> Pump House Access	Required	Provided	MR
	• Terrace level			
	> Discharge of pump	900 LPM	Provided	MR
	> Head of the pump	40 m	Provided	MR
	> Power supply	Required	Provided	MR
	> Auto starting of pump	Required	Provided	MR
14.	Captive water Storage for fire fighting			
	• Underground tank capacity	1,00,000 lts.	Provided	MR
	> Draw of connection	Required	Provided	MR
	> Fire service inlet	Required	Provided	MR
	> Access to tank	Required	Provided	MR
	• Overhead Tank capacity	20,000 ltr	20,000 ltr	MR


Handwritten marks: a circled 'u' and a signature.


N/25


15	Exit Signage	Required	Provided	M/R
16.	Provision of Lifts	Only car lift is existing		
	➤ Pressurization of Lift Shaft	N/A	N/A	N/A
	➤ Pressurization of lift lobby	N/A	N/A	N/A
	➤ Communication in lift Car	N/A	N/A	N/A
	➤ Fireman's Grounding Switch	N/A	N/A	N/A
	➤ Lift Signage	N/A	N/A	N/A
17.	Standby power supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	➤ Total area	N/A	N/A	N/A
	➤ Location	N/A	N/A	N/A
19.	Fire control room			
	➤ Detector system panel	Required	Provided	MR
	➤ Flow Switch Panel	N/A	N/A	N/A
	➤ PA System Panel	N/A	N/A	N/A
	➤ Battery backup	N/A	N/A	N/A
	➤ Building Floor Plans	N/A	N/A	N/A
20.	Special Fire Protection Systems for Protection of special Risks, if any;	N/A	N/A	N/A


The fire protection systems provided in the building were tested, checked and found functional at the time of inspection. MCB and Conduit Metal Wiring has also been provided.


In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter No. N/F6/DFS/MS/Indl./2020/NDZ/348 dated 07/09/2020 renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.


 Signature of the Inspecting Officer
 Name : Yashwant Singh Meena
 Designation : A.D.O. (LN)


 Signature of the Inspecting Officer
 Name : Ashok Kumar Jaiswal
 Designation : D.O. (East Div.)

Dy. CFO (NDZ) 
 26/05/23

C.F.O. 
 26/5/2023

Director 
 29/5/23




 29/5

ADD (LN)


 31/5

P.T.O.