



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/EH/WZ/2023/166

Dated: 30/05/2023

FIRE SAFETY CERTIFICATE

Certified that M/s. Haldiram Products Pvt. Ltd. running at Anchor No.- 03, 19 & 20, Ground Floor only in D Mall building comprised of 03 tier basement, ground plus twelve upper floors, located at D Mall, Netaji Subhash Place, Pitampura, New Delhi- 110034, owned/occupied by M/s. Haldiram Products Pvt. Ltd., was granted fire safety certificate vide letter No. F6/DFS/MS/WZ/2020/68 dated 06.03.2020. The premises was re-inspected by the officer concerned of this department on 25.05.2023 in the presence of Sh. Deepak Kumar (manager) and observed that the management have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class- "Assembly" Group-D (Restaurant at Ground Floor only) with effect from 30/05/2023 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed overleaf.

Issued on 30/05/2023 at New Delhi by.

(Atul Garg)
Director

Copy to:-

1. The Owner / Occupier, M/s. Haldiram Products Pvt. Ltd. Anchor No.- 03, 19 & 20, Ground Floor, D Mall, Netaji Subhash Place, Pitampura, New Delhi- 110034.
2. The Dy. Health Officer, MCD, Keshavpuram Zone, Public Health Department, New Delhi.
3. The Joint Commissioner of Police (Lic.), Police Station Defence Colony, First floor, New Delhi.

INSPECTION REPORT

1. Name & address of the building : M/s. Haldiram Products Ltd. Ltd., Anchor No. 03, 19, 20, Ground Floor, D Mall, Netaji Subhash Place, Pitampura, New Delhi- 110034.
2. Type of Occupancy : Assembly (Restaurant)
3. Type of Case : Renewal
4. Details of previous NOC : F6/DFS/MS/WZ/2020/68 dated 16.03.2020
5. Fire Safety directives letter No : N/A
6. Date of inspection : 25.05.2023
7. Name of the Inspecting Officers : Sh. M.K. Chattopadhyay, Divisional Officer (West)
8. Name and designation of officers from the building side : Sh. Deepak Kumar (Manager)
9. Year of Construction : 2010
10. Applicant's letter No. : ID- 2023032504231

The restaurant is running at Ground Floor of D Mall comprised of 03 tier basements, ground plus 12 upper floors. D-Mall is already issued FSC vide letter No. F6/DFS/MS/Mercantile/WZ/2022/175 dated 20.04.2022.

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Requirement as Rule 35(6) of DFS Rules- 2010	Provided at site	Remarks MR/NMR
1	Access to building			
	• Road width	06 mts	Provided (30)	MR
	• Gate width	05 mts	Provided	MR
	• Width of internal road	06 mts	Provided	MR
2	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases	-	-	-
	• Upper Floors	N/A	Restaurant running at GF	N/A
	• Basements	N/A	N/A	N/A
	b. Width of staircases	-	-	-
	• Upper Floors	N/A	N/A	N/A
	• Basements	N/A	N/A	N/A
	c. Protection of exits	-	-	-
	• Fire check door	Required	Provided by Mall	MR
	• Pressurization	Required	Provided by Mall	MR
	e. No. of continuous staircases to terrace	Required	Provided by Mall	MR
	g. Width of Corridor	Required	Provided by Mall	MR
	h. Door Size	Required	1.93, 1.53 mts	MR
3	Compartmentation.			
	• Fire check door	Required	Provided by Mall	MR
	• Sealing of electrical shafts	Required	Provided by Mall	MR
	• Fire Rating of shaft door	Required	Provided by Mall	MR
	• Water Curtain	Required	Provided by Mall	MR
	• Fire Dampers	Required	Provided by Mall	MR
4	Smoke Management System.			
	• Basements	N/A	N/A	N/A
	• ground floor	Provided	Provided	MR

5	Fire Extinguishers			
	<ul style="list-style-type: none"> Total numbers Types IS marking 	06 CO ₂ , ABC type ISI marked	Provided Provided Provided	MR MR MR
6	First-Aid Hose Reels.			
	<ul style="list-style-type: none"> Total numbers on each floor Length of hose reel hose Nozzle diameter 	01 30 m 5 mm	Provided by Mall near restaurant Provided Provided	MR MR MR
7	Automatic fire detection and alarming system.			
	<ul style="list-style-type: none"> Type of detectors Location of Main Panel Location of Repeater Panel Alternate source of power Hooters' Location 	Smoke & Heat Required at GF N/A Required Required	Provided by Mall Provided N/A Provided by Mall Provided by Mall	MR MR✓ N/A MR MR
8	MOEFA	NA	Provided by Mall	---
9	Public Address System.	Required	Provided by Mall	MR
10	Automatic Sprinkler System.			
	<ul style="list-style-type: none"> Basement Entire Restaurant Sprinkler above false ceiling 	N/A N/A N/A	Provided by Mall Provided by Mall Provided by Mall	---- ---- ----
11	Internal Hydrants			
	<ul style="list-style-type: none"> Size of riser/down-comer Number of hydrants per floor Hose Box 	150 mm 02 02	Provided by Mall Provided by Mall Provided by Mall	MR MR MR
12	Yard Hydrants.			
	<ul style="list-style-type: none"> Total number of hydrants Hose Box 	N/A N/A	N/A N/A	N/A N/A
13	Pumping Arrangements.			
	<ul style="list-style-type: none"> Ground Level <ul style="list-style-type: none"> Discharge of main Pump Head of Main pump Number of main pumps Jockey Pump out put Jockey pump head Standby Pump out put Standby Pump Head Auto Starting/ Manual stopping Pump House Access Terrace level <ul style="list-style-type: none"> Discharge of pump Head of the pump Power Supply Auto Starting of pump 	--- 4500 LPM 65 m 02 180 LPM 65 m 4500 LPM 65 m Required Required ----- N/A N/A N/A N/A	--- Provided by Mall Provided by Mall Provided by Mall Provided by Mall Provided by Mall Provided by Mall Provided by Mall Provided by Mall Provided by Mall ----- N/A N/A N/A N/A	--- MR MR MR MR MR MR MR MR MR ----- N/A N/A N/A N/A
14	Captive Water Storage for fire fighting.			

✗

1/17

	<ul style="list-style-type: none"> Underground tank capacity 	2,50,000 lts	Provided by Mall	MR
	<ul style="list-style-type: none"> Draw-off connection 	Required	Provided by Mall	MR
	<ul style="list-style-type: none"> Fire service inlet 	Required	Provided by Mall	MR
	<ul style="list-style-type: none"> Access to tank 	Required	Provided by Mall	MR
	<ul style="list-style-type: none"> Overhead Tank capacity 	10,000 lts	Provided by Mall	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			
	<ul style="list-style-type: none"> Pressurization of Lift Shaft 	N/A	N/A	N/A
	<ul style="list-style-type: none"> Pressurization of Lift lobby 	N/A	N/A	N/A
	<ul style="list-style-type: none"> Communication In lift Car 	N/A	N/A	N/A
	<ul style="list-style-type: none"> Fireman's Grounding Switch 	N/A	N/A	N/A
	<ul style="list-style-type: none"> Lift Signage 	N/A	N/A	N/A
17	Standby power supply	Required	Provided	MR
18	Refuge Area.			
	<ul style="list-style-type: none"> Total Area 	N/A	N/A	N/A
	<ul style="list-style-type: none"> Location 	N/A	N/A	N/A
19	Fire Control Room			
	<ul style="list-style-type: none"> Detector System Panel 	N/A	N/A	N/A
	<ul style="list-style-type: none"> Flow Switch Panel 	N/A	N/A	N/A
	<ul style="list-style-type: none"> PA System Panel 	N/A	N/A	N/A
	<ul style="list-style-type: none"> Batter backup 	N/A	N/A	N/A
	<ul style="list-style-type: none"> Building Floor Plans 	N/A	N/A	N/A
20	Special Fire Protection Systems for Protection of special Risks, if any:	Required	Fire protection system provided in kitchen hood	MR

The fire protection systems provided in the building were randomly test checked and found functional at the time of inspection.

In view of the deemed compliance of minimum standards on fire prevention and fire safety requirements under the rules, renewal of Fire Safety Certificate issued vide letter no. F6/DFS/MS/WZ/2020/68 dated 16.03.2020 is recommended under Rule 37 of the Delhi Fire Service Rules, 2010 under DFS Act 2007.

Accordingly DFA is put up for approval please.

gcs
29/9/23

[Handwritten signature]
29/9/2023
Director

[Handwritten signature]
29/9/23

Signature of the Inspecting Officer
Name: - M. K. Chattopadhyay
Designation: - DO (West)

DIA/m/kc

P.T.O