



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No.F.6/DFS/MS/School/2023/SZ/ 390

Dated: 06/06/2023

FIRE SAFETY CERTIFICATE

Certified that M/s Mount St. Mary's School, located at 75, Parade Road, Delhi Cantt, New Delhi-110010, having two block i.e. main block comprised of Ground plus two upper floor and auditorium block comprised of ground plus two upper floors having Audi at 1st and 2nd floor, owned/occupied by Mount St. Mary's School has already been issued Fire Safety Certificate Vide letter No F6/DFS/MS/School/2020/SZ/312 date 27/08/2020. The premises was re-inspected by the officer concerned of this department on 18/05/2023 in the presence of Sh. Vipin Maan (Care Taker) of the school and found that the said school premises have deemed compiled with the fire prevention and fire safety requirement in accordance with rule 33 of Delhi Fire Service Rules 2010 and that the building is fit for occupancy class -B "Educational with effect from 06/06/2023 for a period of **three years** in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS rules, 2010.

Issued on 06/06/2023 at New Delhi by


(ATUL GARG)
DIRECTOR

Copy to :-

1. Principal, M/s Mount St. Mary's School, Located at 75, Parade Road, Delhi Cantt, New Delhi-110010.
2. The Director of Education, Old Secretariat, Civil Line, Delhi-110054.

Conditions for the validity of Fire Safety Certificate:

1. All the means of escape / entry / exit shall be kept free from any obstruction.
2. All the fire safety arrangement provided there in shall be maintained in good working conditions at all times.
3. Any loss of life or property due to non- functional fire safety measure shall be at the responsibility of the management.
4. All the staff members must know the correct method of operation of fire fighting system.
5. This Fire Safety Certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
6. "The owner / Occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on WWW.dfs.DelhiGovt.nic.in.

N-14
INSPECTION REPORT

1. Name & address of the building : M/s Mount St Mary's School, Located at 75, Parade Road, Delhi Cantt, New Delhi-110010.
2. Type of Occupancy : Educational, Group-B(School)
3. Type of Case : Renewal
4. Building Comprised of : Two Block each comprised of Ground + 2 Upper Floor only
5. Details of Previous NOC : F6/DFS/MS/School/2020/SZ/312 date 27/08/2020
6. Fire Safety directives Letter No. : Circular of Directorate of the Education dated 17/05/2005 ✓
7. Date of inspection : 18/05/2023.
8. Name of the Inspecting Officer : Santosh Kumar ADO S J
9. Name and designation of Officer from the building side : Vipin Maan (Care Taker)
10. Year of Construction : Not Known

11. Applicant's letter revised through email dated 26/04/2023

S No	Minimum standards on fire prevention and fire safety U/R 33	Old NOC Requirement	Provided at site	Remarks MR/NMR
1.	Access of building			
	• Road width	Required	15mtrs	MR
	• Gate width	N/A	5mtr.	MR
	• Width of internal road	N/A	N/A	N/A
2.	Number, width, Type & Arrangements of exits			
	a. Number of staircases			
	• Upper floors	Main Block=03Nos and Auditorium Block 04 Nos (4 Nos. upto 01 st Floor, 3Nos. upto 2 nd Floor)	Main Block=03Nos. and Auditorium Block 04 Nos (4 Nos. upto 01 st Floor, 3Nos. upto 2 nd Floor)	MR
	• Basements	N/A	N/A	N/A
	b. Width of staircases			
	• Upper floors	1.5mtr & 75cms	Main block=1.73(each) & auditorium block =1.6m, 1.34m, 1.00&1.5m	MR (old case) ✓
	• Basements	N/A	N/A	N/A
	c. Protection of exits			
	• Fire check door	N/A	N/A	N/A
	• Pressurization	N/A	N/A	N/A
	d. No of continuous staircase to terrace	01No	01No. in each Block	MR
	e. Width Of Corridor	N/A	1.5M	N/A
	f. Door Size	01Mtr	1 mtr Provided	MR
3.	Compartmentation			
	• Fire check door	N/A	N/A	N/A
	• Sealing of electrical shafts	Required	Provided	MR
	• Fire Rating of shaft door	N/A	N/A	N/A
	• Water Curtain	N/A	N/A	N/A
	• Fire Dampers	N/A	N/A	N/A
4.	Smoke managements System			
	• Basements	30 ACPH	N/A	N/A
	• Upper floors	12 ACPH	Natural Ventilation & Exhaust fans in auditorium/Multipurpose Hall	MR ✓
5.	Fire Extinguishers			
	• Total numbers	40 Nos	44 Nos	MR
	• Types	ISI marked ABC-Co2/W CO ₂	ABC-22, W/Co2-22 & Co2	M/R
	• IS marking	Required	Provided	M/R

A/B -

N-15

6.	First - Aid Hose Reels			
	• Total numbers on each floor	Required	05 Nos.	MR
	• Length of hose reel hose	30m	30m	MR
	• Nozzle diameter	5mm	5mm	MR
7.	Automatic fire detection and alarming system			
	• Type of detector	N/A	N/A	N/A
	• Location of Main Panel	N/A	N/A	N/A
	• Location of Repeater Panel	N/A	N/A	N/A
	• Alternate source of power	N/A	N/A	N/A
	• Hooters' Location	N/A	N/A	N/A
8.	MOEFA	N/A	N/A	N/A
9.	Public Address System	N/A	Provided	N/A
10.	Automatic Sprinkler System			
	• Basements	N/A	N/A	N/A
	• Upper Floor	N/A	N/A	N/A
	• Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants			
	• Size of riser/down-comer	Required	100mm	MR
	• Number of hydrants per floor	Required	04 Nos	MR
	• Hose Box	Required	04 Nos	MR
12.	Yard Hydrants			
	• Total number of hydrants	N/A	N/A	N/A
	• Hose Box	N/A	N/A	N/A
13.	Pumping Arrangements			
	• Ground Level			
	• Discharge of main pump	N/A	N/A	NA
	> Head of main pump	N/A	N/A	N/A
	> Number of main pumps	N/A	N/A	N/A
	> Jockey pump out put	N/A	N/A	N/A
	> Jockey pump head	N/A	N/A	N/A
	> Standby Pump out put	N/A	N/A	N/A
	> Standby Pump Head	N/A	N/A	N/A
	> Auto Staring/Manual stopping	N/A	N/A	N/A
	• Terrace level			
	> Discharge of pump	450 LPM +180 LPM	450LPM	MR
	> Head of the pump	40m (Each)	40m(Each)	MR
	> Power supply	Required	Provided	MR
	> Auto starting of pump	Required	Provided	MR
14.	Captive water Storage for fire fighting			
	• Underground tank capacity	N/A	N/A	N/A
	> Draw of connection	N/A	N/A	N/A
	> Fire service inlet	N/A	Provided	N/A
	> Access to tank	N/A	N/A	N/A
	• Overhead Tank capacity	5,000 liters	5,000 liters	MR

M

RN

15	Exit Signage	Required	Provided	MR
16.	Provision of Lifts			
	➤ Pressurization of Lift Shaft	N/A	N/A	N/A
	➤ Pressurization of lift lobby	N/A	N/A	N/A
	➤ Communication in lift Car	N/A	N/A	N/A
	➤ Fireman's Grounding Switch	N/A	N/A	N/A
	➤ Lift Signage	N/A	N/A	N/A
17.	Standby power supply	N/A	N/A	N/A
18.	Refuge Area	N/A	N/A	
	➤ Total area	N/A	N/A	N/A
	➤ Location	N/A	N/A	N/A
19.	Fire control room			
	➤ Detector system panel	N/A	N/A	N/A
	➤ Flow Switch Panel	N/A	N/A	N/A
	➤ PA System Panel	N/A	N/A	N/A
	➤ Batter backup	N/A	N/A	N/A
	➤ Building Floor Plans	N/A	N/A	N/A
20.	Special Fire Protection Systems for Protection of special Risks, if any;			N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards on fire prevention and fire safety required under the DOE circular, FSC Issued Vide letter N F6/DFS/MS/School/2020/SZ/312 date 27/08/2020 renewal under rules 37 of the Del fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Santosh Kumar
 25.05.23
 Signature of the Inspecting Officer
 Name : Santosh kumar
 Designation : A.D.O. (S.J.)

DD/CS/WH
msk
 25/5

CFO
Vugh
 31/5/2023

Director
[Signature]
 1/06/23

ANYS

Sir, print F.T for your signature please.

Director
[Signature]
 2/06/23

Santosh Kumar
 06/05/23