

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS; DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/School/2023/393

Dated: 06 106 12023

FIRE SAFETY CERTIFICATE

Certified that the Queen Mary's School, Northend located at Plot No. 4-A, Town-III, Delhl-110009 comprised of Ground & 04 upper floors with separate basement owned/ occupied by Queen Mary's School, Northend was issued Fire Safety Certificated vide this office letter no. F6/DFS/MS/2016/27 dated 06.01.2017 (ground & 03 upper floors with separate basement only). The premise was re-inspected by the officer concerned of this department on 30.05.2023 in the presence of Mr. Sandeep Masih (Admin) and observed that there is premise additional alteration running of offices & class rooms at fourth floor. The premise have therefore deemed complied with the requirements under rule 33 of the Delhi Fire Service Rules, 2010 and the building premise is fit for occupancy under Educational "Group B" with effect from _for a period of Valid up to 31.03.2026 in accordance with the Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40, subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Ph:-011-23414000

Copy to: -

The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi-110054.

2. The Principal, Queen Mary's School, Northend located at Plot No. 4-A, Town-III, Delhi-110009.

Conditions for the validity of Fire Safety Certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection

3. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.

4. All the staff members must know the correct method of operation of firefighting system.

5. The owner / occupier shall submit a declaration every year in Form "K" provided in the first of Delhi Fire Service Rules 2010. The form http://delhi.gov.in/wps/wcm/connect/doit fire/FIRE/Home/Forms

6. This fire safety certificate may not in any way be treated as regularization (Clause 2 8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.

7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

INSPECTION REPORT

Name & address of the building

Type of Occupancy

Queen Mary's School Northend at Plot No. 4-A, Model Town-III, Delhi-09

: Educational

Composition of building 3

Ground plus 04 Upper floor with separate basement

Type of Case

Joint Site Inspection/ Add-Alt

5 Details of previous NOC

: F6/ DFS/MS/2016/27 dated 06:01:2017 (Ground & 03 upper floors only)

Fire Safety directives letter No

: F6/DFS/MS/BP/2004/333 dated 11 02 2004 (Old Guide Line, G+03 floors) F6/DFS/MS/BP/2015/317 dated 101 12 2015 (New Guide Line, G+04 floors)

7 Date of inspection

: 30.05.2023

Name of the Inspecting Officers

: ADO (RN) ~

9. Name and designation of officers

from the building side

: Sh. Sandeep Masih (Admin) Sh. Shahrook Ali (AE. Bidg/DDA)

Sh. Kapil Joshi (Architecture)

10. Year of Construction

: 2003

11. Applicant's letter No.

: Letter No. F13(188)2002/BLDG-OCC dated 30 05 2023

	Minimum Standards on fire prevention and fire safety U/R 33	NBC Part-IV Requirements	Provided at site	Remarks MR/NMR			
1	Access to building						
	Road width	6m	12m	MR			
	Gate width	5m	05m x2	MR			
	Width of internal road	06m	06m	MR V			
	Number, Width, Type & Arrangement of Exits						
	a. Number of staircases						
	Upper Floors	04	04	MR			
	Basements	02	02	MR(Old case)			
	b. Width of staircases						
	Upper Floors	04 nos. of 1.50m each	Provided	MR			
	Basements	1.50m	1.18m & 97cm	MR (old case)			
	c Protection of exits						
	Fire check door	Required	Provided	MR			
	Pressurization	NA NA	NA NA	NA			
	d No of continuous staircases to terrace	04	04	MR			
		Required	Provided	MR			
	e Width of Corridor	0 im &1.20m	1.14 m & 1.20m	MR			
-	Compartmentation.			T NA			
		NA	NA NA				
		NA	NA	NA			
	Sealing of electrical shafts	NA NA	NA	NA NA			
	Fire Rating of shaft door		NA NA	NA.			
	Water Curtain	NA	A	- NA			
	Fire Dampers	NA	NA	NA NA			
				T NA			
	Smoke Management System.	NA NA	Separate basement				
	Basements Upper floors	Required	Provided	MR V			
	Upper Hoors						
	Fire Extinguishers		60nos	MR			
_	Total numbers	40nos	ABC-60	MR			
	C MACAMAN-	ABC/Co2		MR			
	Types	1St Marked	Yes	1000			
	ISI marking First-Aid Hose Reels.						

	4/12		-	C		
		03 each floor	Provided .	MR	1	
	To all sumbers on each floor	30m	30m	MR	11	
	Length of hose reel hose		5mm	MR		
	sete diameter	5mm		NA.		
11	Automatic fire detection and alarming system.	NA	NA .	NA NA		
-	at Agrectors	NA NA	NA	NA.		
1	Location of Main Panel	NA NA	NA		-	
- 1	Location of Repeater Panel		NA	NA		
1	Alternate source of power	NA .	NA.	N/		
	Hooters' Location	NA.	NA NA	N/		
		NA	Provided	M	R	
8	MOEFA	Required	Fictions	1.		
9	Public Address System		Provided	V	IR	
10	Automatic Sprinkler System.	Required			NA.	
	Basement	NA.	NA		NA	
	Upper Floor Upper Floor Upper Floor	NA NA	NA.		INC.	
	Sprinkler above false ceiling				MR	
11	Internal Hydrants	100mm	100mm		MR	
	Size of riser down-comer	03	Provided Provided		MR	
	Number of hydrants per floor	03	Provided			
	Hose Box		N/A		N/A	
12	Yard Hydrants. Total number of hydrants	N/A			N/A	
	The same of the sa	N/A	N/A			
	Hose Box	11:-				
13	Pumping Arrangements.				MR	
	Ground Level	2280LPM	2280LPM		0.000	
+	> Discharge of main Pump	80m	som		MR	
	> Head of Main pump	02Nos	02 Nos		MR	
	> Number of main pumps	180 LPM	180 LPM		MR	
1	> Jockey Pump out put	80m	80m		MR	
	> Jockey pump head	2280 LPM	2280 LPN		MR	
	> Standby Pump out put	(Diesel Operative	(Diesel Opera Provided		MR	
	> Standby Pump Head	Required	Salter Capita		MR	
	Auto Starting/ Manual stopping Pump House Access	Required	Provide	d	MK	
	Page STOCK (AND I		9001	pxt	MR	
	> Discharge of pump	900 LPM	40m		MR	
	Head of the pump	40m			MR	
	> Power Supply	Required	Provid	ed		
	10 e 1 20 A CONTROL A CONTROL A CAL	Required	Provid	icd	MR	
	Autosia					
18		50,000 LT	R 1,00,00	ULTR	MR	
	 Underground tank capacity 			NA NA		
	> Draw-off connection	NA	X		NA NA	
1	> Fire service inlet	NA.			N/	
	Access to tank	NA		A	NV.	
	Overhead Tank capacity	10,000 L	TR 20,0	00 LTR	M	
	3 91	Required Provide		wided	d M	
	5 Exit Signage	Keduin				
	reservation to the Constitution					
-	6 Provision of Lifts.		9. Er			

0	Pressurization of Lift Shaft	Required	Provided	MR	
	Pressurization of Lift lobby	Required	Provided	MR	
	Communication In lift Car	Required	Provided	MR	
	• Fireman's Grounding Switch	Required	Provided	MR	
	Lift Signage	Required	Provided	MR	
-	Standby power supply	Required	Provided	MR	
	Refuge Area.				
1	> Total Area	N/A	N/A	N/A	
	> Location	N/A	N/A	N/A	
9	Fire Control Room				
	Detector System Panel	Required	Ground floor	MR	
	Flow Switch Panel	Required	Ground floor	MR	
	PA System Panel	Required	Ground floor	MR	
	Batter backup	Required	Ground floor	MR	
	Building Floor Plans	Required	Ground floor	MR	
0	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A	

The fire protection systems provided in the building were tested/ checked randomly and found in good working condition, at the time of inspection. The management has complied all the shortcomings issued and communicated by this department vide letter of even no. F6/DFS/MS/2023/School/115 dated 13.03.2023.

Keeping in view the satisfactory compliance of the minimum standard on fire prevention and fire safety requirements as stipulated in NBC Part 4, it is recommended to grant Fire Safety Certificate.

Divisional Officer (NWD)

Signature of the Inspecting Office Name: - C.L. Meena

Designation: - Asst. Div. Officer (RN)

As approved F.T. letter is Parup For your Signature Al. _____ Caro

FIP/G