



C-55

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001




No. F6/DFS/MS/EH/WZ/2023/ 177

Dated: 07/06/2023

FIRE SAFETY CERTIFICATE

Certified that M/s. Devour Foods Concepts running at Ground Floor only in a building comprised of basement, ground plus three upper floors, located at Plot No. 06, Block- B1, Ashok Vihar Phase- II, New Delhi- 110052, owned/occupied by M/s. Devour Foods Concepts, was granted fire safety certificate vide letter No. F6/DFS/MS/WZ/2020/EH/78 dated 19.03.2020. The premises was re-inspected by the officer concerned of this department on 31.05.2023 in the presence of Sh. Tarundeep Singh Takkar (owner) and observed that the owner have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class- "Assembly" Group-D (Restaurant at Ground Floor only) with effect from 07/06/2023 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed overleaf.

Issued on 07/6/2023 at New Delhi by.


(Atul Garg)
Director
92 dyg 7/6/2023

Copy to:-

1. The Owner / Occupier, M/s. Devour Foods Concepts, Ground Floor, Plot No. 06, Block-B1, Ashok Vihar Phase- II, New Delhi- 110052.
2. The Dy. Health Officer, MCD, Keshavpuram Zone, Public Health Department, New Delhi.
3. The Joint Commissioner of Police (Lic.), Police Station Defence Colony, First floor, New Delhi.

1/24

INSPECTION REPORT

1. Name & address of the building : M/s.Devour Food Concepts Restaurant, Plot No. 06, Block- B1, Ground Floor, Ashok Vihar Phase- II, New Delhi- 110052.
2. Type of Occupancy : Assembly (Restaurant)/ running at Ground Floor of G+3 building
3. Type of Case : Renewal
4. Details of previous NOC : F6/DFS/MS/WZ/2020/EH/78 dated 19.03.2020
5. Fire Safety directives letter No : N/A
6. Date of inspection : 31.05.2023
7. Name of the Inspecting Officers : M.K. Chattopadhyay, Dy. Chief Fire Officer
8. Name and designation of officers from the building side : Sh. Tarundeep Singh Takkar, owner
9. Year of Construction : 2001(as per details upload on MHA portal)
10. Applicant's letter No. : Online ID- 2023052209395

The said restaurant is running at upper ground floor in a building comprised of basement, ground plus three floors.

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Requirement as Rule 35(6) of DFS Rules- 2010	Provided at site	Remarks MR/NMR
1	Access to building			
	• Road width	6 mts	Provided	MR
	• Gate width	N/A	N/A	N/A
	• Width of internal road	N/A	N/A	N/A
2	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases	-	-	-
	• Upper Floors	N/A	Rest. At GF only	N/A
	• Basements	N/A	N/A	N/A
	b. Width of staircases	-	-	-
	• Upper Floors	N/A	N/A	N/A
	• Basements	N/A	N/A	N/A
	c. Protection of exits	-	-	-
	• Fire check door	N/A	N/A	N/A
	• Pressurization	N/A	N/A	N/A
	e. No. of continuous staircases to terrace	NA	Provided	N/A
	g. Width of Corridor	N/A	N/A	N/A
	h. Door Size	1x2 0, 1x1 0mts	2.0, 1.5 mts	MR
3	Compartmentation.			
	• Fire check door	N/A	N/A	N/A
	• Sealing of electrical shafts	N/A	N/A	N/A
	• Fire Rating of shaft door	N/A	N/A	N/A
	• Water Curtain	N/A	N/A	N/A
	• Fire Dampers	N/A	N/A	N/A
4	Smoke Management System.			
	• Basements	NA	N/A	N/A
	• Upper floors	Required	Exhaust fan Provided	MR

Signature

N/26

14	Captive Water Storage for fire fighting.			
	• Underground tank capacity	N/A	N/A	N/A
	➤ Draw-off connection	N/A	N/A	N/A
	➤ Fire service inlet	N/A	N/A	N/A
	➤ Access to tank	N/A	N/A	N/A
	• Overhead Tank capacity	10,000 lts	Provided	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			
	• Pressurization of Lift Shaft	N/A	N/A	N/A
	• Pressurization of Lift lobby	N/A	N/A	N/A
	• Communication In lift Car	N/A	N/A	N/A
	• Fireman's Grounding Switch	N/A	N/A	N/A
	• Lift Signage	N/A	N/A	N/A
17	Standby power supply	Required	Provided	MR
18	Refuge Area.			
	➤ Total Area	N/A	N/A	N/A
	➤ Location	N/A	N/A	N/A
19	Fire Control Room			
	• Detector System Panel	N/A	N/A	N/A
	• Flow Switch Panel	N/A	N/A	N/A
	• PA System Panel	N/A	N/A	N/A
	• Batter backup	N/A	N/A	N/A
	• Building Floor Plans	N/A	N/A	N/A
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were randomly test checked at the time of inspection and found functional.

All the shortcomings issued by this department vide letter No. F6/DFS/MS/EH/WZ/2023/20 dated 16.01.2023 have been complied with by the restaurant management.

Note: The Rooms seen earlier have been partially removed at terrace, the FSC shall be null & void if the rooms at terrace are repair/reconstructed/used in future.

In view of the deemed compliance of minimum standards on fire prevention and fire safety requirements under the rules, renewal of Fire Safety Certificate issued vide letter no. F6/DFS/MS/WZ/2020/EH/78 dated 19.03.2020 is recommended under Rule 37 of the Delhi Fire Service Rules, 2010 under DFS Act 2007.

Accordingly, DFA is put up for approval please.

DFE/603
05/06/2023

CFO
6/6/2023

M.K. Chattopadhyay
Dy. Chief Fire Officer