## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/School/WZ/2023/378

FIRE SAFETY CERTIFICATE

Dated 01/06/2023

Certified that the VSPK International School, Sector-13, Rohini, New Delhi-110085, comprised of Basement + Ground + 04 upper floors owned/ occupied by VSPK International School have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of fire service on dated 26.05.2023 in the presence of Mr. Sandeep and that the building/ premise is fit for occupancy Group B Educational with effect from .01 06 2023. for a period of three years, in accordance with the Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 01 06 2023 at New Delhi by

Ph; 011-23414000

Copy to:

1. The Principal, VSPK International School, Sector-13, Rohini, New Delhi-110085.

The Director of Education, GNCT of Delhi Old Secretariat, Delhi-110054

Conditions for validity of Fire Safety Certificate;

- 1. All the fire safety arrangement provided there-in shall be maintained in good working
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility

 The trained fire fighting staff should be available round the clock. 4. Any deviation with regard to the construction etc shall be verified by the concerned building

This certificate cannot be treated in any case for regularizations of unauthorized construction.

6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its

7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on

8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

http://www.delhi.gov.in/wps/wcm/connect/doit\_fire/FIRE/Home/Fire+Safety+Acts+and+Rules/ http://www.delhi.gov.in/wps/wcm/connect/doit\_fire/FIRE/Home/Forms

INSPECTION REPORT 1. Name & address of the building : VSPK International School, Sector-13, Rohini, New Delhi-110085.

2. Type of Occupancy

: Educational

3. Building Comprised

: Basement + Ground + 04 Upper Floors

Type of Case

: New Case

5. Details of Previous NOC

: F6/DFS/MS/2018/School/2386 dated 25/10/2018 (B+Gr.+III)

6. Fire Safety directives letter No

: F.6/DFS/MS/BP/2021/School/272 dated 16.06.2021

Date of inspection

: 26.05.2023

8. Name of Inspecting Officer

: Rajiv Kumar Sinha, ADO (Bawana)

Name and designation of officers

From the building side

: Mr. Sandeep : 2002 & 2021

10. Year of Construction

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	NBC Requirement	Provided at site	Remarks MR/NMR			
1.	Access to building	-122					
	Road width	18m	18m	MR			
	Gate width	2 x 6.0m	2 x 6.0m	MR			
	Width of internal road	6.0m	6.0m to 9.0m	MR			
2.	Number, Width, Type & Arrangement of Exits						
	a. Number of staircases	Description	02 8 01	MR			
	Upper Floors	Required	02 & 01 ramp				
	Basements	04	04	MR			
- 1	b. Width of staircases			1.10			
	Upper Floor	1.5m each	Provided	MR			
	• Basements	1.5m each	Provided	MR			
	c. Protection of exits Fire check door	6 1	×				
	Pressurization	Required	Provided	MR			
	d. No. of continuous staircases to terrace	Required	Provided	MR			
	e. Width of Corridor	02 & 1 Ramp 1.5 m	02 & 1 Ramp	MR			
	f. Door Size		1.5m	MR			
_	Compartmentation	1.0m	1.0m	MR			
-	Fire check door	274					
	FIRE DENTH-CHARLESTANDER FLORENCE I	NA	NA	NA			
	Sealing of electrical shafts	NA	NA	NA			
ı j	Fire Rating of shaft door	NA	NA	NA			
	Water Curtain	NA	NA	NA			
	Fire Dampers	NA	NA	NA			
	Smoke Management System						
	Basements	30 a/c per hour	Exhaust fan	110			
	Upper floors	12 a/c per hour		MR			
I	Fire Extinguishers	- Per noui	Naturally ventilated	MR			
	Total numbers	26					
	• Types	26nos.	28nos.	MR			
	IS marking	ABC/CO2 ABC-28	MR				
F	irst-Aid Hose Reels	ISI marked	Yes	MR			
	Total numbers on each floor	00		7,67,571			
	Length of hose reel hose	02	Provided	MR			
	Nozzle diameter	30mm	Provided	MR			
A	automatic fire detection and alarming syste	⊥ 5m	Provided	MR			
	Type of detectors						
	Location of Main Panel	NA	NA	NA			
	<ul> <li>Location of Repeater Panel</li> </ul>	NA	NA	NA			
		NA NA	NA	NA NA			

			Laurence - American	0	
	Alternate source of power	NA	NA	NA	
8.	Hooters' Location     MOEFA	NA	NA	NA	
9.	Public Address System	Required	Provided	MR	
10.	Automatic Sprinkler System	Required	Provided	MR	
	Basement	Required	Described.	T	
	Ground & Upper Floors	NA	Provided NA	MR	
	Sprinkler above false ceiling	NA NA		NA	
11.	Internal Hydrants	I NA	NA	NA	
	Size of riser/down-comer	100mm	100mm	MR	
	Number of hydrants per floor	02	02	MR	
10	Hose Box	02	02	MR	
12.	Yard Hydrants	THE PLANT	AVE STORY		
	Total number of hydrants	01	01	MR	
13.	Hose Box	01	01	MR	
13.	Pumping Arrangements  • Ground Level				
	Ground Ecycl	-	100 a 1000		
	Discharge of main Pump	2280lpm	2280lpm	MR	
	> Head of Main pump	80m	80m	MR	
	Number of main pumps	01	01	MR	
	> Jockey Pump out put	180lpm	180lpm	MR	
	> Jockey pump head	80m	80m	MR	
	> Standby Pump out put	2280lpm	2280lpm	MR /	
	Standby Pump Head	80m	80m	MR	
	> Auto Starting/Manual Stopping	Required	Provided	MR	
	> Pump House Access	Required	Provided	MR	
	Terrace level				
	> Discharge of pump	900lpm	900lpm	MR	
	➤ Head of the pump ➤ Power Supply	40m	40m	MR	
	> Auto Starting of pump	Required	Provided	MR	
14.	Captive Water Storage for fire fighting	Required	Provided	MR	
	Underground tank capacity     Draw-off connection	2,00,000ltr	2,00,000ltr	MR	
	> Fire service inlet	NA	NA	NA	
	> Access to tank	NA NA	NA	NA	
			NA NA	NA	
		25,000ltr	40,000ltr	MR	
15	Overhead Tank capacity  Fall Signature			A CONTRACTOR OF THE PARTY OF TH	
	Exit Signage.	Required	Provided	MR	
	Exit Signage. Provision of Lifts.			MR	
	Exit Signage.				
	Exit Signage. Provision of Lifts.	Required Required Required	Provided	MR MR MR	
	Exit Signage.  Provision of Lifts.  • Pressurization of Lift Shaft	Required Required Required Required	Provided Provided	MR	
	Exit Signage.  Provision of Lifts.  Pressurization of Lift Shaft Pressurization of Lift lobby	Required Required Required	Provided Provided Provided	MR MR MR	
	Exit Signage.  Provision of Lifts.  Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car	Required Required Required Required	Provided Provided Provided Provided	MR MR MR MR	
16.	Exit Signage.  Provision of Lifts.  Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage	Required Required Required Required Required GF Required	Provided Provided Provided Provided Provided Provided	MR MR MR MR MR	
16.	Exit Signage.  Provision of Lifts.  Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch	Required Required Required Required Required	Provided Provided Provided Provided Provided	MR MR MR MR	
16.	Exit Signage.  Provision of Lifts.  Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage Standby power supply	Required Required Required Required Required GF Required Required	Provided Provided Provided Provided Provided Provided Provided	MR MR MR MR MR	
16.	Exit Signage.  Provision of Lifts.  Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage Standby power supply Refuge Area.	Required Required Required Required Required GF Required Required	Provided Provided Provided Provided Provided Provided Provided Provided NA	MR MR MR MR MR MR	
16. 17. 18.	Exit Signage.  Provision of Lifts.  Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage Standby power supply Refuge Area.  Total Area	Required Required Required Required Required GF Required Required	Provided Provided Provided Provided Provided Provided Provided	MR MR MR MR MR	
16. 17. 18.	Exit Signage.  Provision of Lifts.  Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage Standby power supply Refuge Area. Total Area Location Fire Control Room	Required  Required  Required  Required  Required GF  Required  Required  NA  NA	Provided Provided Provided Provided Provided Provided Provided Provided NA NA	MR MR MR MR MR MR	
15. 16.	Exit Signage.  Provision of Lifts.  Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage Standby power supply Refuge Area.  Total Area Location Fire Control Room	Required Required Required Required Required GF Required Required	Provided Provided Provided Provided Provided Provided Provided Provided NA NA NA NA	MR MR MR MR MR MR	
16. 17. 18.	Exit Signage.  Provision of Lifts.  Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage Standby power supply Refuge Area.  Total Area Location Fire Control Room Detector System Panel	Required Required Required Required Required GF Required Required NA NA NA	Provided Provided Provided Provided Provided Provided Provided Provided NA NA	MR MR MR MR MR MR	

Buttery backup     Building Floor Plans	NA	NA	NA
Special Fire Protection System for Protection of special Risks, if any:	NA	NA	NA

The fire protection systems provided in the building were test checked and found functional at the time of inspection. The management had rectified the shortcomings issued vide letter number F6/DFS/MS/School/2023/WZ/99 dated 28/02/2023.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rule 2010.

> Signature of the Inspecting O : Rajiv Kumar Sinha

Designation: ADO (Bawana)

Sor FT letter in Notes for sign places