



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001 Dated: 06 106 12023

No. F6/DFS/MS/BNQT/NDZ/2023/ 24

FIRE SAFETY CERTIFICATE

Certified that the M/S Shree R.G. Enterprises, (Aqua Tree), located at B-19. Jhilmil Industrial Area, Shahdara, Delhi-110095, building comprised of Ground + 03 Upper Floors but Banquet Hall is running on Ground & Two upper Floors only, owned/occupied by M/s Aqua Tree, have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rule, 2010 and verified by the officers concerned of this department on 25/05/2023 in the presence of Sh. Nitish Maini (Manager) and observed that the building/premises fit for occupancy class "Assembly" (Group D) (Banquet Hall on Ground and Two upper Floors only) with effect from 06 106 12023 for period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010 printed below

Issued on 06/06/2023 at New Delhi by.

0 60 DELHI FIRE SERVICE

Copy to:-

- 1. Sh. Mukesh Aggarwal, Shree R.G. Enterprises, (Aqua Tree), B-19, Jhilmil Industiral Area, Shahdara,
- The Joint C.P. (Licensing), 1st Floor, Police Station Defence Colony, New Delhi-110024 wrt. Online Application ID no. 2023050508281 Dated 11/05/2023.

Conditions for the validity of Fire Safety Certificate:

- Fire Safety Certificate is valid for Ground, 1" & 2"4 Floors only.
- 2. All the fire safety arrangement provided there in shall be maintained in good working conditions at all times.
- 3. Loss of life or property due to non-functional fire safety measure shall be at the responsibility of the Management
- 4 The trained fire fighting staff should be available round the clock
- 5 Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning
- 6. This certificate cannot be treated in any case for regularizations of unauthorized construction
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an
- 8 "The owner / Occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [subrule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry"
- 9 The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The from is available on www.dfs.delliigovt.nic.in.

INSPECTION REPORT

Name & address of the building: Shri R.G. Enterprises (Aqua Tree)

Banquet Hall, B-19, Jhilmil Industiral Area,

Shahdara, Delhi - 110095.

: Ground plus Three upper Floors 2. Building is comprised of

(Banquet Hall is proposed on G+2 upper Floors only)

: Assembly (Banquet) 3. Type of Occupancy

: F6/DFS/MS/BNQT/2020/NDZ/205 Dated 04/06/2020 4. Type of Case

6. Fire Safety directives Letter No.: F6/DFS/MS/2020/797 Dated 18/03/2020

: 25/05/2023

8. Name of the Inspecting Officer: Sh. A.K.Jaiswal D.O.(ED) & ADO Deepak Kumar(Shahd)

Name and designation of Officer

IS Marking

: Sh. Nitish Maini (Manager) from the building side

11. A	Minimum Standards on fire	NBC Part IV/UBBL Requirement	Provided at Site R	Remarks
11.1.1	prevention and fire safety U/R 33	Requirement		
	Access to building	17	12.19 & 18.29 m	MR
	Road width Gate width	6 m 3 m, 2.5 m(front)		
	• date	& 1.5 m x 2	N/A	N/A
	Width of internal road	N/A	11/11	
-	Number, Width, Type and Arrangeme	ent of Exits		
2	a. Number of Staircases		04 Nos.	MR
	Upper Floor	02 Nos.	N/A	N/A
	n	N/A	N/A	
	Basement Width of Staircases Upper Floor	2 m & 1.5 m	GF to FF = 1 54 m x 1 GF to SF = 1 50 m x 1 GF to Terrace=2.5m x1 & 1 25 m x 1	
		N/A	N/A	N/A
	 Basement 	N/A		
	Protection of exits	Descripted	Provided	MR
	Fire check door	Required	N/A	N/A
	Pressurization	N/A	02 Nos.	MR
	d. No. of continuous staircases to	02 Nos.	02	
	terrace		N/A	N/A
		N/A	02 m x 2	MR
	e. Width of Corridor	02 m	02 111 7 2	
	f. Door size		Provided	MR
3	Compartmentation Fire check Door	Required	Provided	MR
	Sealing of electrical Shafts	Required	The second of th	N/A
	Sealing of electrical sharts Fire rating of Shaft Door	N/A	N/A	N/A
	Fire rating of Share Book	N/A	N/A	N/A
	Water Curtain Fire Dampers	N/A	N/A	N/A
1121	Fire Dampers Smoke Management System	-F-94-72-10	Tax / A	N/A
4	Basement	N/A	N/A	N/A
	Basement Upper Floor	N/A	N/A	14/1
	• Upper Floor		1.21	MR
5	Fire Extinguishers	06 Nos.	08 Nos.	MR
	Total Numbers	ABC & Co2	ABC & Co2	MR
	 Types 	ISI Marked	ISI Marked	MIN



1/1/2

П	First-aid-Hose Reels	02 Nos.	02 Nos.	MR	
5	Total numbers of each floor	30 M	30 M	MR	
	• Length of hose reel nose	05 mm	05 mm	MR	
	1 11-marker			110	
7	Automatic fire detection and alarming	Smoke	Provided	MR	
	Type of detectors	G.Floor	Provided	MR	
	Location of main panel	N/A	N/A	N/A	
	Location of repeater panel	Required	Provided	MR	
	Alternate source of power	N/A	N/A	N/A	
	Hooter's Location	Required	Provided	MR	
8	MOEFA	N/A	N/A	N/A	
9	Public address System	N/A		1	
10	Automatic Sprinkler System	N/A	N/A	N/A	
10	Basement		N/A	N/A	
	Hanar Floor	N/A N/A	N/A	N/A	
	Sprinkler above false Ceiling	N/A			
11	Internal Hydrants	1400 mm	100 mm	MR	
11	Cine of rise/down-comer	100 mm	02 nos.	MR	
	Number of Hydrants per Floor	02 nos.	02 nos.	MR	
	Hose Box	02 nos.			
12	Vard Hydrants	13:14	N/A	N/A	
12	Total number of Hydrants	N/A	N/A	N/A	
	Hose Box	N/A	111/11		
13	Pumping Arrangements			1 4	
	Ground Level		Provided	MR	
	> Discharge of main Pump	2280 LPM	Provided	MR	
	> Head of Main Pump	60 MH	Provided	MR	
	> Number of main Pumps	O1 Nos.	Provided	MR	
	> Jockey pump output	180 LPM	Provided	MR	
	> Jockey pump head	60 MH		MR	
	a II outnut	2280 LPM	Provided	MR	
	- II bood	60 MH	Provided	MR	
	> Standby pump head > Auto starting/Manual	Required	Provided	MAIN	
	stopping		D (4)4	MR	
	> Pump house access	Required	Provided	- I-LIX	
	Terrace Level			MR	
	> Discharge of pump	450 LPM	Provided	MR	
	. I Caba numn	40 MH	Provided	MR	
	> head of the pump > Power supply	Required	Provided	_	
	a de la comp	Required	Provided	MR	
	Auto Starting				
14	Captive Water Storage for Fire Fight	1,00,000 Ltrs.	1,00,000 Ltrs.	MR	
	Underground tank capacity	Required	Provided	MR	
	> Draw-off connection	Required	Provided	MR	
	> Fire service inlet	Required	Provided	MR	
	> Access to tank	5,000 Ltrs.	Provided	MR	
	overhead Tank capacity		Provided	MR	
15	Exit Signage	Required			

N. St 201

16	Provision of Lifts		AL /A	N/A	
	 Pressurization of Lift Shaft Pressurization of Lift lobby Communication in lift car 	N/A	N/A		
		N/A	N/A	N/A	
		N/A	N/A	N/A	
1	 Firemen's grounding switch 	N/A	N/A	N/A	
ě	Lift Signage	N/A	N/A	N/A	
17	Standby power supply	Required	Provided	MR	
18	Pefinge Area				
	Total area Location	N/A	N/A	N/A	
		N/A	N/A	N/A	
19	Fire Control Room				
	 Detector system panel Flow switch panel PA system panel Battery backup 	N/A	N/A		
		N/A	N/A	N/A	
		N/A	N/A	N/A	
		N/A	N/A	N/A	
		N/A	N/A	N/A	
	Building floor plans		N/A	N/A	
20	Special Fire Protection systems for protection of special Risks, if any:	N/A	NOT /2021 /NDZ/	2741 Da	

Note:-Shortcomings issued by letter No. F6/DFS/MS/BNQT/2021/NDZ/2741 Dates

24/12/2021 have been complied. The fire protection systems provided in the building were tested, checked and found

functional at the time of inspection. Keeping in view the substantial compliance of the minimum standards on fir prevention and fire safety required under the rules, grant of fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010 is recommended please.

Name: Deepak Kumar

Designation: ADO (Shahdara)

Name: Ashok Kumar Jaiswal Designation DO (East Div)

Sir. F.S. letter is put

up for your kind signature bl.