



## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001

No.F6/DFS/MS/C-Hall/2023/NDZ/ 233

Dated: 19/06/2023

## FIRE SAFETY CERTIFICATE

Certified that the Garhdesiya Bharatri Mandal Regd. located at Plot No. 37-X, Karkardooma Institutional Area, Delhi-110092, building comprised of basement, ground plus two upper floors, owned/occupied by Garhdesiya Bharatri Mandal Regd. The premises was inspected by the officers concerned of this department on dated 06/06/2023 in the presence of Mr. Sanjay Bhatt and observed that all the fire prevention and fire safety arrangements provided in the premises found in good working condition. The premises have complied with rule 33 of the Delhi Fire Service Rules, 2010 and observed that the building/premises is fit for occupancy class "Assembly" Group 'D' with effect from ....12/of/2013 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010, printed below.

Issued on 19/06/2023 at New Delhi by

(ATUL GARG) DIRECTOR DELHI FIRE SERVICE

To,

Sh. Rakesh Chandra
 Garhdesiya Bharatri Mandal Regd. at Plot No. 37-X, Karkardooma Institutional Area, Delhi-110002

 The Joint Commissioner (Lic.)
 1<sup>st</sup> floor Police Station Defence Colony, New Delhi w.r.to MHA ID 2023052309501 dated 24/05/2023

Conditions for the validity of Fire Safety Certificate

Fire Safety Certificate is valid for ground to second floor only. Applicant has submitted an
undertaking dated 06/06/2023 that community hall will not use terrace floor temporary rooms
for any purpose failing which this FSC should be treated null & void.

2. All the means of escape shall be kept free of all type of obstruction all the time.

 All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.

 All the fire fighting equipment shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.

 Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.

6. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction /unauthorized use of land if any.

The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule
of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

The owner / occupier shall apply for renewal of this Fire Safety Certificate of the Director in Form
'J' [sub rule (1) of rule (37)] along with a copy of this Certificate, Six Months prior to its expiry.

1	INSPECTION REPORT						
1.	Name & address of the building	: Garhdesiya Bharatri Mandal Regd at 37 X					
1	Pullding In	Karkar	dooma Institutional Are	a, Delhi-92			
2.	Building is comprised of	: Basem	: Basement , ground plus two upper floors				
3.	(two temporary rooms on the roof)						
4.	Type of Case		: New				
1,000	Details of Previous NOC letter						
100		: Nil					
6.	Fire Safety directive letter No : F.6/DFS/MS/BP/2009/2226 dated 20						
7.	Date of Inspection	spection : 06/06/2023					
8.	8. Name of the Inspecting officers : DO A.K. Jaiswal & ADO Deepak Kui						
	Name and designation of Officer			an ite			
	from the building side : Mr. Sanjay Bhatt						
	Year of Construction		gay conatt				
			: 2002 : 2023052309501 dated 24/05/2023				
	Applicant's application No.	: 202305					
Sr.	Minimum Standards on fire	Directive	Provided at Site	Remarks			
No	prevention and fire safety U/R33	Requirement		MR/NM			
01	Access to building.			-			
	Road width	12m	18m /	MR			
-	Gate width	N/A	N/A	N/A			
	Width of internal road	N/A	N/A	N/A			
02	Number, Width, Type and Arrang	ement of Exits.					
	a. Number of Staircases						
	Upper Floor	02 nos.	02 nos.	MR			
10	Basement	02 nos	02 nos	MR			
	B. Width of Staircases	1.50m	1.50m each r	MR			
	Upper Floor     Basement	1.50m	1.50m each	MR			
10	Protection of exits	150	T. John Cale				
	Fire check door	Required	Provided	MR			
	Pressurization	N/A	N/A	N/A			
d	No. of continuous staircases	OI no	01 no.	MR			
	to terrace Width of Corridor	N/A	N/A	N/A			
	Door Size	1.50m	1.50m	MR			
-	Compartmentation.						
	Fire check door	Required	Provided	MR			
	Sealing of electrical shafts	Required	Sealed	MIK			
	Fire rating of shaft door	N/A	N/A	N/A			
	Water curtain	N/A	N/A	NA			
	Fire Dampers	N/A	N/A	N/A			
Sn	noke Management System.						
	Basement	Required	Exhaust	MR			
	Upper floor	N/A	N/A	NA			
Fir	e Extinguishers						
	Total numbers	08 nos.	10 nos.	MR			
	• types	ABC /CO <sub>2</sub>	ABC/CO <sub>2</sub>	MR MR			
		ISI marked	ISI marked				

A we

06	First-aid-Hose Reels.			
	Total numbers on each floor	01 no.	01 no.	1 10
778	Length of hose reel hose	30m	30m	M
	Nozzle diameter	05 mm	05 mm	MI
07	Automatic fire detection and alarming sys		1 03 mm	INI
	Type of detectors	Smoke/Heat	Described	6
	Location of main panel	The state of the s	Provided	MI
	Location of repeater panel	Required	Provided	ME
	Alternate source of power	N/A Required	N/A	N/A
	Hooter's location	The second secon	Provided	MF
08	MOEFA MOEFA	Required N/A	Provided Provided	ME
09	Public address System.	N/A	Provided	
10	Automatic Sprinkler System.	I NA	Provided	MR
	Basement	1 200		1
	upper floor	N/A N/A	Provided N/A	MR N/A
	sprinkler above false ceiling	N/A	N/A	market dates
1	Internal Hydrants	I NA	N/A	N/A
	size of riser/down-comer	100 mm	100 mm /	MR
	Number of hydrants per floor	01 no.	01 no. /	MR
	Hose Box	01 no.	01 no.	MR
2	Yard Hydrants.	01110	01110.	INIK
	Total number of hydrants	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
3	Pumping Arrangements.			1 19/74
	Ground Level		/	_
	> Discharge of main Pump	1620 LPM	1620 LPM	MR
	➤ Head of Main Pump	60 m	60 m	MR
	Number of main pumps	01 no.	01 no. /	MR
	> Jockey pump out put	180 lpm	180 lpm	MR
	Jockey pump head	60 m	60 m	MR
	> Standby pump out put	1620 LPM	1620 LPM	MR
	Standby pump Head	60 m	60 m	MR
	> Auto Starting /Manual stopping	Required	Provided	MR
	> Pump House Access	Required	Provided	MR
	Terrace Level		/	inix
and .	<ul> <li>Discharge of pump</li> </ul>	450 LPM	450 LPM	MR
	> Head of the Pump	40 m	40 m	MR
	> Power supply	Required	Provided	MR
	➤ Auto Starting of pump	Required	Auto	MR
	Captive Water Storage for Fire Fighting.		7,000	WILL
	Underground tank capacity	50,000 Ltr	50,000 Ltr.	MR
	> Draw-off connection	Required	Provided	MR
	> Fire service inlet	Required	Provided	MR
	> Access to tank	Required	Provided /	MR
	Overhead Tank capacity	5,000 Ltr.	10,000 Ltr.	MR
	Exit Signage.	Required	Provided	MR
	Provision of Lifts.		13573050	3711
	Pressurization of Lift Shaft	N/A	N/A	N/A
	Pressurization of Lift Shaft			N/A N/A
	Pressurization of Lift Shaft     Pressurization of Lift lobby	N/A	N/A	N/A
	Pressurization of Lift Shaft     Pressurization of Lift lobby     Communication in lift car	N/A N/A	N/A N/A	N/A N/A
	Pressurization of Lift Shaft     Pressurization of Lift lobby	N/A	N/A	N/A



17	Standby power supply	Required	Provided	7.0			
18	Refuge Area						
	Total area	N/A	N/A	1			
	Location	N/A	N/A	No			
19	Fire Control Room						
	Detector system panel	Required	Provided	MR			
	Flow switch panel	N/A	N/A	N/A			
	PA system panel	Required	Provided	MR			
	Battery backup	Required	Provided	MR			
	Building Floor Plans	N/A	N/A	11			
20	Special Fire Protection systems for protection of special Risks, if any	N/A	N/A	NA			

Note:- Secretary of the community Hall has submitted an undertaking and photograph that two temporary tin shed rooms on the terrace has been sealed/closed and not used for any purpose in any case and if agreed we may consider FSC.

The fire protection systems provided in the building were tested/checked and found functional at the time of inspection. The shortcomings as communicated earlier vide letter no. F.6/DFS/MS/C-Hall/2023/NDZ/986 dated 16/05/2023 have been rectified now.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rule. It is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer

Name

- Deepak Kumar

Designation :- ADO(Shah )

Signature of the Inspecting Officer

Name

- A K Jaiswal

Designation : DO(ED)