

FIRE SAFETY CERTIFICATE

Certified that the Working Women's Hostel for North Eastern States located at Jasola, New Delhi-25, comprised of Ground + 05 upper floors & was granted Fire Safety Certificate by this department vide letter no. F6/DFS/MS/2011/1088 dated 03.06.2011. The building was re-inspected by a team of officers concerned from this department on 09.06.2023 in the presence of Mr. Meridul (National Commission of Women) and found that the building has deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010. Accordingly, the premises (Ground + 05 upper floors) is fit for occupancy of Class-A "Residential Building (Hostel Building)" with effect from 19/06/2023..... for a period of five years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to conditions under Rule 38 of Delhi Fire Service Rules, 2010 printed below.

Issued on 19/06/2023.....at New Delhi by


(Atul Gargy)
Director
Delhi Fire Service
19/06/23

Copy to:-

1. The Executive Engineer (Building), South DMC, 9th floor, Dr. SPM Civic Centre, JLN Marg, New Delhi.
2. The Admin. Incharge, Working Women's Hostel for North Eastern States located at Jasola, New Delhi-25.

Conditions for the validity of Fire Safety Certificate

1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
3. The trained fire fighting staff should be available round the clock.
4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".
8. Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained thereto before occupancy of the same.

INSPECTION REPORT

1	Name & address of the building	Working Women's Hostel for North Eastern States located at Jasola, New Delhi-25.		
2	Building is comprised of	Ground + 08 upper floors		
3	Type of occupancy	Residential (Hostel building) 'A'		
4	Type of case	Renewal		
5	Details of previous FSC	F6/DFS/MS/2011/1088 dated 03.06.2011		
6	Fire safety direction letter no.	F6/DFS/MS/BP/2008/557 dated 27.02.2008		
7	Date of inspection	09.06.2023		
8	Name of the inspecting officers	Manoj Kumar Sharma, DO (SD) Rajesh Kumar Shukla, ADO (M. Road)		
9	Name of the designation of officer From the building side	Mr. Meridul (National Commission of Women)		
10	Year of construction	2006		
11	Applicant's letter no.	Outdoor Diary no. 1962 dated 15.05.2023		
S. No	Minimum standard of Fire Prevention and Fire Safety U/R 33	Requirements as per Directive issued	Provide at site	Remarks MR/NMR
1	Access to Building			
A	Road width	6.0 mtrs	60.0 mtrs	MR
B	Gate width	6.0 mtrs	6.0 mtrs	MR
C	Width of internal roads	6.0 mtrs	6.0 mtrs	MR
2	Number, Width, Type & Arrangement of Exits			
A	No. of staircase:			
a)	Upper floor	Required	05 nos.	MR ✓
b)	Basements	NA	NA	NA
B	Width of the staircase:			
a)	Upper floors	1.25 mtrs each	4 nos. of 1.25 mtrs & 1 no. of 1.50 mtrs	MR ✓
b)	Basements	NA	NA	NA
C	Protection of Exits			
a)	Fire check door	Required	Provided	MR
b)	Pressurization	NA	NA	NA
D	No. of continuous staircase to terrace:	02 nos.	Provided	MR
E	Width of the corridor	NA	NA	NA
F	Door size	1.0 mtrs	Provided	MR
3	Compartmentation:			
A	Fire check doors	Required	Provided	MR
B	Sealing of horizontal & vertical opening	Required	Provided	MR
C	Fire rating of shaft doors	1 hours	Provided	MR
D	Water curtain	NA	NA	NA
E	Fire dampers	NA	NA	NA
4	Smoke Management System:			
A	Basements	NA	NA	NA
B	Upper floors	12 ACPH	Natural Ventilation	MR
5	Fire Extinguishers			
A	Total numbers	30 nos.	30 nos.	MR ✓
B	Types	CO ₂ , ABC	CO ₂ , ABC	MR
C	ISI marking	Required	Provided	MR

e

m

h

6	First Aid Hose Reel			
A	Total no. at each floor	03 nos.	05 nos.	MR
B	Length of hose reel	30 mtrs	30 mtrs	MR
C	Nozzle diameter	5 mm	5 mm	MR
7	Automatic Fire Detection and Alarm System (ADAS)			
A	Type of detectors	NA	NA	NA
B	Location of main Panel	NA	NA	NA
C	Location of repeater panel	NA	NA	NA
D	Alternate power source	NA	NA	NA
E	Hooter's location	NA	NA	NA
8	MOEFA	Required	Provided	MR
9	Public Address System	Required	Provided	MR
10	Automatic Sprinkler System			
A	Basement	NA	NA	NA
B	Upper floor	NA	NA	NA
C	Sprinklers above false ceiling	NA	NA	NA
11	Internal hydrants			
A	Size of the riser/down comer	100 mm	150 mm	MR
B	No. of hydrants per floor	03 nos.	5 nos.	MR
C	Hose box	03 nos.	5 nos.	MR
12	Yard Hydrants			
A	Total no. of hydrants	Required	Provided	MR
B	Hose box	Required	Provided	MR
13	Pumping Arrangements			
A	Ground Level			
	a) Discharge & head of main pump	NA	NA	NA
	b) Number of main pump	NA	NA	NA
	c) Discharge & head of jockey pump	NA	NA	NA
	d) Discharge & head of Standby pump	NA	NA	NA
	e) Auto starting/ manual stopping	NA	NA	NA
B	Terrace Level			
	a) Discharge of terrace pump	900 LPM	2 nos. of 900 LPM	MR
	b) Head of terrace pump	70 m	70 m	MR
	c) Alternate power supply	Required	Provided	MR
	d) Auto starting of pump	Required	Provided	MR
14	Captive Water Storage for Fire Fighting			
A	Underground tank capacity	NA	NA	NA
B	Draw off connection	NA	NA	NA
C	Fire Service Inlet	NA	NA	NA
E	Access to tank	NA	NA	NA
D	Overhead tank capacity	25,000 Ltrs	Provided	MR
		Required	Provided	MR
15	Exit Signage			
16	Provision of lift			
A	Pressurization of lift shaft	Required	Provided	MR
B	Pressurization of lift lobby	Required	Provided	MR
C	Communication in lift car	Required	Provided	MR
D	Fireman switch	Required	Provided	MR
E	Lift signage	Required	Provided	MR
17	Standby Power Supply			
		Required	Provided	MR

M

18 Refuge Area				
A	Location	NA	NA	NA
B	Total area	NA	NA	NA
19 Fire Control Room				
A	Fire Detection System panel	NA	NA	NA
B	Flow switch panel	NA	NA	NA
C	P A system panel	NA	NA	NA
D	Battery backup	NA	NA	NA
E	Building floor plan	NA	NA	NA
20 Special Fire Protection for special risk if any				
A	Special Fire Protection system for Protection of Special Risk, if any:	Required	Provided	MR

Meeting Requirement (MR), Not Meeting Requirement (NMR), Not Applicable (NA), Provided but Not Functional (PNF), Not Provided (NP).

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

In view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter no. F6/DFS/MS/2011/1088 dated 03.06.2011 is recommended to be renewed under Rule 37 of the Delhi Fire Service Rules 2010.

msk
 Signature of the Inspecting Officer
 Name Manoj Kumar Sharma
 Designation DO (SD)

RK
 Signature of the Inspecting Officer
 Name Rajesh Kumar Shukla
 Designation ADO (M. Road)

CFD *[Signature]*
 13/6/2022

Director

[Signature]
 13/06/22

DO/SD

msk
 13/6/22

ADO (M/Road)

FI is put up ple
 Director (DFS) *[Signature]*
 16/6/23