GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI MEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

F.6/DFS/MS/EH/2023/SZ/ \93 No.

Dated/5/062023

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the Name & Style of M/s CRAY and RIOSA located at T5/T5A, 3rd Floor, Vasant Square Mall, Vasant Kunj, New Delhi-110070 in the building comprised of Two tier Basement, lower ground, upper ground plus 03 upper floors owned/occupied by A Unit of Foodaholic Factory Pvt Ltd have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of department on 07/06/2023 in the presence of Mr. Sunil Kumar and that the premise is fit for occupancy class Group-D Assembly (Eating House running at 3rd Floor only) and Validity upto 31/03/2026 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 15/06/2023 at New Delhi by


DELAH FIRE SERVICE

Copy to: -

1. The DHO, (South Zone), SDMC, Public Health Department, Aurobindo Marg, Green Park, New Delhi-110016 (Ref. MHA Portal ID 2023053009973 dated 30/05/2023)

Conditions for the validity of Fire Safety Certificate -

- All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the management.
- All the staff members must know the correct method of operation of fire-fighting system.
- 4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first form is Fire Service Rules 2010. The schedule of Delhi www dfs delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any
- 6 "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."





		12 C.	अर्मुत मह	iera
1	INSPECTION	ON REPORT		
1	Name & Address of the Building	M/s CRAY and RIOSA (A Unit of Foodaholic Factory Pvt Ltd) located at T5/T5A, 3 rd Floor, Vasant Square Mall, Vasant Kunj, New Delhi-110070		
2	-ype or occupancy	Assembly Building	j, New Delhi-110070 g "Group-D" Restaurant	
3	Building Comprised of	Two tier Basemen	t, lower ground, upper g	round also of
		upper floors (Rest	aurant running at 3rd	floor)
4	Type of Case	New Case	at ord	
5	Details of Previous NOC	Nil		
6	Fire Safety Directives Letter No	F 6/DFS/MS/BP/2005/2251 dated 28/10/2005 F.6/DFS/MS/Mall/2022/SZ/CMT/566 Dated 13/12/2022		
7	Date of Inspection	(Vasant Square M 07/06/2023	fall NOC)	
8	Name of the Inspecting Officers		DO (BCB)	
9	Name & Designation of Officers	DO (South) & A Mr. Manoj Kuma		
	from the building side	Wit. Mailoj Kuma	1	
10	Year of construction	2010		
11	Applicant letter No.	Septimization of the second	2023053009973 dated	30/05/2022
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	Requirement/ Existing Fire Protection	Provided at Site	Remarks MR/NMR
1	Access to Building. FSC No. F.6/DFS/MS/N	Mall/2022/SZ/CMT	E/566 Dated 13/12/2022	Vacant Cause
	Road width	09 m	Provided *	MR MR
	Gate width	05 m	Provided *	MR
	Width of internal road	06 m	Provided *	MR
2	Number, width, type and arrangements of		viided	MK
	a. Number of Staircase		Maintained by Vasant	Sopare Mall
	Upper floors	02 Nos	Provided *	MR
	Basement floor	02 Nos	Provided *	MR
	b. Width of Staircase	Provided &	Maintained by Vasan	
	Upper floors	1.50 mtr each	Provided *	MR
	Basement floor	1.50 mtr each	Provided *	MR
	c. Protection of exits		Maintained by Vasar	
	Fire check door	Required	Provided *	MR
	Pressurization	N/A	As above	N/A
	d. No. of continuous staircase to terrace	C. (20 10 10 10 10 10 10 10 10 10 10 10 10 10	07 Provided *	MR
	e. Width of corridor	N/A	N/A	N/A
	f. Door size	1.50 m each	1.50 m & 1.50 m	MR
3	Compartmentation.		& Maintained by Vasa	
	Fire check door.	Required	Provided *	MR
	Sealing of electrical shafts.	Required	Provided *	MR
	Fire rating of shaft door.	2 hrs	Provided*	MR
	Water curtain	N/A	N/A	N/A
	Fire dampers.	N/A	N/A	N/A
4.	Smoke Management system.	100 P. C.	& Maintained by Vasa	
	Basement	Required.	Exhaust fans provid	
	Upper floors	Required	Exhaust fans provid	Control of the Contro
5.	Fire Extinguishers,	- Augusta	Distinuis runs provid	MI
	Total numbers	04 Nos	06 Na-	1
	Types	04 1408	06 Nos.	M
		ISI marked	ABC-04, W.CO ₂ -02	-
	ISI Marking Birst Aid Hore People	and the second second second	Provided	M
	First Aid Hose Reels. Provided & Maintained by Vasant Squa			sant Square N
6.	- I I I I I I I I I I I I I I I I I I I			
6.	Total numbers on each floor.		02 in Restaurant	M
6.	Alexander Alexan	Hose Reel		

W

/	1	7
	10	

		10 0		0
	Automatic Fire Detection and Alarming sy	stem. (Provided	& Maintained by Vasant \$	quare Mall
7	Automatic Fire Detection and Additional sy	Required	Smoke & Heat	MK
	Type of detectors	Required	As above	MR
	Location of Main Panel	N/A	N/A	N/A
	Location of Repeater Panel	Required	Provided *	MR
	Alternate source of power	Required	Provided *	MR
	Hooter's location	Required	Provided *	MR
8.	MOEFA		Provided *	MR
9.	Public Address System	Provided &	Maintained by Vasant \$	quare Mall
10.	Automatic Sprinkler System	Required	Provided *	IATIK
	Basement	Required	Provided in Restt.	MR
	Upper floors	21/4	N/A	N/A
	Sprinkler above false ceiling	Provided &	Maintained by Vasant S	quare Mall
11.	Internal Hydrants.	Required	Provided *	MR
	Size of Riser/Down-comer	Required	Provided *	MR
	Number of Hydrant per floor	Danwined	Provided *	MR
	Hose box.	Required	Maintained by Vasant	quare Mall
12.	Yard Hydrants.		As above	N/A
	Total number of hydrants.	N/A	As above	N/A
	2. Hose box.	N/A	AS above	
	Pumping arrangements.		Vecant	Sauare Mall
13.	Ground Level	Provided &	& Maintained by Vasant	MR
		4500 LPM	Provided *	MR
	Discharge of main pump.	60 mtr	Provided *	MR
	> Head of main pump.	Two	Provided *	
	Number of main pumps.	2 x 180 LPM	Provided *	MR
	Jockey Pump output.	60 mtr	Provided •	MR
	> Jockey Pump head.	4500 LPM	Provided *	MR
	 Standby Pump output. 	60 mtr	Provided •	MR
	> Standby Pump head.	Required	Provided *	MR
	 Auto Starting / Manual Stopping. 	Dagwired	Provided *	MR
	Access to pump house	P-wided	& Maintained by Vasant	Square Mall
	Terrace Level		N/A	N/A
	Discharge of pump.	N/A	N/A	N/A
	> Head of pump.	N/A	N/A	N/A
	> Power supply	N/A		N/A
	Auto starting of pump.	N/A	N/A	
	Captive water storage for Fire Fighting.		& Maintained by Vasan	MR
14.	Captive water storage for the	2,50,000 Ltr	Provided •	
	Underground tank capacity.	Required	Provided *	MR
	> Draw-off connection.	Required	Provided *	MR
	Fire Service Inlet.	Required	Provided *	MR
	> Access to tank.	30,000 Ltr	Provided *	MR
	Overhead tank capacity.	Deguired	Provided	MR
15.	Exit Signage.	Required	& Maintained by Vasar	t Square Mall
_	Provision of Lifts.		N/A	N/A
16.	Pressurization of lift shaft.	N/A		N/A
	Pressurization of lift lobby	N/A	N/A	N/A
	• Pressurization of the cor	N/A	N/A	
	Communication in lift car.	N/A	N/A	N/A
	Fireman's switch.	N/A	N/A	N/A
	Lift signage	10.00	Provided (DG Set)	MR
17	Standby Power Supply	Required	Literaco (p. 5 55)	
	Refuge Area		NIA	N/A
	Refuge Area	N/A	N/A	
8.		21/4	N/A	N/A
18.	Total area	NI/A		The state of the s
18.	Total area Location	N/A	1 1 1 V	ent Square Mall
18.		Provided	1 & Maintained by Vasa As above	ınt Square Mall

-	Flow Switch Panel	NIA	As above	N/A
	PA system Panel Battery backup Building floor plan	N/A N/A	As above	N/A
		N/A	As above	N/A
		N/A	As above	N/A
20.	Special Fire Protection System for the Protection of special Risk, if any :	N/A	As above	N/A

Note - * Provided & Maintained by Management of Vasant Square Mall, Vasant Kunj, New Delhi

The Fire protection systems provided in the building were test checked at random and found functional at the time of inspection.

Keeping in view of the substantially satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 (3) of the Delhi Fire Service Rules, 2010

Accordingly, DFA is put up for approval and signature please

Signature of the Inspection Officer

Name: Sh. Manoj Kumar Sharma

Design DO (South)

Signature of the Inspecting Officer Name: Sh Rajesh Kumar

Design ADO (BCP)

CFO (HQ)

C-1. letter is futup to