C58



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

F.6/DFS/MS/EH/2023/SZ/ 194 No.

Dated 15 , 6 6,2023

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the Name and Style of M/s Eniverse Hospitality LLP located at Shop No 02, 2nd Floor, Select City Walk Mall, Plot No A-3, District Centre, Saket, New Delhi- 110017 in the building comprised of 03 Tire Basement, Ground plus 07 upper floors owned/occupied by Ms. Sakshi Kanodia (Partner) was issued Fire Safety Certificate by this department vide letter No. F6/DFS/MS/EH/SZ/2021/122 dated 29/06/2021 for the name of Burger King Restaurant. The premise was re-inspected by the officer concerned of this department on 06/06/2023 in the presence of Mr. Manoj Sharma and found that the said premise have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy Class Group -A "Assembly Building" (Restaurant) and validity upto 31/03/2026 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on | 5 /o 6 /2023 at New Delhi by

DELHI FIRE SERVICE

Copy to: -

1. The Dy. Health Officer, Public Health Department, MCD, Green Park, Delhi- 110016 (Ref. MHA Portal ID 20223053009914 dated 30/05/2023)

Conditions for the validity of Fire Safety Certificate: -

All the means of escape/entry/exit shall be kept free from any obstruction. 1.

All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to nonfunctional fire safety measures shall be at the responsibility of the management.

All the staff members must know the correct method of operation of fire fighting system.

The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

This fire safety certificate may not in any way be treated as regularization (Clause 2 8 of 5 UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if

"The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its

expiry."



| | INSPECT | | | | |
|-----|--|--|--|--|---|
| | Name & Address of the Building | 02, 2m | Floor, S | lospitality LLP located a elect City Walk Mall, Plo Saket, New Delhi- 1100 | ot No A-3, |
| | Type of Occupancy | Group-D Assembly Building (Restaurant) | | | |
| | Building Comprised of | 03 tier Basements, Ground + 07 Upper Floors | | | |
| | Type of Case | New case | | | |
| | Details of Previous NOC | F6/DFS/MS/EH/SZ/2021/122 dated 29/06/2021 for the | | | |
| | Details of Fierrous Froe | name of Burger King Restaurant | | | |
| , | Fire Safety Directives Letter No | F 6/MS/DFS/BP/2006/1141 dated 15/05/2006 & F 6/DFS/MS/Mall/2022/SZ/335 Dt 27/07/2022 for Mall | | | Ł |
| | The Salety Directives Letter 110 | | | | |
| 7 | Date of Inspection | 06/06/2023 | | | |
| 8 | Name of the Inspecting Officers | DO (South) & ADO (BCP) | | | |
| 9 | Name & Designation of Officers | Mr Manoj Sharma | | | |
| | from the building side | | | | |
| 10 | Year of construction | 2020 | Restt at s | shop No 02 at 2nd floor of M | all bldg |
| 11 | Applicant letter No. | MHA | | 20223053009914 dated 30/0 | |
| S | Minimum standards on Fire Prevention and | UBBL | 2016 | Provided at Site | Remarks |
| No. | Fire Safety U/R 33 | Requir | | | MR/NMF |
| 1 | | 11.000.000 | and the same of th | /MS/Mall/2022/SZ/335 Dt. 2 | 7/07/2022) |
| | Road width | 9 mtr | | Provided* | MR |
| | Gate width | 5 mtr 6 mtr | | Provided* | MR |
| | Width of internal road | | | Provided* | MR |
| 2 | Number, width, type & arrangement of exits. | | | Tiviiaya | 1414 |
| | Number of Staircase | Provided & Maintained by Select City Walk, Saket | | | Saket |
| | Upper floors. Basement floor. | 02 Nos | ed to mail | Provided* | MR |
| | | N/A | | N/A | N/A |
| | Width of Staircase | | | ntained by Select City Wal | 100000000000000000000000000000000000000 |
| | Upper floors | 1 50 mtr each 2m, 1 50 m & 1 25 m | | MR | |
| | Basement floor | N/A | | N/A | N/A |
| | Protection of exits | | | ntained by Select City Wall | |
| | Fire check door | Required | | Provided* | 1 |
| | Pressurization | Required Required N/A | | Provided* | MR MR |
| | No. of continuous staircase to terrace | | | Provided* | MR |
| | Width of corndor | | | N/A | N/A |
| _ | Door size | 02 exit | s, 1.50 m | 1.50 mtr each | MR |
| 3 | Compartmentation. | Provided & Maintained by Select City Walk, Saket | | | c. Saket |
| | Fire check door | Require | ed | Provided* | MR |
| | Sealing of electrical shafts. Fire rating of shaft door. Water curtain | Requir | ed | Provided* | MR |
| | | N/A | | N/A | N/A |
| | Fire dampers. | N/A | | N/A | N/A |
| 4 | The state of the s | N/A | | N/A | N/A |
| 4 | Smoke Management system. Basement | Provided & Mair | | ntained by Select City Wall | k. Saket |
| | Upper floors | 30 AC | PH | N/A | N/A |
| 5 | Fire Extinguishers. | 12 AC | PH | Exhaust Fans Provided | MR |
| , | Total numbers | | | | 1 |
| | Types | Requi | Total Control of the | 10 Nos | MR |
| | ISI Marking | ABC/ | | ABC & CO ₂ | MR |
| 6 | First Aid Hose Reels | Requi | | Provided | MD |
| * | Total numbers on each floor | Provided & Maintained by Select City Walk, Saler | | | |
| | Length of hose-reel hose. | One near Restt 30m | | Provided* | MR |
| - | - The of nosc-reet nose. | | | Provided* | |

 $h_{J_{1},J_{2}}$

आजादी का अगृत महोत्सव

| | Nozzle Diameter | 5mm | Provided* | MR | |
|----|--|--|--|--------------------|--|
| 7 | Automatic fire detection & alarming system | n. (Provided & | Maintained by Select | City Walk, Sal | |
| | Type of detectors | Required | Smoke & heat | MR | |
| | Location of Main Panel | Required | Provided* | MR | |
| | Location of Repeater Panel | Required | Provided* | MR | |
| | Alternate source of power | Required | Provided* | MR | |
| | Hooter's location | Required | Provided* | MR | |
| } | MOEFA | Required | Provided* | MR | |
|) | Public Address System | Required | Provided* | MR | |
| 0 | Automatic Sprinkler System | II I NOSO(1 ■ / × 1 NOZ 1 2 | aintained by Select Cit | 100000 | |
| _ | Basement | Required | Provided* | MR | |
| | Upper floor | Required | Provided* | MR | |
| | Sprinkler above false ceiling | N/A | N/A | N/A | |
| 11 | Internal Hydrants. | | aintained by Select City | | |
| | Size of Riser/Down-comer | | Provided* | MR | |
| | | Required | Carra manager | | |
| | Number of Hydrant per floor Hose box | Required | Provided* | MR | |
| 12 | 10.000000000000000000000000000000000000 | Required | Provided* | MR Walls Salvet | |
| 12 | Yard Hydrants. | | aintained by Select City | | |
| | Total number of hydrants. | N/A | As above | N/A | |
| | Hose box. | N/A | As above | N/A | |
| 13 | Pumping arrangements. | | aintained by Select City | | |
| | Ground Level | The state of the s | ping arrangements for en | | |
| | Discharge of main pump. | 4500 LPM | Provided* | MR | |
| | Head of main pump | 88m | Provided* | MR | |
| | Number of main pumps. | 02 Nos. | Provided* | MR | |
| | Jockey Pump output | 180 LPM | Provided* | MR | |
| | Jockey Pump head. Standby Pump output. | 88m | Provided* | MR | |
| | Standby Pump head | 4500 LPM | Provided* | MR | |
| | Auto Starting/Manual Stopping | 88m | Provided* | MR | |
| | Pump house access. | Required | Provided* | MR | |
| | 10.00 | Required | Provided* | MR | |
| | Terrace Level | | | | |
| | Discharge of pump. | 450 LPM | Provided* | MR | |
| | Head of pump | 40 m | Provided* | MR | |
| | Power supply | Required | Provided* | MR | |
| | Auto starting of pump | Required | Provided* | MR | |
| 14 | Captive water storage for fire fighting. | | Provided & Maintained by Select City Walk, Saket | | |
| | Underground tank capacity Draw-off connection. | Required | 5,00,000 ltrs | MR | |
| | Fire Service Inlet | Required | Provided | MR | |
| | Access to tank | Required | Provided | MR | |
| | Overhead tank capacity | Required | Provided | MR | |
| 16 | | Required | 30,000 Ltrs | MR | |
| 16 | Exit Signage Provision of Lifts. | Required | Provided | MR | |
| 10 | | | intained by Select City | | |
| | Pressurization of lift shaft. Pressurization of lift lobby. | N/A | As above | N/A | |
| | Communication in lift car. | N/A | As above | N/A | |
| | Fireman's switch | N/A | As above | N/A | |
| | Lift signage | N/A | As above | N/A | |
| 17 | Standby Power Supply | N/A | As above | N/A | |
| 18 | Refuge Area | Required | Provided | MR | |
| 18 | Total area | N/A | 18/4 | | |
| | Location | N/A | N/A | N/A | |
| 19 | Fire Control Room | N/A | N/A untained by Select City | N/A | |

Lu





| | | TNUA | As above | N/A |
|----|---|------|----------|-----|
| | Detector system panel. Flow switch panel. PA system panel. Battery backup. Building floor plan. | N/A | | N/A |
| | | N/A | As above | N/A |
| | | N/A | As above | |
| | | N/A | As above | N/A |
| | | | As above | N/A |
| | | N/A | | N/A |
| 20 | Special Fire Protection System for the Protection of special Risk, if any. | N/A | As above | |

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Keeping in view of the substantially satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 (3) of the Delhi Fire Service Rules, 2010

Accordingly, DFA is put up for approval and signature please

Signature of the Inspection Officer

Name: Sh. Manoj Kumar Sharma

Design: DO (South)

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar

Design: ADO (BCP)

CFO (HQ)

As appointed, F.I. better en fortip to your synden Pl