

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI-110 001.

No.F.6/DFS/MS/School/2023/SZ/443

Dated: 27/06/2023

FIRE SAFETY CERTIFICATE

Certified that the **Green View Public School**, Dwarka Vihar, Kakrola Road, Najafgarh, New Delhi-110043 (Near Sector-16B Dwarka) comprised of ground plus two upper floors (3rd floor having five rooms which are not in use), owned/occupied by Green View Public School was issued Fire Safety Certificate by this department vide letter No. F.6/DFS/MS/School/2020/SZ/337 dated 10/09/2020. The School building was re-inspected by the officer concerned of this department on 12/06/2023 in the presence of Sh. BP Dabas (Manager) and found that the School building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the building (G+2) is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of **three years** in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule-38 of the Delhi Fire Service Rules, 2010 printed as below.

Issued on 27/06/2023 at New Delhi.


(ANIL GARG)
DIRECTOR
DELHI FIRE SERVICE
o/c

Copy to:-

1. The Principal, Green View Public School, Dwarka Vihar, Kakrola Road, Najafgarh, New Delhi-110043 (Near Sector-16B Dwarka)
2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi - 110054.

Following fire safety directives must be adhered to -

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
4. The trained staff should be available round the clock.
5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in
8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

1 Name & address of the building	Green View Public School, Dwarka Vihar, Kakrola Road, Najafgarh, New Delhi-110043(Near Sector-16B Dwarka)
2 Building is comprised of	Ground plus two upper floors & 5 rooms at 3 rd floor not in use
3 Type of Occupancy	Educational
4 Type of Case	Renewal
5 Details of Previous FSC letter	F 6/DFS/MS/School/2020/SZ/337 dated 10/09/2020
6 Fire Safety direction letter No	Nil
7 Date of Inspection	12/06/2023
8 Name of the Inspecting officers	ADO R K. Yadav
9 Name and designation of Officer from the building side	Sh. BP Dabas (Manager)
10 Year of Construction	2003 & 2009
11 Applicant's letter No	GVPS/DFS/SH/2023/055 Dated- 09/03/2023

S/N	Minimum Standards on fire prevention and fire safety U/R33	Requirement	Provided at Site	Remarks MR/NMR
1	Access to building			
	• Road width	06 M	09 m	MR
	• Gate width	4.5 M	4.8 & 3.2 M X2 Nos	MR ✓
	• Width of internal road	N/A	N/A	N/A
2	Number, Width, Type and Arrangement of exits			
	a Number of Staircases			
	• Upper Floor	03 Nos	03 Nos	MR
	• Basement	N/A	N/A	N/A
	B. Width of Staircases			
	• Upper Floor	1.5 m each	1.5 m each	MR
	• Basement	N/A	N/A	N/A
	c Protection of exits			
	• Fire check door	N/A	N/A	N/A
	• Pressurization	N/A	N/A	N/A
	d No. of continuous staircases to terrace	03 Nos	Provided	MR ✓
	e Width of Corridor	1.5 m	1.5 to 2.35 m	MR
	f. Door Size	1.0 m	1.05 to 1.10 m	MR
3	Compartmentation.			
	• Fire check door	N/A	N/A	N/A
	• Sealing of electrical shafts	N/A	N/A	N/A
	• Fire rating of shaft door	N/A	N/A	N/A
	• Water curtain	N/A	N/A	N/A
	• Fire Dampers	N/A	N/A	N/A
4	Smoke Management System			
	• Basement	N/A	N/A	N/A
	• Upper floor	Required	Natural Ventilation	MR
5	Fire Extinguishers			
	• Total numbers	12 nos	Provided	MR
	• Types	ABC CO ₂	ABC CO ₂	MR
	• IS marking	ISI marked	ISI marked	MR

6	First-aid-Hose Reels			
	Total numbers of each floor	03 Nos	Provided	MR
	• Length of hose reel hose	30 m	Provided	MR
	• Nozzle diameter	05mm	Provided	MR
7	Automatic fire detection and alarming system			
	• Type of detectors	N/A	N/A	N/A
	• Location of main panel	N/A	N/A	N/A
	• Location of repeater panel	N/A	N/A	N/A
	• Alternate source of power	N/A	N/A	N/A
	• Hooter's location	N/A	N/A	N/A
8	MOEFA	N/A	N/A	N/A
9	Public address System	N/A	Provided	N/A
10	Automatic Sprinkler System			
	• Basement	N/A	N/A	N/A
	• upper floor	N/A	N/A	N/A
	• sprinkler above false ceiling	N/A	N/A	N/A
11	Internal Hydrants			
	• size of riser/down-comer	N/A	N/A	N/A
	• Number of hydrants per floor	N/A	N/A	N/A
	• Hose Box	N/A	N/A	N/A
12	Yard Hydrants			
	• Total number of hydrants	N/A	N/A	N/A
	• Hose Box	N/A	N/A	N/A
13	Pumping Arrangements			
	• Ground Level			
	➤ Discharge of main Pump	N/A	N/A	N/A
	➤ Head of Main Pump	N/A	N/A	N/A
	➤ Number of main pumps	N/A	N/A	N/A
	➤ Jockey pump out put	N/A	N/A	N/A
	➤ Jockey pump head	N/A	N/A	N/A
	➤ Standby pump out put	N/A	N/A	N/A
	➤ Standby pump Head	N/A	N/A	N/A
	➤ Auto Starting /Manual stopping	N/A	N/A	N/A
	➤ Pump House Access	N/A	N/A	N/A
	• Terrace Level			
	➤ Discharge of pump	450 LPM	Provided	MR
	➤ Head of the Pump	40 M	Provided	MR
	➤ Power supply	Required	Provided	MR
	➤ Auto Starting of pump	Required	Provided	MR
14	Captive Water Storage for Fire Fighting			
	• Underground tank capacity	N/A	N/A	N/A
	➤ Draw-off connection	N/A	N/A	N/A
	➤ Fire service inlet	N/A	N/A	N/A
	➤ Access to tank	N/A	N/A	N/A
	• Overhead Tank capacity	10,000 Ltr	Provided	MR
15	Exit Signage	Required	Provided	MR


N/A

16	Provision of Lifts			
	• Pressurization of Lift Shaft	N/A	N/A	N/A
	• Pressurization of Lift lobby	N/A	N/A	N/A
	• Communication in lift car	N/A	N/A	N/A
	• Firemen's grounding switch	N/A	N/A	N/A
	• Lift Signage	N/A	N/A	N/A
17	Standby power supply	N/A	N/A	N/A
18	Refuge Area			
	• Total area	N/A	N/A	N/A
	• Location	N/A	N/A	N/A
19	Fire Control Room			
	• Detector system panel	N/A	N/A	N/A
	• Flow switch panel	N/A	N/A	N/A
	• PA system panel	N/A	N/A	N/A
	• Battery backup	N/A	N/A	N/A
	• Building Floor Plans	N/A	N/A	N/A
20	Special Fire Protection systems for protection of special Risks, if any.	N/A	N/A	N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection



Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety measures as required under the rules the FSC issued vide letter No. F-6/DFS/MS/School/2020/SZ/337 dated 10/09/2020 renewal under the Rule 37 of the Delhi Fire Service Rules 2010 is recommended

Note:-Undertaking submitted by the principal placed at (C-39) management have recently constructed five rooms on 3rd floor which are presently not in use


 Signature of the Inspecting Officer
 Name- R K Yadav
 Designation- A D O (JKP)

DO (South West)

 14/6/23

CFO (S2)

 Director

 15/6/2023